

RECEIVED

MAY 22 2013

CITY OF MILWAUKEE

2013 MAY 21 PM 3: 28

Randy S. Parlee Writer's e-mail address:

CITY CLERK'S OFFICE

rparlee@pjmlaw.com

OFFICE OF CITY ATTORNEY

May 20, 2013

Milwaukee City Clerk 200 E. Wells Street, Room 205 Milwaukee, WI 53202

RE:

Great West Casualty File No. F97937-L-206

Your File No. 1068-2013-781 Your Invoice. No. 5140006983

Dear Clerk:

I represent Great West Casualty Company regarding the captioned claim.

Pursuant to the attached letter, we do request a hearing on this matter.

Thank you.

Very truly yours,

PETERSON, JOHNSON & MURRAY, S.C.

Randy S. Parlee

RSP:pp Enclosure

f:\docs\222\0019\00781893.doc



800-228-8602 • Claims fax: 800-833-1851

CITY OF MILWAUKEE

2013 MAR - | After Difference is Service

CITY CLERK'S OFFICE

February 26, 2013

City Clerk

Attention: CLAIMS City of Milwaukee

200 E Wells Street, Room 205 Milwaukee, WI 53202-3567

RE:

Submission of our claim against the City of Milwaukee

O/File #:

F97940-936 Cargo

F97941-936 Trailer

O/Insured:

First Express Inc

O/Drivers: D/Loss:

John Neubert

December 14, 2012

Dear City Clerk:

This letter with the enclosed proofs constitute our demand to the City of Milwaukee for payment in the full amount of \$7,530.17. Payment needs to be made to Great West Casualty Company as subrogee of First Express Inc and forwarded to us at 1100 W. 29th Street, PO Box 277, South Sioux City, NE 68776-0277. Please put our claim number, F97941 on the draft when payment is issued. Our insured's address is 1135 Freightliner Dr., Nashville Tennessee 37210-2213. Their phone number is (615) 244-1425. Our general contact information is noted above but my direct phone number is noted below.

On the above date, our insured driver was driving a 2011 International semi tractor unit # 212 and pulling a 2006 Wabash trailer Unit # 56014. The trailer was loaded with scrap metal. Our insured had just loaded his trailer at Capitol Stamping, 2700 West Meinecke and was driving down Meinecke Ave when his trailer was caught by a low hanging tree branches. When his trailer was caught, and because the tree was rotting, the tree then fell into the trailer resulted in the subject damages. Unfortunately, the tree branches were not hanging low enough to alert our driver to the hazard they and the rotting trunk posed to him. Other property at this location also could have been damaged. Fortunatelym the cargo delivered without a loss and the tractor was not damaged. Enclosed is the applicable police report which states this incident occurred on December 14, 2012 at 1605 hours (4:05 PM) on Meinecke Avenue 200 feet west of 28th Street North and refers to house # 2818.

Our insured and Great West Casualty Company did receive a claim from the City of Milwaukee for the tree removal and replacement. Said claim from the City of Milwaukee will be addressed by our liability department if it has not already been addressed. No other claims have been received herein.

Claim #: F97940-936

Page Two

Enclosed is a draft copy and its corresponding invoice establishing that the repairs to the trailer cost \$7,530.17. Included in the invoice for repairs was the \$311.00 charged for travel to North Avenue to pick up the trailer, the labor involved in cutting off a large section of the trailer siding plus the expense of transporting the trailer to the shop for repairs. Prior to authorizing repairs, we did assess the damages and did determine that this trailer was not a total and that it was repairable. The value of the trailer was approximately \$14,900.

The City of Milwaukee has a duty to protect traffic and persons on its streets from low hanging tree limbs and from the danger of rotting trees that may fall into the streets or onto street traffic. Low hanging branches need to be trimmed and rotting trees removed for the safety of all. The city police did not cite our insured for any violations and did not factor him for any contributing circumstances. Our insured was properly on this street in his tractor pulling his trailer. It was negligent for the city to fail to exercise due care to make sure tree limbs were properly trimmed up and that rotting trees were properly removed in order to prevent them from becoming a hazard to traffic on its street.

I have enclosed photos and the police report which support our position that our insured has no fault here and that the cause of this incident was the failure of the City of Milwaukee to remove its rotting tree, or at least, to trim its branches which were hanging just low enough to catch on the trailer but not the tractor.

I will look forward to receiving payment as noted above.

Sincerely,

GREAT WEST CASUALTY COMPANY

Rhoda J. Ganzel Subrogation Attorney

402-494-8571

r.ganzel@gwccnet.com

RG

Enclosures

Certified Mail - Return Receipt Requested

ALL PAYEES MUST ENDORSE DRAFT AS DRAWN

INSURED: FIRST EXPRESS INC

OWNER:

CLAIMANT: FIRST EXPRESS INC

VEHICLE: 2006 WABASH VAN - 006447

PAY TO THE MASTER FLEET SERVICES

ORDER OF

AMOUNT: *****7,530.17

REMARKS: UPS OVERNIGHT MONDAY

SEND TO: MASTER FLEET SERVICES

3360 SPIRIT WAY

GREEN BAY WI 54307-1906

POLICY NO:

GWP87461B

AGENT:

0530

DATE OF LOSS: 12/14/12 TYPE OF LOSS: COLLISION

DRAFT NO: 3742322 DATE: 02/01/13

CLAIM NO: F97941-M U01

TRANS CODE:

210

ADJ REGION:

00

O.P.:

DBQ9

IMG

(PLEASE DETACH BEFORE ENDORSING)

CHECK FOR CHECK NO. GREAT WEST CASUALTY COMPANY 1100 WEST 29TH STREET 210 3742322 **SOUTH SIOUX CITY NE 68776** DATE PAYTOTHE MASTER FLEET SERVICES 02/01/13 CEDEROF AMOUNT *****7,530.17 ************,530DOLLARS and17CENTS-----PAYABLE FOR FULL & FINAL PAYMENT FOR INVOICE # 31-000010271 CLAIM NOMBER POLICY NUMBER IMSURED DATE OF LOSS GWP87461B F97941-M U01 FIRST EXPRESS INC 12/14/12 CLAIM FILE COPY VALID ONLY WITHIN U.S. BANK SIX MONTHS OF ISSUE b3742322b AUTHORIZED SIGNATURE

Repair Invoice



Invoice No:

04 000040074

31-000010271

RO No: RO Open Dt: 31-000010902

Invoice Date: Customer No: PO No:

CASHTAX FIRST EXPRES

RO Closed Dt: Unit Id: 12/19/2012

56014

., W1.

Cash Taxable

Remit To:

Master Fleet LLC - Accts Recv.

PO Box 11906

Green Bay, WI 54307-1906

(920) 347-1800

Make:

WABSH

Model:

53 FT VAN

Year:

2006

Division:

DIVISION

VIN:

1JJV532W36L006447

Customer Phone:

Ext:

Section: 1

Component: 071
Comp. Desc: Body

....

Rep Reason:

Complaint:

MAINTENANCE HAS HOLE IN Comments:

PICK UP UNIT FROM 2700 W NORTH AVE.

PICK UP DAMAGED UNIT AND BRING TO

MASTER FLEET YARD

Comments

Description

WENT TO 27TH AND NORTH AVE TO PICK UP A TRAILER / CUT OFF LARGE

SECTION OF SIDING AND PUT IT IN THE TRAILER [915]

HELP CUT OFF SECTION OF TRAILER AND FOLLOW MIKE BACK TO SHOP.

[302]

Labor:

\$311.50

Section Total:

\$311.50



Invoice No: 31-000010271

Customer No: CASHTAX

PO No: FIRST EXPRES

Unit Id: 56014

Section: 2

Component: 071 Comp. Desc: Body Rep Reason: Complaint:

DAMAGE

BROKEN

Comments:

RECIEVED APPROVAL TO MAKE REPAIRS TO

ROOF PER ESTIMATE
ANY CHANGES TO THE REPAIR ESTIMATE NEEDS TO BE APPROVED PRIOR TO ANY REPAIR MADE**

CONTACK SONNY PETTY 615-244-1425 E-MAIL SONNYPETTY@FRISTEXPRESS.NET

OR

RICH VANDENBERG 402-494-7891

* *			INSURANC	CE # F97941	
Comments		Description		*	
		COMPLETE REPAIRS PER ESTIMATE ANY CHANGES NE APPROVED PRIOR TO MAKING ANYTHING	EEDS TO BE	,	
Part Charges	Part ID	Description	Qty	Unit Price	Total
	NL050X49X110WHLP	Panel - Side 49x110 PPW	1.00	\$114.40	\$114.40
¥	WABE8351200	Panel - Corner	1.00	\$166.87	\$166.87
TWT	WAB04A01826	Rail - Nose, Front Wall Upper	1,00	\$201.73	\$201.73
	WAPNL1-16	Panel - Duraplate, White, Logistic (Charge by Linear Foot)	3.00	\$310.07	\$930.20
	WAB01S00636	Post - Side, Logistic Duraplate	3.00	\$56.20	\$168.60
· ·	WAB01A01752	Cover - Outer Logistic Duraplate, White, 116in, Rivet Strip	3.00	\$32,88	\$98,65
	WAB01S00010	Plate - Splice, Top Rail, 4ft	1.00	. \$18.99.	\$18.99
	WAB0076260	Rail - Top	. 11.00	\$13.26	\$145.86
	WA03100028	Bow - Roof (Trailer)	3.00	\$16,65	\$49.95
	NL1164517	Panel - Aluminum Roof, .040in Thick x 103in Wide	17.00	\$24.86	- \$422.62
	WAB01S00009	Plate - Splice, Top Rail, 6in	2.00	\$9.50	\$19.00
	TL35001Y	Clearance Lamp Kit - Yellow, 4in x .75in Rect Sealed LED	2.00	\$11.15	\$22.30
	PLV810-1/8	Tape - Foam, 1/8	95.00	\$0.24	\$22.80
	0740560	SOLID ALUM H 1/4X3/8 (PKG QTY 500)	250.00	\$0.20	\$50.03
F-90	0730710	Rivet - Aluminum, 1/4 x 7/8 Hard	500.00	\$0.20	\$100.00
	0730590	Rivet - Aluminum, 1/4 x 3/4 Hard	200.00	\$0.16	\$32.00
	0730570	Rivet - Aluminum, 1/4 x 1/2 Hard	100.00	\$0.16	\$16.00
	0730610	Rivet - Aluminum, 3/16 x 3/8 Soft	500.00	\$0.05	\$25.00
	0909330	Tubing - Nylon, Red, 3/8	1.00	\$1.52	\$1.52
	0909360	Tubing - Nylon, Blue, 3/8	1.00	\$1.28	\$1.28
	0757110	Rivet - Multi Range, 3/16 x 3/4	50.00	\$0.35	\$17.50
	MFPLYWOOD1/4	Plywood - Lining, 1/4in x 4ft x 8ft	2.00	\$20.36	\$40.72
	TL98101	Tape - Reflective, Red/White, 2in x 150ft	8.00	\$1.89	\$15.13
	SI221-242	Caulk - Sika-Flex, Gray	3.00	\$8.98	\$26.94
	NL1013477	Sealant - Roof (Seal-A-Gap)	1.00	\$13.40	\$13.40
	NL2-402	Wire - 2 Strand	8.00	\$0.91	\$7.28
				Parts:	\$2,728.77
				Labor:	\$4,049.50
			Sec	tion Total:	\$6,778.27

Invoice Total:

7,530.17



Unit ld: 56014 Invoice No: 31-000010271 Customer No: CASHTAX PO No: FIRST EXPRES Taxes & Fees Qty Fees **Unit Charge** Total Description \$75.00 Misc. Shop Supplies 1.00 \$75.00 Description Charge Total Taxes 5% Sales Tax - Invoicing \$358.24 \$358.24 WI Racine County .1% Sales Tax - Invoicing \$7.16 \$7.16

Messages:

PLEASE PAY FROM THIS INVOICE. Terms and Conditions: A charge of 1.5% per month (18% per year) may be charged on all past due balances together with reasonable attorney's fees in case of suit. No returns without prior approval. All merchandise returned is subject to 20% restocking charge. All returned items must be accompanied with invoice number. Special order and cut-to-size items may not be returnable. All warranties on the products sold hereby are those made by the manufacturer, most covering parts only, no labor after a period of 90 days.

Total Parts Charges: Total Labor Charges: Total Service Charges:	\$2,728.77 \$4,361.00
Taxes:	 \$365.40
Fees:	\$75.00
Invoice Totals:	\$ 7,530.17

1/31/2013




DATE: 12/20/2012

3845 WEST FRONTAGE ROAD FRANKSVILLE WISCONSIN 53126

262-732-4055

	FLEET MAINTENANCE SOLUTIONS		PARTS	LABOR	SUB TOTAL
				1	a vi
STOM	ER FRIST EXPRESS	TOTALS:	#######	\$4,316.50	\$6,895.87
0 / VI	n: 56014 / 1JJV532W36L006447	This estimate is be		Eroiabt	20.00
		found as work is sta	dedThere will be		\$0.00
	And the second s	balances along with	attorney fees in		\$6,895.87
					\$344.79
					\$7,240.66
Repla	DESCRIPTION OF REPAIR NEEDED	PARTS		1	JOB TOTAL
	ESTIMATE FOR REPAIRS	TARTO	HOURS	AND DESCRIPTION OF THE PARTY OF	The second secon
	DIACNOSTICS / DESEABOLU BART PRICING / AVAIL ARLITY				
_				\$0.00	\$0.00
X	REPLACE COMPLETE FRONT HEADER	\$250.00	6.00	\$534.00	\$784.00
X	REPLACE ROAD SIDE RADIUS PANEL TO INCLUED ONE FRONT PANEL / ALSO TWO PLY LINERS ON FRONT WALL.	\$250.00	8.00	\$712.00	\$962.00
X	SECTION 16 FEET OF UPPER RAIL ON ROAD SIDE	\$185.00	9.00	\$801.00	\$986.00
х	REPLACE 6 DAMAGED ROOF BOWS	\$84.00	1.50	\$133.50	\$217.50
X	SECTION 18 FEET OF ALUM. ROOF	\$359.64	8.00	\$712.00	\$1,071.64
X	REPLACE 3 DAMAGED Z-PLATE SIDE PANELS	\$1,025.73	16.00	\$1,424.00	\$2,449.73
x	Z-PLATE SIDE POSTS	\$275.00		\$0.00	\$275.00
	MISC. RIVETS AND CAULK	\$150.00		\$0.00	\$150.00
		j			
<u></u>					
		-		1	
		1			
				!	
	YEAI MODE COLOI LEAGI	YEAR: MODEL: WABASH 53 VAN COLOR: LEAGE: DESCRIPTION OF REPAIR NEEDED "ESTIMATE FOR REPAIRS"* DIAGNOSTICS / RESEARCH PART PRICING / AVAILABLITY X REPLACE COMPLETE FRONT HEADER X REPLACE ROAD SIDE RADIUS PANEL TO INCLUED ONE FRONT PANEL / ALSO TWO PLY LINERS ON FRONT WALL. X SECTION 16 FEET OF UPPER RAIL ON ROAD SIDE X REPLACE 6 DAMAGED ROOF BOWS X SECTION 18 FEET OF ALUM. ROOF X REPLACE 3 DAMAGED Z-PLATE SIDE PANELS X Z-PLATE SIDE POSTS	YEAR: MODEL: WABASH 53 VAN COLOR: LEAGE: DESCRIPTION OF REPAIR NEEDED PARTS "ESTIMATE FOR REPAIRS" DIAGNOSTICS / RESEARCH PART PRICING / AVAILABLITY X REPLACE COMPLETE FRONT HEADER X REPLACE ROAD SIDE RADIUS PANEL TO INCLUED ONE FRONT PANEL / ALSO TWO PLY LINERS ON FRONT WALL. X SECTION 16 FEET OF UPPER RAIL ON ROAD SIDE X REPLACE 6 DAMAGED ROOF BOWS X REPLACE 3 DAMAGED Z-PLATE SIDE PANELS X REPLACE 3 DAMAGED Z-PLATE SIDE PANELS \$275.00	YEAR: MODEL: WABASH 53 VAN MODEL: WABASH 53 VAN MODEL: WABASH 53 VAN MODEL: WABASH 53 VAN COLOR: LEAGE: Estimate submitted by: RUSS GORLEWSKI 48.50 PARTS PARTS DESCRIPTION OF REPAIR NEEDED **ESTIMATE FOR REPAIRS** DIAGNOSTICS / RESEARCH PART PRICING / AVAILABLITY X REPLACE COMPLETE FRONT HEADER X REPLACE ROAD SIDE RADIUS PANEL TO INCLUED ONE FRONT PANEL / ALSO TWO PLY LINERS ON FRONT WALL. X SECTION 16 FEET OF UPPER RAIL ON ROAD SIDE X REPLACE 6 DAMAGED ROOF BOWS X SECTION 18 FEET OF ALUM. ROOF X REPLACE 3 DAMAGED Z-PLATE SIDE PANELS \$ 275.00 **275.00 **275.00 **275.00 **275.00 **275.00 **275.00	YEAR: MISC. MODEL: WABASH 53 VAN MISC. Total COLOR: Estimate submitted by: RUSS GORLEWSKI DESCRIPTION OF REPAIR NEEDED PARTS DIAGNOSTICS / RESEARCH PART PRICING / AVAILABLITY X REPLACE COMPLETE FRONT HEADER X REPLACE ROAD SIDE RADIUS PANEL TO INCLUED ONE FRONT PANEL / ALSO TWO PLY LINERS ON FRONT WALL. X SECTION 16 FEET OF UPPER RAIL ON ROAD SIDE X REPLACE 6 DAMAGED ROOF BOWS X REPLACE 3 DAMAGED Z-PLATE SIDE PANELS X REPLACE 3 DAMAGED Z-PLATE SIDE PANELS X REPLACE SIDE POSTS SO.00 S1,424,00 S275.00 S0.00 S0.00 S1,424,00 S275.00 S0.00 S0.00



Home | Register | Contact Us

High/Low/Average

North America Listings

You Searched For: Category = DRY VAN TRAILERS; Manufacturer = WABASH; Year From = 2005; Year To = 2006

		Auction Prices	Equipment For Sale Prices
Total number of listings found:		0	21
Highest price found:	RECEIVED		US \$18,900
Lowest price found:			US \$11,950
Average price:	FEB 0 1 2013		US \$14,919
Average w/out High & Low:	MRO-17		US \$14,866

Here is an at-a-glance view of current "quick sale", auction prices, and also current asking, or "retail", prices.

We have done computations on both "Equipment For Sale" & "Auction Results" listings for the type of equipment you specified. Above you see the average price found, the highest & lowest prices, and the average price computed again after throwing out the highest & lowest prices. For clarification, we've also displayed the number of listings on which the computations were performed. (NOTE: Items without a price have been omitted from the calculations.)

Retum To Previous Page

Home Copyright & Legal Notice Privacy Policy Site Map Contact Us

Copyright © by Sandhills Publishing Company 2013. All rights reserved.

90 - Alcohol Test TEST NOT GIVEN

QPTHZB8

1 of 4 Page

Ac PK2

	Reportable Ad	cident	110	n Emer	gency	 Am	nended		Document N H ZB 8	umber	Docume	nt Override	Number
	Agency Accident Nun 123492004	nber			-	Police N	lumber						
	4 - Accident Date 12/14/2012		5 - Time 1605	e of Accid	ent (Militar	y Time)	6 - Tot	al Units	7 - Tota	l Injured	8 - Total K 00	illed	
	2 - County :		11 (810) POR CARRON (1999)	cipality UKEE	(\$4-10P)\$24\$y\$50(0_6)\$7945	2014/09/04/04/04/04 JP		77.7		X-1706-97-853 X2543545	cident Loca NTERSEC	n the least that it will be	
			eet Name CEAVW					14 - Bu	s/Frnt/Rmp	15 - Es 200	15 - Est. Dist Ft/Mi 15 - Hwy. Dir		
NO.	16 - Fr/At Hwy No.	16 - From 28TH S	n/At Street I	Name			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1	6 - Business	Frontage	e/Ramp		
GENERAL INFORMATION	17 - Structure Type HOUSE #	17 - St 2818	ructure Nu	tude			13	- Longitud	le				
FOF	80 - First Harmful Event TREE						- Manner COLLI			R VEHI	CLEIN TR	ANSPO	RT
AL II	112 - Access Control 113 - Road Curvature NO CONTROL STRAIGHT				- Road To		Surface CONCE	Type RETE - 1					
NER	115 - Traffic Way NOT-PHYSICALL	Y-DIVIDI	ED-(2-WA	Y TRAF	FIC)								
8	117 - Relation To Ros ON-ROADWAY	sdway											
	114 - Light Condition DUSK			116 - Ro DRY	ad Surfac	e Conditio	on	\$31-231-850	- Weather				
		9 Gov	ernment	Property	, 9	Fire	Pho	tos Tak	en 🛚 🖂	Trailer o	r Towed		
	9 Truck, Bus, or	Hazard	ous Mate	rials	9 Loa	nd Spilla	ige [_	struction 2	Zone	9 Nam	es Excha	anged
	101 Supplemental	Reports	102	Witness	Stateme	ents	103 Me	asurem	ents Take		-EMSNu	mber	
	Operator/Pede:	strian											
	Unit Status				81 -	Most Har	mful Eve	nt: Collisi	on With	23 - EA	Dir Of Trav ST	el 24 - S 25	ipeed Limi
	36 - Operating as Cla A CLASS	ssified	37 -	Endorsen	nents	***************************************		35		ıg Comr	nercial Mo	tor Vehi	cle
	29 Driver's License NU972419	Number			30 - OH		31 - Expir 2015		17 34 On				
	25 - Operator/Pedest	ian Last I	Jame			25 - Fir	st Name				5 - Middle II	nitial 25	- Suffix
	32 - Date Of Birth 07/08/1960		33 - Sex MALE					X Control of the				: E : E : E : E : E : E : E : E : E : E	
	26 - Address Street 8										26 - F	PO Box	
-	27 - City HOLLAND					1000	27 - State OH	27 - Z 4352	ip Code		28 - Teleph (423) 646		
5	39 - Seat Position FRONT-SEAT-LEI	FT-SIDE	-(MC/BIK	E DRIVE	R, TRAII	N COND	UCTOR	:)	40 - Safet		ent E-UNKNO	WN	
AN	38 - Injury Severity N - NO APPAREN	TINJUR	Y	0.0000000000000000000000000000000000000	Airbag N-DEPL	OYED	100	12 - Eject			44 Me	dical Tra	nsport
STR	43 - Trapped/Extricat NOT-TRAPPED	ed	92	- Peclestri	an Locatio	on	92 - Pec	lestrian A	ction				
EDE	119 - What Driver Wa	- 12			1000	Traffic Co			-		62 - No. o	f Citations	Issued
OPERATOR/PEDESTRIAN	64 - 1st Statute No.		2nd Statute	No.		d Statute		64 -	4th Statute	No.	64 - 5tl	n Statute N	lo.
	122 - Driver Factors												
RAT	NOT-APPLICABL	E											

90 - Alcohol Content

91 - Drug Test TEST-NOT-GIVEN

	91 - Drugs	Reported									
	(23)	way Factors PLICABLE					,				
	Vehicle										
	21 - Unit T	уре			Vehicle Type	,				22 - Total Occ	
	TRUCK	se Plate Number 🦠	#2000 (100 h)					-ATTACHED		1	
	X391HZ	se Frate Humper			68 - State 69 FN 20	Exp ≀- 113		- Vehicle Ident HSCUAPR5B		1	
10	50 - Year 2011	51 - Make INTL		52 - Model TRUCK TRAC		Body Styl	е	54 - Color BLU	100 - Sk	dmarks to Imp	
VEHICLE	94 - Vehicl	VEHICLE									
>	95 - Extent Of Damage 96 SEVERE Vehicle Towed				Due To Dama	age	97 - Veh OPERA	icle Removed I ATOR	oved By		
	Vehicle Owner 45 Vehicle Owner Same As Operator										
	45		As Op	erator							
R 01	45 Vehic			erator 46 - Firs	rt Name		4	i 6 - Middle Initia	I 46 - Suffix	Date Of Bir	
	45 Vehice 46 - Vehice	le Owner Same e Owner Last Name			it Name		4	i6 - Middle Initia	l 46 - Suffix	Date Of Bir	
OWNER	45 Vehicle 46 - Vehicle 46 - Compa	ele Owner Same e Owner Last Name any Name KPRESS INC es Street & Number)		rt Name	47 - 1	PO Box	6 - Middle Initia	I 46 - Suffix	Date Of Bir	
	45 Vehicle 46 - Vehicle 46 - Compa	ele Owner Same e Owner Last Name any Name KPRESS INC is Street & Number EIGHTLINER DR)		t Name		PO Box		I 46 - Suffix 49 - Telephone 615) 244-142	Number	
OWNER	45 Vehicl 46 - Vehicl 46 - Compa FIRST EX 47- Addres 1135 FRE 48 - City	ele Owner Same e Owner Last Name any Name (PRESS INC) as Street & Number EIGHTLINER DR)		48 - State	48 - Zi	PO Box		49 - Telephone	Number	
VEH OWNER	46 - Vehicl 46 - Vehicl 46 - Computer FIRST EX 47 - Addres 1135 FRE 48 - City NASHVIL INSURANCE 63 - Liabilit GREAT-V	cle Owner Same e Owner Last Name any Name (PRESS INC as Street & Number EIGHTLINER DR LE Ce y Insurance Compa	iny		48 - State	48 - Zi	PO Box	60	49 - Telephone	Number 25 EXT.	
OWNER	46 - Vehicl 46 - Vehicl 46 - Computer FIRST EX 47 - Addres 1135 FRE 48 - City NASHVIL INSURANCE 63 - Liabilit GREAT-V 61 - Policy	cle Owner Same e Owner Last Name any Name (PRESS INC as Street & Number EIGHTLINER DR LE Ce y Insurance Compa VEST-CASUALT Holder Last Name	iny		48 - State TN	48 - Zi 37210	PO Box	60 Policy	49 - Telephone 615) 244-142	Number 25 EXT.	
01 VEH OWNER	46 - Vehicle 46 - Vehicle 46 - Computer FIRST EX 47 - Address 1135 FRE 48 - City NASHVIL INSURANCE 63 - Liability GREAT-V 61 - Policy 61 - Policy	cle Owner Same e Owner Last Name any Name (PRESS INC as Street & Number EIGHTLINER DR LE Ce y Insurance Compa	iny		48 - State TN	48 - Zi 37210	PO Box	60 Policy	49 - Telephone 615) 244-142	Number 25 EXT.	
01 VEH OWNER	46 - Vehicle 46 - Vehicle 46 - Computer FIRST EX 47 - Address 1135 FRE 48 - City NASHVIL INSURANCE 63 - Liability GREAT-V 61 - Policy 61 - Policy	cle Owner Same e Owner Last Name any Name (VPRESS INC as Street & Number EIGHTLINER DR LE Ce ty Insurance Compa VEST-CASUALT Holder Last Name Holder Company (VPRESS INC) Bus	iny	46 - Firs	48 - State TN	48 - Zi 37210	PO Box p Code)	60 Policy	49 - Telephone 615) 244-142	Number 25 EXT.	

. 01	106 - Power Unit Number 01	License Plate Number T858515	Plate Type STL	State TN	Expiration Year 2013
균	Trailer Make		Unit Type	***************************************	Vehicle Identification Number
F	WABA		SEMI		1JJV532W36L006447

Property

(consumer of					
	Organization Type	84 - Property Owner Last Name	84 - First Name	84 - Middle Initial	84 - Suffix
	GOVERNMENT		19 He CM		Control Control Control

QPTHZB8


3 of 4 Page

	84 - Company Name CITY OF MILWAU	KEE	Government Property Type COUNTY/MUNICIPAL			
2	85 - Address Street & 200 E WELLS ST	85 - PO Box				
OWNER	86 - City MILWAUKEE		86 - State WI	86 - Zip Code 53202		87 - Telephone Number (414) 286-2150 EXT.
2,000	83 - Government Dar					
PROPERTY	82 - Striking Unit 1	82 - Object Struck TREE		82 - Striking Unit	82 - Object	t Struck
PR	82 - Striking Unit	82 - Object Struck		82 - Striking Unit	82 - Object	t Struck
	82 - Striking Unit	82 - Object Struck		82 - Striking Unit	82 - Object	t Struck

Property

	Organization Type INDIVIDUAL	84 - Property Owner Last N METZGER	lame	84 - First Name ELWOOD		84 - Middle Initial A	84 - Suffix		
	84 - Company Name		,	Government Property Type					
02	85 - Address Street 2424 N 29TH ST	& Number	85 - PO Box						
OWNER	86 - City MILWAUKEE		86 - State WI	86 - Zip Code 53210		87 - Telephone Number (414) 915-5156 EXT.			
	83 - Government Da	mage Tag Number							
E	Fixed Objects	Struck							
PROPERTY	82 - Striking Unit 1	82 - Object Struck FENCE		82 - Striking Unit	82 - Object Struck				
PR	82 - Striking Unit	82 - Object Struck	82 - Striking Unit	82 - Object Struck					
	82 - Striking Unit	82 - Object Struck		82 - Striking Unit	82 - Object	t Struck			

Diagram and Narrative




Accident Report MV4000e 01/2005

PK2011


UNIT ONE IS A SEMI WITH A SEMI TRAILER. UNIT ONE STATES HE WAS DRIVING IN THE W/B LANE DUE TO PARKED VEHICLES IN THE EASTBOUND LANE. UNIT ONE PASSED UNDER A TREE AND THE TREE GOT CAUGHT ON THE SEMI TRAILER. THE TREE THEN FELL CAUSING DAMAGE TO THE TRAILER AS WELL AS A NEARBY FENCE AND HOUSE. MINOR DAMAGE TO SEMI TRACTOR, MAJOR DAMAGE TO SEMI TRAILER. MINIMUM DAMAGE TO HOUSE.


Officer Information


	125 - Officer Last Name THOMPSON			irst Name HEW	e 125 - Middle D		Initial	131 - Officer ID 18576
RMATION	129 - Law Enforcement Agency No. 32	- Law Enforcement Agence WAUKEE POLICE DE						
RMAT	126 - Law Enforcement Agency Add 749 WEST STATE STREET	treet & Number						
INFOR	127 - City MILWAUKEE		127 - State WI		127 - Zip Code 53233		128 - Telephone Number (414) 933-4444 EXT.	
K	132 - Date Notified 133 - 12/14/2012 1631				134 - Time Arrived (Military Time) 1639		135 - Date Of Report 12/14/2012	
OFFIC	Agency Accident Number 123492004 18 - Agency Space	Number	19 - Special Study					






















CIA File #: Customer Claim #: F97937

151-022663

Date of Loss: 12/14/2012 Adjuster:

Timothy Rice

Insured/Owner:

First Express



Photo #: 1

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CLOSE UP OF TREE BASE



Photo #: 2

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: TREE LONG VIEW



CIA File #: Customer Claim #: F97937

151-022663

Date of Loss: 12/14/2012 Adjuster:

Timothy Rice

Insured/Owner:

First Express



Photo #: 3

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: TREE DOWN



Photo #: 4

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: TREE DOWN LONG VIEW



CIA File #: Customer Claim #: F97937

151-022663

Adjuster:

Date of Loss: 12/14/2012 **Timothy Rice**


Insured/Owner:

First Express



Taken By: Timothy Rice

Description: TREE AGAINST DUPLEX





Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CLOSE UP





CIA File #:

151-022663 Customer Claim #: F97937

Insured/Owner:

First Express

Date of Loss: 12/14/2012

Adjuster:

Timothy Rice




Photo #: 7

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: TREE BRANCHES AGAINST TRAILER



Photo #: 8

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: LOOKING SOUTH TREE ON HOUSE



CIA File #: Customer Claim #: F97937 Insured/Owner:

151-022663

First Express

Date of Loss: 12/14/2012 Adjuster:

Timothy Rice



Photo #: 9

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CLOSE UP



Photo #: 10

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: LOOKING WEST



CIA File #: Customer Claim #: F97937

151-022663 First Express Date of Loss: 12/14/2012 Adjuster:

Timothy Rice




Photo #: 11

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: REAR OF INSURED'S TRAILER




Photo #: 12

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: REAR PASSENGER SIDE



CIA File #: Customer Claim #: F97937

151-022663

Insured/Owner:

First Express

Date of Loss: 12/14/2012

Adjuster:

Timothy Rice



Photo #: 13

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: IDENTIFYING РНОТО



Photo #: 14

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: FRONT DRIVER'S SIDE



CIA File #: Customer Claim #: F97937 Insured/Owner:

151-022663 First Express Date of Loss: 12/14/2012 Adjuster:

Timothy Rice




Photo #: 15

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: LOOKING NORTHEAST



Photo #: 16

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: FRONT DRIVER'S SIDE



CIA File #:

151-022663 Customer Claim #: F97937 First Express Date of Loss: 12/14/2012 Adjuster:

Timothy Rice

Insured/Owner:




Photo #: 17

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: BRANCHES AGAINST FENCE




Photo #: 18

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: DAMAGE TO INSURED'S TRAILER, FRONT DRIVER'S SIDE



CIA File #:

151-022663 Customer Claim #: F97937

Adjuster:

Date of Loss: 12/14/2012 **Timothy Rice**

Insured/Owner:

First Express



Photo #: 19

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CLOSE UP



Photo #: 20

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: LOOKING SOUTHEAST, TREE ON **DWELLING**



CIA File #:

151-022663 Customer Claim #: F97937

Date of Loss: 12/14/2012 Adjuster:

Timothy Rice

Insured/Owner:

First Express




Photo #: 21

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: LOOKING NORTH




Photo #: 22

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: INSURED UNIT MOVING TOWARD PLANT



CIA File #:

Insured/Owner:

151-022663 Customer Claim #: F97937

Adjuster:

Date of Loss: 12/14/2012 **Timothy Rice**

First Express



Photo #: 23

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: INSURED UNIT MOVING TOWARD PLANT




Photo #: 24

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: TREE ON ROOF

1



CIA File #: Customer Claim #: F97937

151-022663

Adjuster:

Date of Loss: 12/14/2012 **Timothy Rice**

Insured/Owner:

First Express




Photo #: 33

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: LOOKING NORTH, WIDE VIEW




Photo #: 34

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CLOSE UP



CIA File #: Customer Claim #: F97937

151-022663

First Express

Date of Loss: 12/14/2012

Adjuster:

Timothy Rice




Photo #: 35

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: REAR DRIVER'S SIDE




Photo #: 36

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: REAR PASSENGER SIDE



CIA File #: Customer Claim #: 151-022663 F97937

Date of Loss: 12/14/2012 Adjuster:

Timothy Rice

Insured/Owner:

First Express



Photo #: 37

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CLOSE UP



Photo #: 38

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: DAMAGE TO INSURED'S TRAILER



CIA File #: Customer Claim #: F97937

151-022663

Adjuster:

Date of Loss: 12/14/2012 **Timothy Rice**

Insured/Owner:

First Express



Photo #: 39

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: FRONT DRIVER'S SIDE



Photo #: 40

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: FRONT DRIVER'S SIDE



CIA File #:

151-022663 Customer Claim #: F97937

Date of Loss: 12/14/2012 Adjuster:

Timothy Rice




Photo #: 41

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: FRONT DRIVER CLOSE UP



Photo #: 42

Date Taken: 12/14/2012

Taken By: Timothy Rice

Description: CITY OF MILWAUKEE FORESTRY SERVICE