City Clerk ATTN: CLAIMS 200 E. Wells St., Room 205 Milwaukee, WI 53202-3567 2023 AUG 28 PM 2:52

CITY CLERK'S OFFICE

We have owned our home at 3405 N Humboldt Blvd in Milwaukee since July of 2014 and had never had any previous trouble with our sewer line until last year. We would like to be reimbursed for our expenses in fixing the damage done by a city project contracting company.

During the city's lead lateral water line replacement work last fall, 5-Star Energy hit our original clay sewer pipe while excavating with either their drill or backhoe on March 8, 2022. They informed us of the issue that afternoon so that we would not use our water. We took photos while watching the repair and could see that a tamper was not used to compact the soil.

5-Star completed the repair that night about 9 or 10pm. We learned later that the repair was never inspected and had no camera exam to confirm that the work was done well or to be able to compare to future issues.

On August 21, 2022, our sewer backed up into our home, flooding our basement including our laundry room and basement office. Rugs, carpet tiles, etc. were ruined. We had a two month old baby and two young kids at home, and grandparents visiting at the time. We cleaned the mess ourselves and hired ABC Sewer to immediately snake the pipe (\$90). They were unable to reach the blockage so we hired Roto-Rooter the next day to snake the pipe again and send a camera through (\$935.83). They did not bring a long enough snake so were only able to reach part way through the pipe. Roto-Rooter recommended we video the pipe, which is how we learned that the pipe was broken.

After calling several companies to get quotes, timelines, and compare solutions, we hired Heiden Plumbing to water jet debris from the manhole and video the pipe (\$896.75). They could not come out to do the work until September 15, 2022 so we had to stay with family in Madison during that time because our plumbing was still not useable.

In the new video footage from Heiden, we can see that the joint between the original pipe and repaired section looks rough and most likely leaked. We have photos of the interior of the pipe that also show sediment build up in the patched PVC (upstream) side of the joint that is not present in the clay pipe. Since misaligned pipes can cause wastewater to leak into the surrounding soil and cause erosion and increased pressure on the line, we believe the original damage and repair by 5-Star Energy caused our pipe to collapse.

After Heiden water jetted the pipe, it was useable for a short time, but we needed a permanent solution before the pipe collapsed in other sections, or debris fell in the hole. We hired IHN Company to line our pipe with a cured-in-place pipe lining (CIPP) from the manhole to our house that included a warranty (\$11,850). The work was completed on October 10, 2022.

Four days after our new liner was installed, 5-Star excavated the area of our yard where they had patched the pipe to inspect their work. They claimed that it looked fine.

On March 29, 2023, Sirrah Construction excavated on Humboldt in front of our house as part of the Humboldt reconstruction project. They were digging to put in storm sewer drains and ripped a hole in our new sewer liner. They repaired the damage with another patch of PVC, but our warranty is now void. This work was inspected when it was completed.



Because we paid out of pocket to repair our pipe due to the damage caused by city contractors, and especially now that our warranty is void, we believe we should be reimbursed by the City of Milwaukee for our total costs of \$13,772.58.

Thank you,

Katie and Ivan Eisenberg

3405 N. Humboldt Blvd Milwaukee, WI 53212

Katie: 203-273-5497 katie.layman@gmail.com

Ivan: 814-969-5919

ivan.eisenberg@gmail.com

Ned Warr jet Couldn't spen



Milwaukee, WI 53207 PO Box 07461

Phone: 414-744-6060 www.ABCsewer.com

jeff@ABC sewer.com

No. 302520

INVOICE

Date: 8-21-33

N Humboldt

OTHER COMMENTS

- Please include the invoice number on your check.
- I understand that ABC Sewer & Drain Cleaning is not responsible for any damage done by conventional repair efforts to plumbing fixtures or piping that is aged or deteriorated.

TOTAL \$

If you have any questions about this invoice, please contact Tammy Hammond, 414-744-6060, tammy@ABCsewer.com

Thank you for your business!

thweste	Transaction Details	scription: POS Pl	Amount: -\$935.83	Date: AUG 23	Type: Withdrawal	Fee: \$0.00		7707	AUG POS PURCH - RO 23 ROTO-ROOTER 2022	AUG Check#10 2022
Northwestern Mutual	etails	Description: POS PURCH - ROTO-ROOTER 1799 WI WEST ALLIS	3	AUG 23, 2022	awai		Close		POS PURCH - ROTO-ROOTER 1799 WI WEST ALLIS ROTO-ROOTER US	Check #1001 SHR DRAFT - SHARE DRAFT 1001
Messages Mobile Settings Log Off	×	WI WEST ALLIS ROTO-ROOTER US							-\$935.83	00.06\$-

HEIDEN PLUMBING CO., INC 1100 W. Bruce Street,	SERVICE DATE:	- 1'AA (TIT) 731"0463
NAME.	SERVICE DATE:	
ADDRESS:	JOB LOCATION:	
CITY, STATE, ZIP:	INVOICE NO.:	ACCOUNT NO.:
PHONE:	CONTACT INFORMATION:	
DESCRIPTION OF WORK:		
RECOMMENDATIONS:		
As required by the Wisconsin construction lien law, Contractor hereby notified Owner that persons or		
companies furnishing labor or materials for the construction on Owner's land may have lien rights on	TRUCK / TRIP CHARGE:	
Owner's land or buildings if not paid. Those entitled to	TOTAL MATERIALS:	
lien rights, in addition to Contractor, are those who contract directly with the Owner or those who give the	TOTAL MATERIALS.	
Owner notice within 60 days after they first furnished labor or materials for the construction. Accordingly,	TOTAL LABOR:	
Owner probably will receive notices from those who furnish labor or materials for the construction, and should		
give a copy of each notice received to his mortgage lender, f any. Contractor agrees to cooperate with the Owner and		
nis lender, if any, to see that all potential lien claimants are duly paid.	SUB TOTAL	
ARRIVAL TIME: DEPARTURE TIME:	SALES TAX	

CUSTOMER'S APPROVAL:

TOTAL

Ihn Plumbing Company

633 Cecelia Drive Pewaukee, WI 53072 US +1 2626910402 annie@ihncompany.com www.ihncompany.com

Invoice



BILL TO Ivan & Katie Eisenberg 3405 N. Humboldt Avenue Milwaukee, WI 53212

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
15627	10/10/2022	\$0.00	10/10/2022	Due on receipt	

PLUMBER/TECH

Lining Crew

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
10/10/2022	Sales	Contractor proposes on nish labor and materials for to be performed in according with the following spectory is. Description work CIPP Linit 1.) To furnish and install new CIPP Lining from basement clean out to city main.			12,150.00
		2.) To Clean root infiltration out of existing sewer lateral.			
		3.) To water jet sewer system as needed,	# 1		
		4.) To back fill, intall clean out to proper height.			
		5.) To furnish and install new concrete as needed.			
		If additional work is needed other than listed above it will be at a time and material rate.			
		Payment 60% down to start, balance due upon completion Please make checks payable to			
		IHN Plumbing Company Surcharge of 3.5% added to credit card transactions			
	Refund or Discount		1	-300.00	-300.00

Ihn Plumbing Company

633 Cecelia Drive
Pewaukee, WI 53072 US
+1 2626910402
annie@ihncompany.com
www.ihncompany.com

Invoice

Hello Aran Kratie
Glad we could help
Miss all a surr
Tion 122 days

BILL TO

Ivan & Katie Eisenberg 3405 N. Humboldt Avenue Milwaukee, WI 53212

INVOICE #	DATE	TOTAL DUE	DUE DATE	TERMS	ENCLOSED
15627	10/10/2022	\$8,350.00	10/10/2022	Due on receipt	

PLUMBER/TECH

Lining Crew

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
10/10/2022		Contractor proposes to furnish labor and materials for work to be performed in accordance with the following specifications. Description of work	:		
	Sales	CIPP Lining 1.) To furnish and install new CIPP Lining from basement clean out to city main.			12,150.00
:		2.) To Clean root infiltration out of existing sewer lateral.	:		
		To water jet sewer system as needed,		:	İ
· · · · · · · · · · · · · · · · · · ·	í	4.) To back fill , intall clean out to proper height.		:	:
; ! :	:	5.) To furnish and install new concrete as needed.			
	• • • • • • • • • • • • • • • • • • •	If additional work is needed other than listed above it will be at a time and material rate.		:	
		Payment 60% down to start, balance due upon completion Please make checks payable to IHN Plumbing Company Surcharge of 3.5% added to credit card transactions			
	Refund or Discount		1	-300.00	-300.00

PAYMENT BALANCE DUE 3,500.00

\$8,350.00

OCT 1 : 2022

The Control of the Control

Angstapy . Angstapy

Ţ.				
h		7		
			K	_
W.		a [喜	
	77		9	1

633 Cecelia Dr. • Pewaukee, WI 53072

262-691-0402

www.ihncompany.com

WORKMAN

DATE.

JOB TICKET

TIME

lame (Owr	er/Tenant)	5	7	tame (Owner/Tenant) WAN EIFEN BUILTO Bull To Bill To	мот
ob at		2	The state of the s	TEL TEL	
Tature of Work	ork C	J 3		P.O.	
rand:				Model: Serial:	
	DES	SCRIE	E FUL	DESCRIBE FULLY: Nature of Work Done, Exact Location of Each Fixture or Repair Made, Continue on Reverse Side if Necessary	
Time	From	Po	Hours		AMOUNT
Mon.				of Customed CHOOSES OFFICE A I TO LINE FROM MM	
Tue.				HOCE TO FOUNDATION WINCE	
Wed.		19		SOO ON TURE OF BUTTERS FROM TOTAL CUIT TO ALL	
Thur.				FRONT CIENT BIME TOTO	
Fri.					
Sat.					
F	TOTAL HOTIES	36			(

RIGHTS ON THE OWNER'S LAND AND BUILDINGS IF NOT PAID. THOSE ENTITLED TO LIEN RIGHTS, IN ADDITION TO NOTICE WITHIN 60 DAYS AFTER THEY FIRST FURNISH LABOR OR MATERIALS FOR THE CONSTRUCTION. MATERIALS FOR THE CONSTRUCTION, AND SHOULD GIVE A COPY OF EACH NOTICE RECEIVED TO HIS MORTGAGE IHN COMPANY, INC, ARE THOSE WHO CONTRACT DIRECTLY WITH THE OWNER OR WHO GIVE THE OWNER A AS REQUIRED BY THE WISCONSIN CONSTRUCTION LIEN LAW, BUILDER HEREBY NOTIFIES OWNER THAT PERSONS OR COMPANIES FURNISHING LABOR OR MATERIALS FOR CONSTRUCTION ON THE OWNER'S LAND MAY HAVE LIEN ACCORDINGLY, THE OWNER WILL PROBABLY RECEIVE NOTICES FROM THOSE WHO FURNISH LABOR OR LENDER, IF ANY. BUILDER AGREES TO COOPERATE WITH THE OWNER AND HIS LENDER, IF ANY, TO SEE THAT ALL POTENTIAL LIEN CLAIMANTS ARE DULY PAID.

Min. Material Charge - \$20

3.5% cc surcharge

Sub-Total

Trip Charge

Labor

5.1%

Tax

Other

Total

and enable us to give you absolute satisfactory service. You are respectfully requested to examine the material and labor statement before workmen leave the job and if you find everything satisfactory, okay this ticket. If service is unsatisfactory in any way, please phone our office TO THE CUSTOMER: Service men are required to have work slips signed. This is done in order to protect you, the workmen and ourselves, mmediately.

I the undersigned, find the time and material charged above satisfactory and agree to pay at the time of completion.

Signed:

	DISCOVER	
000		or Charge





