



South (main) façade



South Facade



West Facade



West Facade



West Facade



West Façade, 1901 addition evident on left



North Facade



North Facade





North Facade



North façade entryway



Fireplace surround



Formal parlor



Dining room



Dining room



Decorative door hinge



Partially dug basement





Corbelled chimney close up



Circa 1983 Chapel




Chapel north façade



Chapel interior



Chapel framing



Chapel stained glass windows



Chapel door lintel detail



Chapel exterior, capital reused from demolished Milwaukee building





Rear yard looking north