



SOUTHEAST
CORNER

NORTHEAST
CORNER

SOUTHEAST
ROOF



PILASTER
AT FRONT
DOOR

FRONT
WALK

PILASTER
BASE AT
FRONT DOOR
w/o PLINETH



FRONT
COVERED
ENTRY

FRONT
DOOR

FRONT
ENTRY
PILASTER



SOUTH SIDE
3RD FLOOR
DORMERS

NORTHEAST
GUTTER

SOUTH EAST
2ND FLOOR



PROTECTED
AREA -

NORTH SIDE

FRONT
PORCH

NORTHEAST

CORNER -

VIEW OF

FAILED

PANTRY

GUTTER




NORTHEAST
CORNER

FRONT
FACADE

—
3RD FLOOR
DORMER

EAVE
PROBLEMS



NORTH ~~WEST~~ REAR

EAVE
PROBLEMS

NORTH EAST
2 STORY PLASTER



WATER
TABLE
DEFECTS

S.E.
PLASTER
BASE

S.E.
PLASTER
BASE



EAVE
&
CHIMNEY
AREA

BETTER
PILASTER
CAP

PORCH
FINIAL



SOUTH
WALL

REAR
OF
HOUSE

N.E
PLASTER
BASE