

May 19, 2009

To Whom It May Concern:

My name is Silvestre Villarreal. My address is 1510 S. 37<sup>th</sup> St Milwaukee, WI 53215. I can be reached at 414-750-7024.

On May 16, 2009 I was visiting the following address 2540 S. 9<sup>th</sup> Place in Milwaukee, WI 53215, but had my car parked at 2562 S. 9<sup>th</sup> Place in Milwaukee, WI 53215. Between 8:00 and 8:30 am a tree branch fell on my car. A neighbor called me and told me about it and then a police officer showed up. The officer told me not to worry about it that city workers will show up to cut the branch so my car could be moved. They arrived between 10:15 and 10:30 am.


A statement of damages is attached.

Thank You



Silvestre Villarreal

Enclosures



Francisco J. Pedroza

My commission expires 03/20/2011

Notary Public

State of Wisconsin

City Of Milwaukee

CITY OF MILWAUKEE  
RECEIVED  
2009 MAY 20 PM 3:37  
CITY ATTORNEY

CITY OF MILWAUKEE  
2009 MAY 20 AM 10:03  
RONALD D. LEONARD  
CITY CLERK

METROPOLITAN CADILLAC, INC.  
 10221 WEST ARTHUR AVENUE  
 WEST ALLIS, WI 53227  
 PHONE: (414) 327-1400 FAX: (414) 546-5490

CD LOG NO 9677-1 DATE 05/19/09

SHOP: METROPOLITAN CADILLAC  
 CITY STATE: , WI

INSP DATE: 05/19/09  
 CONTACT: DAN SHELBY

OWNER: VILLARREAL, SILVESTRE  
 ADDRESS: 1510 S 37TH ST  
 CITY STATE: MILWAUKEE, WI  
 ZIP: 53215

HOME PHONE: (414)750-7024

POINT OF IMPACT: 34

DAYS TO REPAIR: 19

LIC#: .  
 BODY COLOR: BLACK  
 CONDITION:

STATE:

VIN: 1GYEK13R5YR134844  
 MILEAGE: 121,650  
 ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

\*\*\*ESTIMATE FOR VISIBLE DAMAGE ONLY...ADDL DAMAGE POSSIBLE\*\*\*  
 POSSIBLE TOTAL LOSS

2000 CADILLAC ESCALADE STD 4DOOR WAGON 8CYL GASOLINE 5.7  
 CODE: T7104A/B OPTNS R/24A

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES  
 DUAL REAR DOORS

TWO-STAGE - INTERIOR SURFACES

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	B%	HOURS	R
---	---	---	-----	-----	-----	---	---	-----	-
L	0621		COMPLETE SIDE	LT REFINISH				10.7	4
				10.5 SURFACE					
				0.2 TWO STAGE					
L	0622		COMPLETE SIDE	RT REFINISH				10.5	4
				10.5 SURFACE					
				INC TWO STAGE					
UM	0006		COVER, FRONT BUMPER	REMAN/REBUILT PAR	480.00*			1.9	1
L	0006	13	COVER, FRONT BUMPER	REFINISH				3.7	4

			2.6 SURFACE			
			0.6 TWO STAGE SETUP			
			0.5 TWO STAGE			
EC0083	PANEL, HOOD		ECONOMY PART	520.00*		1.6 1
L 0083	PANEL, HOOD		REFINISH			5.7 4
			3.3 SURFACE			
			1.4 EDGE			
			1.0 TWO STAGE			
RI0107	MLDG, WHEEL OPENING	LT	R&I ASSEMBLY			2.5 1
RI0108	MLDG, WHEEL OPENING	RT	R&I ASSEMBLY			1.7 1
SB0143	WINDSHIELD, SHADED		SUBLET REPAIR	380.00*+20.00		1
I 0209	PNL, FRONT DOOR OUTE	LT	REPAIR			3.0*1
I 0210	PNL, FRONT DOOR OUTE	RT	REPAIR			4.0*1
RI0246	MLDG, FRONT DOOR LOW	LT	R&I ASSEMBLY			0.4 1
RI0247	MLDG, FRONT DOOR LOW	RT	R&I ASSEMBLY			0.4 1
E 0386	N/PLATE, FRONT DOOR	LT	15031383 GM PART	36.59		0.2 1
E 0387	N/PLATE, FRONT DOOR	RT	15031383 GM PART	36.59		0.2 1
RI0248	MIRROR, OUTER R/C	LT	R&I ASSEMBLY			0.3 1
EU0249	MIRROR, OUTER R/C	RT	SALVAGE PART	300.00*+25.00		0.3 1
L 0249	MIRROR, OUTER R/C	RT	REFINISH			0.6 4
			0.5 SURFACE			
			0.1 TWO STAGE			
RI0227	HANDLE, FRONT DOOR O	LT	R&I ASSEMBLY			1.1 1
RI0228	HANDLE, FRONT DOOR O	RT	R&I ASSEMBLY			1.1 1
EU0287	DOOR ASSEMBLY, REAR	LT	SALVAGE PART	450.00*+25.00		1.8 1
I 0290	PNL, REAR DOOR OUTER	RT	REPAIR			1.5*1
RI0115	W/STRIP, BELT OUTER	LT	R&I ASSEMBLY			0.3 1
RI0116	W/STRIP, BELT OUTER	RT	R&I ASSEMBLY			0.7 1
RI0508	MLDG, REAR DOOR LOWE	LT	R&I ASSEMBLY			0.5 1
RI0509	MLDG, REAR DOOR LOWE	RT	R&I ASSEMBLY			0.5 1
RI0305	HANDLE, RR DOOR OUTE	LT	R&I ASSEMBLY			INC 1
RI0306	HANDLE, RR DOOR OUTE	RT	R&I ASSEMBLY			0.2 1
E 0341	PANEL, ROOF		15740023 GM PART	676.36		28.8 1
L 0341	PANEL, ROOF		REFINISH			5.6 4
			4.7 SURFACE			
			0.9 TWO STAGE			
EC0369	RACK ASSEMBLY, LUGGAGE		ECONOMY PART	524.88*		INC 1
EU0541	GLASS, BACK DOOR HTD	LT	SALVAGE PART	320.00*+25.00		1.6 1
EU0542	GLASS, BACK DOOR HTD	RT	SALVAGE PART	320.00*+25.00		1.6 1
E 0586	LAMP, HIGH MOUNTED STOP		15030176 GM PART	205.97		INC 1
ECM03	FLEX ADDITIVE		ECONOMY PART	5.00*		4
SBM06	PINSTRIPES-PAINTED		SUBLET REPAIR	220.00*+20.00		4*
SBM07	PINSTRIPES-TAPE		SUBLET REPAIR	270.00*+20.00		1*
I M14	CORROSION PROTECTION		REPAIR	*		0.5*4*
ECM17	COVER CAR EXTERIOR		ECONOMY PART	10.00*		4*
N	MASK JAMBS		ADDNL LABOR OPERA			1.0*1*

40 ITEMS

MC MESSAGE(S)  
 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES  
 GROSS PARTS

955.51

2000 CADILLAC ESCALADE STD 4DOOR WAGON  
 CD LOG NO 9677-1

OTHER PARTS				2,929.88
LINE ITEM MARKUP				347.50+
PAINT MATERIAL				999.00**
PARTS & MATERIAL TOTAL				5,231.89
TAX ON PARTS & MATERIAL @			5.600%	292.99

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	52.00	47.7	9.5	2,974.40
2-MECH/ELEC	90.00			
3-FRAME	55.00			
4-REFINISH	52.00	36.8	0.5	1,939.60
5-PAINT MATERIAL	32.00			
LABOR TOTAL				4,914.00
TAX ON LABOR		@	5.600%	275.18
SUBLET REPAIRS				1,044.00
TAX ON SUBLET		@	5.600%	58.46
TOWING				
STORAGE				

GROSS TOTAL				11,816.52
NET TOTAL				11,816.52

SHOPLINK U1486 ES CD LOG 9677-1 DATE 05/19/09 03:49:31PM R6.37 CD 05/09  
 PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53227  
 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

\*\*USER-ESTABLISHED THRESHOLD FOR PAINT MATERIAL HAS BEEN REACHED AND CALCULATED IN THIS ESTIMATE. ANY ADDITIONAL MATERIALS MAY REQUIRE FURTHER APPROVAL.

3.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA. AUDATEX TWO-STAGE EXTERIOR THRESHOLD OF 2.5 HOURS WAS CALCULATED IN THIS ESTIMATE.

-----  
 THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.



Office of the City Clerk

Ben E. Johnson  
City Clerk

Wm. Mudgett  
Deputy City Clerk

INSTRUCTIONS FOR FILING A CLAIM AGAINST THE CITY OF MILWAUKEE

To file a claim against the City of Milwaukee which complies with sec. 893.80, Stats., the following information must be submitted in writing to the City Clerk, Room 205, City Hall, 200 East Wells Street 53202:

1. A document stating the circumstances of the claim, which must be signed by the claimant, or his/her agent or attorney. This document should be filed within 120 days of the event.
2. A document stating the address of the claimant and a statement of the relief sought. If money damages are sought, a specific sum must be stated.

The above information may be combined in a single document.

In order to allow the City to thoroughly and promptly act on your claim, the following information should also be submitted:

1. Proof of the amount of the claim by means of either estimates or receipted bills.
2. Your phone number where you can be reached during business hours.
3. As detailed a description of the incident as possible, including the date, time and place.

BEN E. JOHNSON  
City Clerk













