

7-21-16

OFFICE OF THE CITY CLERK
Milwaukee Wisconsin

INSTRUCTIONS FOR FILING A CLAIM AGAINST THE CITY OF MILWAUKEE

RECEIVED
AUG 18 2016
OFFICE OF
CITY ATTORNEY

To file a claim against the City a claimant must comply with Section 893.80(1), Wis. Stats., a copy of which is printed on the reverse side of this instruction sheet. Generally the statute requires the claimant to submit to the City Clerk:

- I. A document stating the circumstances of the claim which must be signed by the claimant, or his/her agent or attorney. This document should be filed within 120 days of the event.
2. A document stating the address of the claimant and a statement of the relief sought. If money damages are sought, a specific sum must be stated.

(The above information may be combined in a single document.)

The following information should also be submitted to allow the City to promptly act on your claim:

1. Proof of the amount of the claim by means of either itemized receipts or two itemized estimates.
2. A phone number where the claimant can be reached during business hours as well as the claimant's e-mail address, if any.
3. As detailed a description of the incident as possible, including the date, time and place.

All information should be submitted to:

City Clerk
ATTN: CLAIMS
200 E. Wells St., Room 205
Milwaukee, WI 53202-3567

ADDITIONAL INFORMATION

Before you can file a lawsuit against the City of Milwaukee for reimbursement, State law requires that you first follow the claim procedures established by the City Clerk.

Filing a claim against the City does not automatically guarantee reimbursement from the City. However, the City examines each claim on an individual basis in determining if reimbursement is legally required.

In order to obtain reimbursement for a claim against the City, you must prove that the City or its employees acted unlawfully, or negligently.

Only the City Attorney or the Common Council and the Mayor can authorize payment of a claim against the City. Any other representations made by City employees are not legally binding on the City.



Scott A English
1041 South 22nd St Lower
Milwaukee, WI 53204
414-841-1703 House: 414-837-4499

Milwaukee Auto Glass And Sound LLC
1400 West Mitchell Street
Milwaukee, WI 53204
(414) 430-5400 / Fax (414) 647-8615

Quote #	Q MKE0018674	Date	07/22/2016
Cust. #	4147152206	Billcode	WI
P.O. #		Sold By	
Fed. Tax #		Inst'l By	

Viola, Scott A English

() -

Year	2004	Make	FORD	Policy #	
Model	EXPLORER	Body Style	4 DOOR UTILITY	Author-ized By	
Lic. #		V.I.N.		Claim #	
Home Phone	() -	Bus. Phone	() -	Loss Date	07/22/2016
				Damage/ Cause	

Qty.	Part	Description	Block Size	List	Price	Total
1	DW01474GBYN	Windshield (slr contr)	33.2 x 64.4	251.20	175.00	175.00
1	LABOR	Labor 2.70 hours		0.00	0.00	
raessr						
1	HAH000448	2.0 Fast-Cure Urethane, Dam, Primer		0.00	0.00	0.00

Milwaukee Auto Glass & Sound LLC thanks you for your business!

RECEIVED
AUG 18 2016
 OFFICE OF
 CITY ATTORNEY

SPECIAL INSTRUCTIONS		Subtotal	175.00
INSTALLATION WARRANTY. We warranty the installation of windshield or back glass as long as the present owner continues to own or lease the vehicle. This means that new windshield or back glass will be properly installed and sealed by an experienced technician. It will not leak unless it is broken or the vehicle has rust around it. This guarantee is limited to repair or replacement by Milwaukee Auto Glass & Sound. Note that any rust in the pinchweld area may void the leakage warranty. Any rust repairs needed are the sole responsibilities of the owner. This warranty covers only the replacement mentioned above, and does not cover any incidental, indirect, or consequential damages.		Labor	0.00
		Tax	9.80
		Total	184.80
Terms of payment are 0 days from invoice date. A service charge of 0.00% per month (0.00% annum) will be added to past due accounts.		Balance	184.80
RECEIVED BY <i>Viola A English</i> 7/22/16 11:09am by ADMIN Updated 7/22/16 11:09am by ADMIN	The glass listed has been replaced / repaired with like kind and quality to my entire satisfaction, and I authorize my Insurance Company to pay Milwaukee Auto Glass And Sound LLC directly for the glass and Installation charges, or repairs.		



CARSTAR LOU'S AUTO BODY

Workfile ID: 76fe4b57

3940 S 13TH ST, MILWAUKEE, WI 53221
Phone: (414) 481-9449

RECEIVED
AUG 18 2016

Estimate

RO Number:

OFFICE OF
CITY ATTORNEY

Customer:	Insurance:	Adjuster:	Estimator:	Lando Arce
SCOTT, ENGLISH	CUSTOMER PAY	Phone:	Create Date:	7/27/2016
1041 S 22ND STREET		Claim:		
MILWAUKEE, WI 53204		Loss Date:		
(414) 841-1703		Deductible:		

2004 FORD EXPLORER 4X4 XLT 4D UTV 6-4.0L-FI

VIN: 1FMZU73K84ZB39596	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color:	Mileage Out:	
State:	Production Date:	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		HOOD						
2	E01	Remove/Replace	Hood	1	928.78T	OEM	1.4T	Body	3.0T
3	E01		Add for Clear Coat						1.2T
4	E01		Add for Underside(Complete)						1.5T
5	E01	Remove/Replace	BUG SHEILD	1	95.00T	Other	0.6T	Body	
6	E01		FENDER						
7	E01	Repair	RT Fender w/o wheel opng molding				1.0T	Body	2.2T
8	E01		Overlap Major Adj. Panel						(0.4)T
9	E01		Add for Clear Coat						0.4T
10	E01	Repair	LT Fender w/o wheel opng molding				2.0T	Body	2.2T
11	E01		Overlap Major Adj. Panel						(0.4)T
12	E01		Add for Clear Coat						0.4T
13	E01		ELECTRICAL						
14	E01	Remove/Install	Mast				0.1T	Body	
15	E01	Remove/Install	Bezel				0.1T	Body	
16	E01		WINDSHIELD						
17	E01	Remove/Install	Windshield Ford tinted				0.0T	Body	
18	E01		ROOF						
19	E01	Remove/Replace	Roof panel w/o sunroof	1	1,656.97T	OEM	18.5T	Body	3.8T
20	E01		Overlap Major Adj. Panel						(0.4)T
21	E01		Add for Clear Coat						0.7T
22	E01	Remove/Replace	RT Side rail	1	243.33T	OEM	0.5T	Body	
23	E01	Remove/Install	LT Side rail				0.5T	Body	
24	E01		PILLARS, ROCKER & FLOOR						
25	E01	Repair	RT Uniside assy				1.0T	Body	4.2T

CITY CLERK'S OFFICE
 2016 AUG 17 AM 9:26
 CITY OF MILWAUKEE

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2004 FORD EXPLORER 4X4 XLT 4D UTV 6-4.0L-FI

26	E01		Overlap Major Non-Adj. Panel					(0.2)T
27	E01		Add for Clear Coat					0.8T
28	E01	Repair	LT Uniside assy			3.0T	Body	4.2T
29	E01		Overlap Major Non-Adj. Panel					(0.2)T
30	E01		Add for Clear Coat					0.8T
31	E01		REAR DOOR					
32	E01	Repair	RT Door shell w/o wheel opng moldngs			4.0T	Body	2.3T
33	E01		Overlap Major Adj. Panel					(0.4)T
34	E01		Add for Clear Coat					0.4T
35	E01	Remove/Install	RT Belt w'strip			0.3T	Body	
36	E01	Remove/Install	RT Vent glass Ford, w/o chrome gray tint			0.7T	Body	
37	E01	Remove/Install	RT Door glass Ford gray tint			0.0T	Body	
38	E01	Remove/Install	RT R&I trim panel			0.5T	Body	
39	E01	Repair	LT Door shell w/o wheel opng moldngs			1.0T	Body	2.3T
40	E01		Overlap Major Adj. Panel					(0.4)T
41	E01		Add for Clear Coat					0.4T
42	E01	Remove/Install	LT Belt w'strip			0.3T	Body	
43	E01	Remove/Install	LT Vent glass Ford, w/o chrome gray tint			0.7T	Body	
44	E01	Remove/Install	LT Door glass Ford gray tint			0.0T	Body	
45	E01	Remove/Install	LT R&I trim panel			0.5T	Body	
46	E01		QUARTER PANEL					
47	E01	Repair	RT Quarter panel XLT, EDDIE BAUER, LIMITED			7.0T	Body	2.4T
48	E01		Overlap Major Adj. Panel					(0.4)T
49	E01		Add for Clear Coat					0.4T
50	E01	Remove/Install	RT Qtr glass Ford gray tint			1.4T	Body	
51	E01	Remove/Install	LT Qtr glass Ford gray tint			1.4T	Body	
52	E01	Remove/Replace	Cover car	1	8.00T	Other	0.3T	Body
53	E01	Remove/Replace	Urethane kit	3	89.85T	Other		
54	E01	Sublet	Hazardous waste removal	1	3.50T	Other		
55	E01	Remove/Replace	Corrosion protection	1	8.00T	Other	0.3T	Body

RECEIVED

AUG 18 2016

**OFFICE OF
CITY ATTORNEY**

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					3,029.93
Sublet/Miscellaneous					3.50
Labor, Body			56.00	47.1	2,637.60
Labor, Refinish			56.00	30.8	1,724.80
Material, Paint					1,108.80
Subtotal					8,504.63
Sales Tax					476.26
Grand Total					8,980.89

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2004 FORD EXPLORER 4X4 XLT 4D UTV 6-4.0L-FI

Net Total	8,980.89
------------------	-----------------

Estimate Version	Total \$
Original	8,980.89

Insurance Total \$:	8,980.89
Received from Insurance \$:	0.00
<hr/> Balance due from Insurance \$:	<hr/> 8,980.89

Customer Total \$:	0.00
Received from Customer \$:	0.00
<hr/> Balance due from Customer \$:	<hr/> 0.00

RECEIVED

AUG 18 2016

OFFICE OF
CITY ATTORNEY



TENDERCAR

Workfile ID: 157224db

The Customer's Direct Repair Shop
1825 S. Kinnickinnic Ave, Milwaukee, WI 53204
Phone: (414) 389-1014
FAX: (414) 389-1779

RECEIVED

AUG 18 2016

OFFICE OF
CITY ATTORNEY

Estimate

RO Number:

Customer:	Insurance:	Adjuster:	Estimator:	Jon/Kelsey
English, Scott	CUSTOMER PAY	Phone:	Create Date:	7/26/2016
1041 S 22 st		Claim:		
Milwaukee, WI 53204		Loss Date:		
(414) 841-1703		Deductible:		

2004 FORD EXPLORER 4X4 NBX 4D UTV 6-4.0L-FI silver

VIN: 1FMZU73K84ZB39596	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color: silver	Mileage Out:	
State:	Production Date:	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		HOOD						
2	E01	Remove/Replace	Hood	1	928.78T	OEM	1.4T	Body	3.0T
3	E01		Add for Clear Coat						1.2T
4	E01		Add for Two Tone						1.2T
5	E01		Add for Underside(Complete)						1.5T
6	E01	Remove/Install	Insulator				0.0T	Body	
7	E01	Remove/Install	Deflector				0.2T	Body	
8	E01		FENDER						
9	E01	Repair	RT Fender w/o wheel opng molding				4.0T	Body	2.2T
10	E01		Overlap Major Adj. Panel						(0.4)T
11	E01		Add for Clear Coat						0.4T
12	E01		Add for Two Tone						0.5T
13	E01	Repair	LT Fender w/o wheel opng molding				4.0T	Body	2.2T
14	E01		Overlap Major Adj. Panel						(0.4)T
15	E01		Add for Clear Coat						0.4T
16	E01		Add for Two Tone						0.5T
17	E01		ROOF						
18	E01	Remove/Replace	Roof panel w/o sunroof	1	1,656.97T	OEM	18.5T	Body	3.8T
19	E01		Overlap Major Adj. Panel						(0.4)T
20	E01		Add for Clear Coat						0.7T
21	E01		Add for Two Tone						1.0T
22	E01	Remove/Install	RT Side rail				0.5T	Body	
23	E01	Remove/Install	LT Side rail				0.5T	Body	
24	E01	Remove/Install	Cross rail				0.2T	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2004 FORD EXPLORER 4X4 NBX 4D UTV 6-4.0L-FI silver

25	E01	Remove/Install	Cross rail retainer					0.1T	Body	
26	E01	Remove/Install	Headliner w/o head airbag, w/o rear heat/AC graphite					0.0T	Body	
27	E01		PILLARS, ROCKER & FLOOR							
28	E01	Repair	RT Unside assy					10.0T	Body	4.2T
29	E01		Overlap Major Non-Adj. Panel							(0.2)T
30	E01		Add for Clear Coat							0.8T
31	E01		Add for Two Tone							1.2T
32	E01	Repair	RT Upper plr reinf					2.0T	Body	
33	E01	Remove/Replace	LT Upper plr reinf							
34	E01		FRONT DOOR							
35	E01	Repair	RT Door shell					1.0T	Body	2.4T
36	E01		Overlap Major Adj. Panel							(0.4)T
37	E01		Add for Clear Coat							0.4T
38	E01		Add for Two Tone							0.6T
39	E01	Remove/Install	RT Mirror assy w/o light, w/o heat					0.4T	Body	
40	E01	Repair	LT Door shell					1.0T	Body	2.4T
41	E01		Overlap Major Adj. Panel							(0.4)T
42	E01		Add for Clear Coat							0.4T
43	E01		Add for Two Tone							0.6T
44	E01	Remove/Install	LT Mirror assy w/o light, w/o heat					0.4T	Body	
45	E01	Remove/Install	RT Handle, outside black texture					0.4T	Body	
46	E01	Remove/Install	LT Handle, outside black texture					0.4T	Body	
47	E01	Remove/Replace	RT Nameplate "EXPLORER"	1	46.32T	OEM		0.2T	Body	
48	E01	Remove/Replace	LT Nameplate "EXPLORER"	1	46.32T	OEM		0.2T	Body	
49	E01		REAR DOOR							
50	E01	Repair	RT Door shell w/wheel opng moldings					5.0T	Body	2.3T
51	E01		Overlap Major Adj. Panel							(0.4)T
52	E01		Add for Clear Coat							0.4T
53	E01		Add for Two Tone							0.6T
54	E01		QUARTER PANEL							
55	E01	Repair	RT Quarter panel XLT, EDDIE BAUER, LIMITED					10.0T	Body	2.4T
56	E01		Overlap Major Adj. Panel							(0.4)T
57	E01		Add for Clear Coat							0.4T
58	E01		Add for Two Tone							0.6T

RECEIVED

AUG 18 2016

OFFICE OF
CITY ATTORNEY

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					2,678.39
Labor, Body			58.00	60.4	3,503.20
Labor, Refinish			58.00	35.3	2,047.40
Material, Paint					1,341.40
Material, Shop			5.00	57.3	286.50

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2004 FORD EXPLORER 4X4 NBX 4D UTV 6-4.0L-FI silver

Subtotal	9,856.89
Sales Tax	551.99
Grand Total	10,408.88
Net Total	10,408.88

Estimate Version	Total \$
Original	10,408.88

Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	10,408.88
Received from Customer \$:	0.00
Balance due from Customer \$:	10,408.88

Hidden damage possible once tore down

- Any Zarandazchi
Service Writer
Tender Car

RECEIVED
AUG 18 2016
OFFICE OF
CITY ATTORNEY

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural



02/15/2015
10:18 AM
10/15/2015



PHOTO TAKEN
ON 8/10/08
AT 10:30 AM



RECEIVED
JUN 18 2008
MILWAUKEE FIRE DEPARTMENT



4/24/13
MILWAUKEE
MILWAUKEE



02/15/12
10:30 AM
10/15/12