



Stair and ramp
to be replaced.

Exhibit A
View of south facade along E. Wells St.



Exhibit B
View of west facade along N. Jackson St.
Ramp and stair are generally obscured
by trees.



Exhibit C
View of east facade of ramp and stair.
Existing gas meter to remain.



Exhibit D
View of west facade of ramp. Tree to the west
obscures most of this view from N. Jackson St.



Exhibit E
Alternate view of south facade along
E. Wells Ave.