To whom it may concern,

The month of February ,2024 my white van was parked in front of my neighbor's house at 7638 W Howard Ave. The garbage cans were already put out for collection in front of 7708 W Howard Ave. Garbage truck tried to slide in between my vehicle and the garbage can curbside and caught the driver side corner of my vehicle causing damage.

I am submitting 2 estimates for damages and also pictures that were taken.

I'm requesting the amount of \$3,350.00 to pay for repairs.

If you have any questions please feel free to call me at 414.446.1358.

Regards,

Frank Pero

A STICK ALSO FO BOTTED

2024 JUN 21 PM 12: 28



Gerber Collision & Glass - Hales Corners

Highly Wreck - ommended! 6135 S 108th St, Hales Corners, WI 53130

Phone: (414) 427-8500

0dbc5200 Workfile ID: 51-0394062 Federal ID: State ID: N/A N/A Federal EPA: State EPA: N/A

Preliminary Estimate

Customer: Peror, Frank

Written By: Kathleen Penkert

Gerber Collision & Glass - Hales Corners

Insured:

Peror, Frank

Policy #:

Claim #:

SELF PAY

78,931

Type of Loss:

Point of Impact: 11 Left Front

Date of Loss:

Days to Repair: 0

Owner:

Peror, Frank

Inspection Location:

Insurance Company:

7708 W Howard Ave Milwaukee, WI 53220

6135 S 108th St

Hales Corners, WI 53130

(414) 446-1358 Cell

Repair Facility

(414) 427-8500 Business

VEHICLE

2018 DODG Grand Caravan SXT 4D VAN 6-3.6L Flex Fuel Sequential MPI White

VIN:

State:

2C4RDGCG3JR263930

Interior Color:

Mileage In:

Vehicle Out:

License: ANH3126 WI

Exterior Color:

White

Mileage Out:

Job #:

Production Date:

4/2018

Condition:

TRANSMISSION

Automatic Transmission

POWER

Power Steering Power Brakes **Power Windows**

Power Locks

Power Mirrors

Heated Mirrors Power Driver Seat

DECOR

Dual Mirrors Body Side Moldings

Privacy Glass

Console/Storage

Overhead Console **Wood Interior Trim** CONVENIENCE

Air Conditioning

Intermittent Wipers Tilt Wheel

Cruise Control Rear Defogger

Keyless Entry Alarm

Steering Wheel Touch Controls

Rear Window Wiper Telescopic Wheel Climate Control

Dual Air Condition Backup Camera

Dual Power Sliding Doors

Remote Starter **RADIO**

AM Radio FM Radio Stereo

Search/Seek CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes **Traction Control**

Stability Control Front Side Impact Air Bags Head/Curtain Air Bags Hands Free Device

ROOF

Luggage/Roof Rack

SEATS

Bucket Seats

Reclining/Lounge Seats

3rd Row Seat Retractable Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps Rear Spoiler

California Emissions

TRUCK

Rear Step Bumper Power Trunk/Liftgate

Customer: Peror, Frank

2018 DODG Grand Caravan SXT 4D VAN 6-3.6L Flex Fuel Sequential MPI White

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUI	MPER						
2			O/H front bumper				2.0	
3	** <>	Repl	A/M CAPA Bumper cover	68088966AB	1	299.00	Incl.	3.0
4			Add for Clear Coat					1.2
5		R&I	Air shield				Incl.	
6		R&I	RT Fog lamp bezel				Incl.	
7		R&I	LT Fog lamp bezel				Incl.	
8		R&I	License mount				0.2	
9	GRILLE						2-11-4-0	
10		R&I	Upper grille chrome				Incl.	
11	**	Repl	A/M CAPA Lower grille	68100690AA	1	145.00	Incl.	
12	FRONT LAN	4PS						
13	*	Repl	LKQ LT Headlamp assy w/o black bezel +30%	5113337AI	1	228.80	0.5	t
14		R&I	RT Fog lamp assy				Incl.	
15		R&I	LT Fog lamp assy				Incl.	
16		Repl	Aim headlamps		1		0.5	
17	FENDER							
18	*	Rpr	LT Fender				3.0	2.2
19			Overlap Major Non-Adj. Panel					-0.2
20			Add for Clear Coat					0.4
21		R&I	LT Fender liner				0.4	
22	VEHICLE D	IAGNOST	ICS					
23	*		Pre-repair scan		1		m <u>0.5</u> D	
24	*		Post-repair scan		1		m <u>0.5</u> D	
25	#	Subl	Hazardous Waste		1	3.50	Т	
26	#		Cover Car		1	10.00	Т	
27	#	Repl	Corrosion Protection		1	5.00		
28	#	Repl	Flex Additive		1	11.00	Т	
29	#		*May find additional damahe once the bumper cover is removed		1			
				SUBTOTALS		702.30	7.6	6.6

Customer: Peror, Frank

2018 DODG Grand Caravan SXT 4D VAN 6-3.6L Flex Fuel Sequential MPI White

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				677.80
Body Labor	6.6 hrs	@	\$ 80.00 /hr	528.00
Paint Labor	6.6 hrs	@	\$ 80.00 /hr	528.00
Diagnostic Labor	1.0 hrs	@	\$ 129.00 /hr	129.00
Paint	6.6 hrs	@	\$ 58.00 /hr	382.80
Body Supplies	4.0 hrs	@	\$ 10.00 /hr	40.00
Miscellaneous				24.50
Subtotal				2,310.10
Sales Tax	\$ 2,310.10	@	5.9000 %	136.30
Grand Total				2,446.40

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Customer: Peror, Frank

2018 DODG Grand Caravan SXT 4D VAN 6-3.6L Flex Fuel Sequential MPI White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3TE08, CCC Data Date 04/01/2024, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Customer: Peror, Frank

2018 DODG Grand Caravan SXT 4D VAN 6-3.6L Flex Fuel Sequential MPI White

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
3	KSI Trading Corp.	#1386424Q	\$ 299.00
	5414A West Roosevelt Road	A/M CAPA Bumper cover	
	Chicago IL 60644	Quote: 132798170	
	(800) 244-2639	Expires: 04/12/24	
11	KSI Trading Corp.	#1386317Q	\$ 145.00
	5414A West Roosevelt Road	A/M CAPA Lower grille	
	Chicago IL 60644	Quote: 132798334	
	(800) 244-2639	Expires: 04/12/24	
13	All Star Auto Parts North	#02062429	\$ 176.00
	15326 Oakwood Dr	LKQ LT Headlamp assy w/o black bezel +30%	
	Romulus MI 48174	LH,HAL,BARE,PR0020	
	(407) 271-8949	Quote: CCC-225711260	
		Expires: 04/15/24	

CONCOURS AUTO WORKS, LTD. 9508 WEST NATIONAL AVENUE WEST ALLIS, WI 53227 OFFICE: (414) 321-4200

*** PRELIMINARY ESTIMATE ***

03/08/2024 02:22 PM

Owner

Owner: FRANK PERO

Address: 7708 W. HOWARD AVE

City State Zip: Milwaukee, WI 53220

Cell: (414)446-1358

FAX:

Inspection

Inspection Date: 03/08/2024 02:22 PM

Inspection Type:

Repairer

CONCOURS AUTO WORKS,

Repairer: LTD.

Address: 9508 WEST NATIONAL AVENUE

City State Zip: WEST ALLIS, WI 53227

Email: milwaukeesfinest@concoursautoworks.com

Target Complete Date/Time:

Contact: Michael

Work/Day: (414)321-4200

FAX: (414)321-4106

Days To Repair: 6

Vehicle

2018 Dodge Caravan Grand SXT 4 DR Passenger Van 6 cyl Gas Flex Fuel 3.6 6-Speed Automatic

> Lic Expire: Veh Insp# : Condition:

Ext. Refinish: Two-Stage

VIN: 2C4RDGCG3JR263930

Mileage Type: Actual Code: N6664C

Int. Refinish: Two-Stage

3rd Row Head Airbags

Anti-Lock Brakes

Chrome Grille

Bodyside Moldings

Options

1st Row LCD Monitor(s)
AM/FM CD Player
Automatic Dimming Mirror
Bucket Seats
Color-Keyed Bumper(s)
Driver Information Sys

Dual Airbags
Elect. Stability Control
Halogen Headlights
Heated Rear Window Wiper
Illuminated Visor Mirror
Keyless Ignition System

Leather Seats Overhead Console Power Door Locks Power Quarter Windows 2nd Row Head Airbags Aluminum/Alloy Wheels Auxiliary Audio Input Center Console Cruise Control Driver Knee Airbag Dual Power Sliding Doors Electro-Hyd Steering Head Airbags

Heated Rear Wiper Park Intermittent Wipers Knee Air Bags Lighted Entry System Perimeter Alarm System Power Drivers Seat

Power Steering

Daytime Running Lights
Dual Air Conditioning
Dual Zone Auto A/C
Floor Mats
Heated Power Mirrors
Heavy Duty Cooling
Keyless Entry System
LED Brakelights
MP3 Decoder
Power Brakes
Power Liftgate
Power Windows

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries						
OEM Parts					\$218.60	
Other Parts					\$829.00	
Paint & Materials		10.0	Hours @ \$!	58.00	\$580.00	
Parts & Material Total						\$1,627.60
Tax on Parts & Material			@ 5.	900%		\$96.03
Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs		
Sheet Metal (SM)	\$78.00	4.1	3.4	7.5	\$585.00	
Mech/Elec (ME)	\$165.00		1.0	1.0	\$165.00	
Frame (FR)	\$82.00					
Refinish (RF)	\$78.00	10.0		10.0	\$780.00	
Labor Total				18.5 H	ours	\$1,530.00
Tax on Labor Sublet Repairs		(9 5.900%		\$90.27 \$5.00	
Tax on Sublet Gross Total Net Total		(D 5.900%		\$0.30	\$3,349.20 \$3,349.20

Alternate Parts Y/04/01/00/03/03 Cumulative 04/01/00/03/03 Zip Code: 53227 Default Rate Name Default

Audatex Estimating 10.26.70 ES 03/08/2024 02:26 PM REL 10.26.70 DT 02/01/2024 DB 03/01/2024 State Disclosure:WI

© 2024 Audatex North America, LLC.

A 90% Blend Refinish calculation of basecoat refinish labor was used for applicable panels on this estimate. 2.0 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM= Replace PXN Reman/Rebit
UM= Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG= Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage

03/08/2024 02:26 PM

Butch's Auto Repair & Body Shop Estimate / Impoles

Butch Krasuba (847) 520 5024

The second secon	Ark fele		man of the of the	4-110 tan S	MET I		
ien United p Improve con		104178	T. J. S	STAND C	discussed by		
enema erus Epina (hen	The transfer of the same		Alperton .				
V	TRAIL	ACADIZATA)		Albert Partie	Marie VALL		
	TARRETA	urnit coll	LIMITER	I hours			
	- 1000 -	1864 (1873) (1884 (1884) 1864 (1874 (1884) (1884) 1864 (1884) (1884)					
		Transport of the second			*****		
	The same of the same						
		en galacia de la composición del la composición del composición de la composición del composición del composición de la composición de la composición del composic	THE SELECTION OF THE SE				
				MAN IS NOT	Torrio		
n della della est e del directorio del	And the West of the Con-	e November (ng staling an ana tro Mal diger atao i gan tao alia ana Katamatan Dicara at ing ala an Malangan kalangan at ing ala an Malangan kalangan Sanarap		17 10 10			
a B A	de tempe pe propos		MAN WATE	TOTAL DURING 1			
1 11	11		And the second s	1 1100.			













