

Debra Berrones  
6904 Eustid ave  
Milw WI 53219

debraberrones@a  
Yahoo. Com  
414-837-7244

CITY OF MILWAUKEE  
2021 NOV 17 PM 2:56  
CITY CLERK'S OFFICE

On Tuesday, Oct 19, 2021, at approximately 10:30 PM. I was stopped behind a street sweeper on 69th & Ohio. He proceeded to go forward, then without warning, began backing up while turning his vehicle and backed right into my vehicle, while I was still at a standstill at the intersection. He then turned the corner and left. It was pitch black out, I exited my car to check for damage and he was gone. You can see the crush marks on my grill, along with all the other damage.

Thank You  
Debra Berrones  
(over)

Before This occurred, my  
car was in perfect condition,  
with out a scratch on it.  
Now it looks Like  
Dumper car.

OFFICE OF CITY ATTORNEY  
02 NOV 21 PM 03:43

WEST ALLIS AUTO BODY  
8808 W. NATIONAL AVE.  
WEST ALLIS, WISC 53227  
PHONE: 414-327-4140 FAX: 414-327-0033

\*\*\* PRELIMINARY ESTIMATE \*\*\*

10/28/2021 02:56 PM

Owner

Owner: *Debra*  
DEBORAH BERRONES

Inspection

Inspection Date: 10/28/2021 02:56 PM

Inspection Type:

Appraiser Name: Glenn

Appraiser License # :

Repairer

Repairer: WEST ALLIS AUTO BODY  
Address: 8808 W NATIONAL AVE

Contact: Glenn  
Work/Day: (414)327-4140  
Home/Evening: (414)327-4143  
FAX: (414)327-0033

City State Zip: West Allis, WI 53227  
Email: waab6@aol.com

Target Complete Date/Time:

Days To Repair: 4

Vehicle

2002 Honda Civic EX 4 DR Sedan  
4cyl Gasoline 1.7 VTEC  
4 Speed Automatic

Lic Expire:  
Veh Insp# :  
Condition:  
Ext. Refinish: Two-Stage

VIN: Unreadable VIN  
Mileage Type: Actual  
Code: H0263E  
Int. Refinish: Two-Stage

Options

AM/FM CD Player	Air Conditioning	Air Dam
Alarm System	Anti-Lock Brakes	Bucket Seats
Center Console	Cruise Control	Dual Airbags
Intermittent Wipers	Keyless Entry System	Lighted Entry System
Power Brakes	Power Door Locks	Power Mirrors
Power Moonroof	Power Steering	Power Windows
Rear Window Defroster	Rem Trunk-L/Gate Release	Split Folding Rear Seat
Tachometer	Tilt Steering Wheel	Tinted Glass
Velour/Cloth Seats		

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
------	----	-------	----	-------------	--------------	-------	------	----	-------	---

**Front Body And Windshield**

1	EP	83	Panel,Hood	Replace PXN	\$417.00	1.6	SM
2	L	83	13 Panel,Hood	Refinish		5.2	RF
				2.8 Surface			
				1.0 Edge			
				0.6 Two-stage setup			
				0.8 Two-stage			
3	EP	88	Mldg,Hood Front	Replace PXN	\$66.00	INC	SM
4	EP	104	Fender,Front RT	Replace PXN	\$197.00	2.3	SM
5	L	104	Fender,Front RT	Refinish		2.6	RF
				1.7 Surface			
				0.5 Edge			
				0.4 Two-stage			

**Manual Entries**

6	EC	COVER CAR EXTERIOR	Replace Economy	\$5.00*			RF
7	EC	CORROSION PROTECTION	Replace Economy	\$5.00*			RF
7		Items					

**MC Message**

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

Other Parts		\$690.00	
Paint & Materials	7.8 Hours @ \$38.00	\$296.40	
Parts & Material Total			\$986.40
Tax on Parts & Material	@ 5.500%		\$54.25

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$58.00	3.9		3.9	\$226.20
Mech/Elec (ME)	\$65.00				
Frame (FR)	\$58.00				
Refinish (RF)	\$58.00	7.8		7.8	\$452.40

Labor Total		11.7 Hours	\$678.60
Tax on Labor	@ 5.500%		\$37.32
Gross Total			\$1,756.57
Net Total			\$1,756.57

Alternate Parts Y/03/03/03/00/00 Cumulative 03/03/03/00/00 Zip Code: 53227 Audatex Host  
Rate Name Default

Audatex Estimating 8.1.325 Update 3 ES 10/28/2021 02:57 PM REL 8.1.325 Update 3 DT 10/01/2021


State Disclosure: Not Selected

© 2021 Audatex North America, Inc.

1.8 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

**Op Codes**


* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = Replace OEM
NG = Replace NAGS	EC = Replace Economy	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = Replace PXN
EU = Replace Recycled	TE = Partial Replace Price	PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt	L = Refinish	PC = Replace PXN Reconditioned
UC = Replace Reconditioned	TT = Two-Tone	SB = Sublet Repair
N = Additional Labor	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	AA = Appearance Allowance	RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2021 Audatex North America, Inc.  
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.






7

Debra Semones  
6904 W. Euclid Ave  
Milwaukee, WI 53219

CITY OF MILWAUKEE  
2021 NOV -1 PM 2:55  
CITY CLERK'S OFFICE

City Clerk  
ATTN: CLAIMS  
200 E. Wells St. Room 205  
Milwaukee, WI 53202-3567

MILWAUKEE WI 530  
29 OCT 2021 PM 2



OFFICE OF CITY ATTORNEY  
02 NOV '21 PM 03:44

53202-357099

