

2024

On June 7th at approximately 9:00 AM  
I received a phone call from my  
Neighbor Mr. Dave that a tree fell  
on to my Van. I had gone  
outside to take a look at the  
damage that was done to my  
Van. I called the City office  
to assist me with help.  
There were City workers sent out  
to take pictures of my Van.  
I later had to call in to work  
for that day off.

My Van hasn't been towed  
since the incident due to  
my windshield having strips along  
the windshield sides being damaged  
in fear of my windshield coming  
out of place causing an accident,  
as well as harm.

My name is Kenneth L. Hall  
Phone # is 414-803-7979  
This incident occurred in front of  
my residence 1014 S. 26th St.  
Milwaukee, WI 53204

My Neighbor name is Mr. Dave  
414-630-7825  
Thank you, Ken H.

2024 OCT 1 AM 9:31  
CITY CLERK'S DESK  
MILWAUKEE

OFFICE OF CITY ATTORNEY  
01 OCT '24 PM 04:42













# Braeger's Lake Auto Body

Workfile ID: 774e3362  
PartsShare: 83MqGc

4100 S 27TH ST, MILWAUKEE, WI 53221

Phone: (414) 281-0454

FAX: (414) 921-9720

## Estimate

### RO Number:

Customer:	Insurance:	Adjuster:	Estimator:	Calvin Klinker
Hale, Kenneth		Phone:	Create Date:	7/17/2024
1016 S 26th St		Claim:		
Milwaukee, WI 53204		Loss Date:		
(414) 803-7979		Deductible:		

2012 NISS Quest LE 4D VAN 6-3.5L Gasoline Electronic Fuel Injection SILVER

VIN: JN8AE2KP5C9042308	Interior Color:	Mileage In: 60,000	Vehicle Out:
License: AEA8799	Exterior Color: SILVER	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		<b>FRONT BUMPER</b>						
2	E01	Remove/Install	R&I bumper cover-DROP-				0.5T	Body	
3	E01		<b>FRONT LAMPS</b>						
4	E01	Remove/Install	RT R&I headlamp assy				0.3T	Body	
5	E01		<b>HOOD</b>						
6	E01	Repair	Hood				2.0T	Body	2.8T
7	E01		Add for Clear Coat						1.1T
8	E01		BCR						(0.3)T
9	E01		<b>FENDER</b>						
10	E01	Repair	RT Fender w/16" wheels				1.5T	Body	2.6T
11	E01		Overlap Major Adj. Panel						(0.4)T
12	E01		Add for Clear Coat						0.4T
13	E01		BCR						(0.3)T
14	E01		<b>ROOF</b>						
15	E01	Remove/Replace	RT Drip molding	1	563.56T	OEM	0.9T	Body	
16	E01	Remove/Install	LT Drip molding				0.9T	Body	
17	E01	Repair	Roof panel w/o satellite radio w/roof rack				1.0T	Body	3.8T
18	E01		Overlap Major Adj. Panel						(0.4)T
19	E01		Add for Clear Coat						0.7T
20	E01	Remove/Install	RT Roof rack				0.4T	Body	
21	E01		BCR						(0.5)T
22	E01	Remove/Install	LT Roof rack				0.4T	Body	
23	E01	Remove/Install	R&I headliner				2.8T	Body	
24	E01		<b>PILLARS, ROCKER &amp; FLOOR</b>						
25	E01	Remove/Replace	RT Vent glass Nissan	1	395.75T	Glass	1.1T	Body	
26	E01		<b>FRONT DOOR</b>						

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

**Estimate**

**RO Number:**

2012 NISS Quest LE 4D VAN 6-3.5L Gasoline Electronic Fuel Injection SILVER

27	E01	Remove/Replace	RT Belt molding	1	276.98T	OEM	0.3T	Body	
28	E01	Repair	RT Door shell w/o S, SV				3.0T	Body	2.3T
29	E01		Overlap Major Adj. Panel						(0.4)T
30	E01		Add for Clear Coat						0.4T
31	E01		BCR						(0.3)T
32	E01	Remove/Install	LT R&I mirror				0.4T	Body	
33	E01	Remove/Install	RT Handle, outside				0.5T	Body	
34	E01	Remove/Install	RT R&I trim panel				0.6T	Body	
35	E01		<b>SIDE LOADING DOOR</b>						
36	E01	Repair	RT Door shell LE				1.0T	Body	2.3T
37	E01		Overlap Major Adj. Panel						(0.4)T
38	E01		Add for Clear Coat						0.4T
39	E01		BCR						(0.3)T
40	E01	Remove/Replace	RT Belt molding	1	295.84T	OEM	0.3T	Body	
41	E01	Remove/Install	RT Upper molding				0.3T	Body	
42	E01	Remove/Install	RT Handle, outside				0.5T	Body	
43	E01	Remove/Install	RT R&I trim panel				0.5T	Body	
44	E01	Sublet	Hazardous Waste Disposal	1	5.00T	Other			
45	E01	Remove/Replace	Car Cover/ Mask for Overspray	1	5.00T	Other			
46	E01	Repair	De-nib & Polish				0.3T	Body	
47	E01	Repair	Mask For Prime/Block				0.2T	Body	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					1,532.13
Labor, Body			75.00	19.7	1,477.50
Labor, Refinish			75.00	13.5	1,012.50
Material, Paint			55.00	13.5	742.50
Miscellaneous					10.00
<b>Subtotal</b>					<b>4,774.63</b>
Sales Tax					377.20
<b>Grand Total</b>					<b>5,151.83</b>
<b>Net Total</b>					<b>5,151.83</b>

Estimate Version	Total \$
Original	5,151.83

Insurance Total \$:	0.00
Received from Insurance \$:	0.00
Balance due from Insurance \$:	0.00
Customer Total \$:	5,151.83
Received from Customer \$:	0.00
Balance due from Customer \$:	5,151.83

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural