




Existing window deterioration



View of exterior existing window



View of exterior existing window

## MPS - Existing Window Condition

3360 N Sherman Boulevard Milwaukee, Wisconsin



Interior view broken window



Existing entry doorway




North elevation exterior view

# MPS - Existing Window Condition

3360 N Sherman Boulevard Milwaukee, Wisconsin



Interior view glass block window



Interior view existing window



Interior view gym windows

## MPS - Existing Window Condition

3360 N Sherman Boulevard Milwaukee, Wisconsin