



2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo of Primary Facade and existing deck





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo of existing deck and east facing stairs





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo showing east steps, deteriorating concrete





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo showing chipped stone cap at top of steps





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo facing front door showing existing concrete cracking





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo looking toward north showing concrete cracking





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo looking east showing mortar failures





2239 N Terrace Ave - Deck Replacement - COA Application Nov 7, 2023

Photo of north stair wing wall showing cracking brick













South Wall



East Wall



