

CONCOURS AUTO WORKS, LTD.  
 9508 WEST NATIONAL AVENUE  
 WEST ALLIS, WI 53227  
 OFFICE: (414) 321-4200

CD LOG NO 6623-1 DATE 01/08/10

SHOP: CONCOURS AUTO WORKS, LTD. INSP DATE: 01/08/10  
 ADDRESS: 9508 WEST NATIONAL AVENUE PHONE 1: (414) 321-4200  
 CITY STATE: WEST ALLIS, WI FAX: (414) 321-4106  
 ZIP: 53227-

OWNER: HREN, JOESPH CELL PHONE: (414) 202-5613  
 ADDRESS: 13745 W GRAHAM ST  
 CITY STATE: NEW BERLIN, WI  
 ZIP: 53151

POINT OF IMPACT: 0

LIC#: STATE: VIN: 2GCEK19T0X1139126  
 BODY COLOR: MILEAGE: 175,000  
 CONDITION: EXCELLENT ACCTNG CTL#:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

1999 CHEVROLET SILVERADO K1500 LS 2DOOR EXT CAB 8CYL GASOLINE 5.3  
 CODE: U8033D/A OPTNS T/24XDJPQGTCTR

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
4-WHEEL DRIVE	POWER DOOR LOCKS
REMOTE KEYLESS ENTRY SYSTEM	POWER WINDOWS
ELEC REMOTE CONTROL MIRRORS	REAR BUMPER
AIR CONDITIONING	CRUISE CONTROL
OVERHEAD CONSOLE	

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
E	0024		BUMPER, FRONT	12336026 GM PART	430.33			2.6	1
E	0152		DEFL, FRONT BUMPER	15199825 GM PART	106.22				INC 1
I	0176		PNL, CAB SIDE OUTER	LT REPAIR					5.0*1
L	0176	13	PNL, CAB SIDE OUTER	LT REFINISH					3.6 4
				2.5 SURFACE					
				0.6 TWO STAGE SETUP					

1999 CHEVROLET SILVERADO K1500 LS 2DOOR EXT CAB  
CD LOG ,NO 6623-1

3. I DO NOT WANT AN ESTIMATE.

MOTOR VEHICLE PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE  
ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF  
AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN  
53708-8911.

**ABRA NEW BERLIN**  
Federal ID #:411653085  
14750 W. National Avenue  
New Berlin, WI 53151  
(262)649-1210 Fax: (262)649-4155

**PRELIMINARY ESTIMATE**

Written By: Craig Eickermann  
Adjuster:

<b>Insured:</b> JOSEPH HREN	<b>Claim #</b>
<b>Owner:</b> JOSEPH HREN	<b>Policy #</b>
<b>Address:</b> 13745 W GRAHAM ST	<b>Deductible:</b>
NEW BERLIN, WI 53151	<b>Date of Loss:</b>
<b>Cellular:</b> (414)202-5613	<b>Type of Loss:</b>
	<b>Point of Impact:</b> 6. Rear
<b>Inspect</b> ABRA NEW BERLIN	<b>Business:</b> (262)649-1210
<b>Location:</b> 14750 W. National Avenue	
New Berlin, WI 53151	

**Insurance  
Company:**

Days to Repair

1999 CHEV K1500 4X4 SILVERADO LS EXT 8-5.3L-FI 3D SHORT BLUE Int:GREY  
VIN: 2GCEK19T0X1139126 Lic: EN7046 WI Prod Date: 11/1998 Odometer: 179964

Air Conditioning	Tilt Wheel	Cruise Control
Intermittent Wipers	Keyless Entry	Alarm
Message Center	Tinted Glass	Body Side Moldings
Dual Mirrors	Overhead Console	Clear Coat Paint
Two Tone Paint	Metallic Paint	Power Steering
Power Brakes	Power Windows	Power Locks
Power Mirrors	AM Radio	FM Radio
Stereo	CD Player	Anti-Lock Brakes (4)
Driver Air Bag	Passenger Air Bag	4 Wheel Disc Brakes
Leather Seats	Recline/Lounge Seats	Rear Step Bumper
Automatic Transmission	4 Wheel Drive	Overdrive
Styled Steel Wheels		

NO.	OP.	DESCRIPTION	QTY	EXT.	PRICE	LABOR	PAINT
1		FRONT BUMPER					
2		O/H front bumper				1.9	
3**	Repl	A/M Bumper chrome	1	337.00		Incl.	
4**	Repl	A/M CAPA Air deflector 4WD	1	74.00		Incl.	
5		REAR BUMPER					
6		O/H rear bumper				1.8	
7**	Repl	A/M Bumper chrome production	1	263.00		Incl.	
8	R&I	RT Step pad outer				Incl.	
9	R&I	LT Step pad outer				Incl.	
10	R&I	Step pad center				Incl.	
11	R&I	Trailer hitch				1.0	

PRELIMINARY ESTIMATE

1999 CHEV K1500 4X4 SILVERADO LS EXT 8-5.3L-FI 3D SHORT BLUE Int:GREY

NO.	OP.	DESCRIPTION	QTY	EXT. PRICE	LABOR	PAINT
12		BACK GLASS				
13	R&I	Back glass tinted non heated			1.5	
14		PICK UP BOX				
15*	Rpr	RT Side panel			<u>10.0</u>	3.3
16		Add for Clear Coat				1.3
17		Add for Two Tone				1.3
18	R&I	R&I tailgate assy			0.3	
19	Repl	RT Decal "4X4"	1	14.00	0.3	
20#	R&I	TONUE COVER			1.0	
21#	Refn	TONUE COVER				1.5
22#	Repl	`Urethane Kit	1	25.00		
23		CAB				
24	Repl	RT Nameplate "LS"	1	13.98	0.2	
N 25*	Rpr	Cab			<u>4.0</u>	<u>1.5</u>
26		Overlap Major Non-Adj. Panel				-0.2
27		Add for Clear Coat				0.3
28*		Add for Two Tone				<u>0.0</u>
29#		`Hazardous Waste	1	5.00		
30#	Repl	`Car Cover	1	5.00		
Subtotals ==>				736.98	22.0	9.0

Line 25 : PARTIAL PAINT AND PARTIAL CLEAR COAT, NO TWO TONE

Estimate Notes:  
NO DISASSEMBLY AT TIME OF ESTIMATE

Prior Damage Notes:  
SCUFFS RT AND LFT SIDE

Parts		736.98
Body Labor	22.0 hrs @ \$ 56.00/hr	1232.00
Paint Labor	9.0 hrs @ \$ 56.00/hr	504.00
Paint Supplies	9.0 hrs @ \$ 35.00/hr	315.00
SUBTOTAL		\$ 2787.98
Sales Tax	\$ 2787.98 @ 5.1000%	142.19
GRAND TOTAL		\$ 2930.17

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

**PRELIMINARY ESTIMATE**

1999 CHEV K1500 4X4 SILVERADO LS EXT 8-5.3L-FI 3D SHORT BLUE Int:GREY

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR1GH99, CCC Data Date 12/16/2009, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries. Some 2010 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The Pathways estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

CCC Pathways - A product of CCC Information Services Inc.

01/11/2010 at 02:12 PM  
36747

Job Number:

**PRELIMINARY ESTIMATE**

1999 CHEV K1500 4X4 SILVERADO LS EXT 8-5.3L-FI 3D SHORT BLUE Int:GREY

**ALTERNATE PARTS SUPPLIERS**

3 A/M Bumper chrome	Part No.	GM1002376	Price \$337.00
4 A/M CAPA Air deflector 4WD	Part No.	GM1092167PP	Price \$74.00
7 A/M Bumper chrome productio	Part No.	GM1102411PP	Price \$263.00

Keystone - Complete	(800)924-8230
9532 W. CARMEN AVE.	(414)463-1019
MILWAUKEE, WI 53225	

Keystone - Complete	(800)352-7252
5969 HAASE RD. SUITE B	(608)249-4775
DEFOREST, WI 53532	

HOLZ MOTORS, INC. BODY SHOP

5961 S.108TH PLACE

HALES CORNERS, WI 53130

DIRECT LINE: (414) 529-7848 & (414) 425-2400 FAX: (414) 529-7533

FEDERAL I.D. #39-0792093

CD LOG NO 11519-1 DATE 01/11/10

SHOP:
CITY STATE: , WI

INSP DATE: 01/11/10
CONTACT: DAVE LUEDKE

OWNER: HREN, JOSEPH
ADDRESS: 13745 GRAHAM ST
CITY STATE: NEW BERLIN, WI
ZIP: 53151

POINT OF IMPACT: 34

DAYS TO REPAIR: 5

LIC#:
BODY COLOR: BLUE/SILVER
CONDITION:

STATE:

VIN: 2GCEK19T0X1139126
MILEAGE: 175,177
ACCTNG CTL#:

DRIVEABLE: YES

VEH. INSP#:

\*=USER-ENTERED VALUE
EC=REPLACE ECONOMY
UM=REMAN/REBUILT PRT
OE=REPLACE PXN OE SRPLS
TE=PARTL REPL PRICE
I=REPAIR
TT=TWO-TONE
N=ADDITIONAL LABOR
AA=APPEAR ALLOWANCE

E=REPLACE OEM
UE=REPLACE OE SURPLUS
EU=REPLACE SALVAGE
PC=PXN RECONDITIONED
ET=PARTL REPL LABOR
L=REFINISH
CG=CHIPGUARD
RI=R&I ASSEMBLY
RP=RELATED PRIOR

NG=REPLACE NAGS
UC=RECONDITIONED PRT
EP=REPLACE PXN
PM=PXN REMAN/REBUILT
IT=PARTIAL REPAIR
BR=BLEND REFINISH
SB=SUBLET
P=CHECK
UP=UNRELATED PRIOR

\*\*\*\*\*
PRELIMINARY ESTIMATE
\*\*\*\*\*

1999 CHEVROLET SILVERADO K1500 STD 2DOOR EXT CAB 8CYL GASOLINE 5.3
CODE: U8033D/A OPTNS T/24X

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
4-WHEEL DRIVE

TWO-STAGE - INTERIOR SURFACES

Table with 7 columns: OP, GDE, MC, DESCRIPTION, MFG. PART NO., PRICE, AJ% B%, HOURS R. Rows include bumper, brace, and pnl repairs.

L 0177	13	PNL,CAB SIDE OUTER	RT	REFINISH			2.0	4
E 0141		NAMEPLATE,CAB REAR	RT	15036136 GM PART	11.36		0.2	1
E 0369		BACK GLASS,TINTED		15198871 GM PART	192.19		2.0	1
EC0370		SEALANT KIT,BACK GLASS		ECONOMY PART	18.50*		INC	1
I 1639		PANEL,BEDSIDE OUTER	RT	REPAIR			8.0*	1
L 1639		PANEL,BEDSIDE OUTER	RT	REFINISH			2.9	4
TT1639	15	PANEL,BEDSIDE OUTER	RT	TWO TONE			1.1	4
E 0485		DECAL,BEDSIDE PANEL	RT	15779675 GM PART	14.00		0.3	1
I 0479		SHELL,TAILGATE		REPAIR			2.0*	1
L 0479		SHELL,TAILGATE		REFINISH			2.8	4
E 0491		N/PLATE,TAILGATE		15126056 GM PART	47.44		0.2	1
E 0492		N/PLATE,TAILGATE		15114063 GM PART	49.39		0.2	1
RI0435		BEZEL,TAILGATE HANDLE		R&I ASSEMBLY			0.2	1
RI1527	01	COVER,TONNEAU		R&I ASSEMBLY			1.0*	1
RI0381		COMPL BED ASSY R & I		R&I ASSEMBLY			2.5	1
E 0565		BUMPER,REAR STEP		12473000 GM PART	309.54		2.6	1
E 0579		BRKT,REAR BUMPER MT	RT	15705674 GM PART	36.61		INC	1
E 0574		BRACE,REAR BUMPER	RT	15705670 GM PART	32.36		INC	1
E 0571		PAD,REAR BUMPER STEP		12335696 GM PART	52.42		INC	1
E 1097		PAD,REAR BUMPER STE	LT	15738017 GM PART	74.00		INC	1
E 1098		PAD,REAR BUMPER STE	RT	15738018 GM PART	71.15		INC	1
E 0586		REINF,TRAILER HITCH		15154375 GM PART	225.14		INC	1
ECM14		CORROSION PROTECTION		ECONOMY PART	5.00*		0.5*	1*
ECM17		COVER CAR EXTERIOR		ECONOMY PART	6.00*			1*

28 ITEMS

MC MESSAGE(S)

- 01 CALL DEALER FOR EXACT PART NUMBER / PRICE
- 02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO
- 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE
- 15 INCLUDES 0.4 HOURS FIRST PANEL TWO-TONE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS					1,609.90
OTHER PARTS					29.50
PAINT MATERIAL					281.60
PARTS & MATERIAL TOTAL					1,921.00
TAX ON PARTS & MATERIAL @				5.600%	107.58
LABOR	RATE	REPLACE HRS	REPAIR HRS		
1-SHEET METAL	52.00	12.3	13.5		1,341.60
2-MECH/ELEC	78.00				
3-FRAME	55.00				
4-REFINISH	52.00	8.8			457.60
5-PAINT MATERIAL	32.00				
LABOR TOTAL					1,799.20
TAX ON LABOR		@		5.600%	100.76
SUBLET REPAIRS					
TOWING					
STORAGE					
GROSS TOTAL					3,928.54



1999 CHEVROLET SILVERADO K1500 STD 2DOOR EXT CAB  
CD LOG NO 11519-1

NET TOTAL

3,928.54

SHOPLINK U3508 ES CD LOG 11519-1 DATE 01/11/10 01:51:42PM R6.37 CD 12/09

PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53130

HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

1.8 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

-----

HEISER CHEVROLET  
 COLLISION REPAIR AND REFINISHING  
 10200 W. ARTHUR AVENUE  
 WEST ALLIS, WI 53227  
 OFFICE: 414-327-2300 FAX: 414-546-7877

\*\*\* PRELIMINARY ESTIMATE \*\*\*

01/08/2010 04:44 PM

Owner

Owner: JOSEPH HREN  
 Address: 13745 W GRAHAM ST  
 City State Zip: New Berlin, WI 53151

Work/Day: (414)202-5613  
 FAX:

Inspection

Inspection Date: 01/08/2010 04:44 PM  
 Primary Impact: Front

Inspection Type:  
 Secondary Impact: Right Rear Corner

Appraiser Name: PETE COONEY

Appraiser License #:

Repairer

Repairer: HEISER CHEVROLET BODY  
 SHOP  
 Address: 10200 WEST ARTHUR AVENUE  
 TAX ID# 39-1655466  
 City State Zip: WEST ALLIS, WI 53227  
 Email: pcooney@heiser.com

Contact: PETE COONEY  
 Work/Day: (414)328-2453  
 Home/Evening: (414)327-2300  
 FAX: (414)546-7877

Vehicle

1999 Chevrolet Silverado K1500 LS 2 DR Ext Cab Short Bed  
 8cyl Gasoline 5.3  
 4 Speed Automatic

Lic.Plate: EN7486  
 Lic Expire:  
 Prod Date: 11/1998  
 Veh Insp# :  
 Condition: Good  
 Ext. Color: BLUE/GOLD  
 Ext. Refinish: Two-Stage

Lic State: WI  
 VIN: 2GCEK19T0X1139126  
 Mileage: 175,000  
 Mileage Type: Actual  
 Code: U8033D  
 Int. Color:  
 Int. Refinish: Two-Stage

Options

4-Wheel Drive	AM/FM CD Player	Air Conditioning
Alarm System	Anti-lock Brakes	Chrome Steel Wheels
Chrome Step Bumper	Cruise Control	Dual Airbags
Hinged Third Door	Intermittent Wipers	Keyless Entry System
Leather Steering Wheel	Lighted Entry System	Overhead Console
Power Brakes	Power Door Locks	Power Mirrors
Power Steering	Power Windows	Tachometer
Tilt Steering Wheel	Tutone Paint	Velour/Cloth Seats

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
1	E	24	49	Bumper,Front	12336026 GM Part	\$430.33		INC	SM
2	N	8		Front Bumper Overhaul	Additional Labor			2.6	SM
3	E	15	49	Cvr,Front Bumper Up	15050703 GM Part	\$119.59		INC	SM
4	E	152	49	Defl,Front Bumper	15199825 GM Part	\$108.22		INC	SM
5	E	1245		Retainer,Front Bumper	MULTI-PART GM Part	\$61.23		INC	SM

6	E	98		Hook,Front Bumper Tow RT	15709128 GM Part	\$25.85		0.2	SM
7	I	177		Pnl,Cab Side Outer RT	Repair			10.0*	SM
8	L	177	13	Pnl,Cab Side Outer RT	Refinish			2.0	RF
9	RI	636		Mldg,Cab Side Lower RT	R & I Assembly			0.2	SM
10	E	139		Nameplate,Cab Rear RT	15036135 GM Part	\$13.98		0.2	SM
11	BR	288		Door Shell,Rear RT	Blend Refinish			1.2	RF
12	RI	1410		Mldg,Rear Door Lower RT	R & I Assembly			0.2	SM
13	SB	501		Glass,Rear Vent T RT	Sublet Repair	\$100.00*	+25.00		SM
14	RI	349		Mldg,Rear Drip RT	R & I Assembly			0.2	SM
15	E	369		Back Glass,Tinted	15198871 GM Part	\$192.19		2.0	SM
16	I	498		Panel,Bedside RT	Repair			16.0*	SM
17	L	498		Panel,Bedside RT	Refinish			2.9	RF
18	N	975		Bed Assembly,Set Back	Additional Labor			2.0	SM
19	RI	1555		Mldg,Bedside Pnl Lwr L/F	R & I Assembly			0.3	SM
20	E	485		Decal,Bedside Panel RT	15779675 GM Part	\$14.00		0.3	SM
21	I	479		Shell,Tailgate	Repair			2.0*	SM
22	L	479		Shell,Tailgate	Refinish			2.8	RF
23	E	491		N/Plate,Tailgate	15126056 GM Part	\$47.44		0.2	SM
24	E	492		N/Plate,Tailgate	15114063 GM Part	\$49.39		0.2	SM
25	RI	427		Handle,Tailgate Outer	R & I Assembly			0.2	SM
26	RI	507		Protector,Tailgate	R & I Assembly			0.2	SM
27	I	1527		Cover,Tonneau	Repair			6.0*	SM
28	E	453	#	Accessory RR Bmpr Kit # = 01, 49	12496085 GM Part	\$533.79		INC	SM
29	N	9		Rear Bumper Overhaul	Additional Labor			2.6	SM
30	E	571	49	Pad,Rear Bumper Step	12335696 GM Part	\$52.42		INC	SM
31	E	1098	49	Pad,Rear Bumper Step RT	15738018 GM Part	\$71.15		INC	SM
32	N			Corrosion Protection	Additional Labor			0.3*	RF*
33	N			Cover Car Exterior	Additional Labor	\$5.00*			SM
34	N			Hazardous Waste Removal	Additional Labor	\$5.00*			SM
35	N			Set-Up And Measure	Additional Labor			2.0*	FR*
36	N			ROUGH PULL	Additional Labor			2.0*	FR*
37	L			Cover,Tonneau	Refinish			4.0*	RF*
38	EC			URETHANE KIT	Replace Economy	\$35.00*			SM*
39	L			feather, prime, and block	Refinish			1.0*	RF*

39 Items

**MC Message**

- 01 CALL DEALER FOR EXACT PART # / PRICE
- 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE
- 49 UNPRINTED ALTERNATE PARTS COMPARE

**Estimate Total & Entries**

Gross Parts	\$1,717.58	
Other Parts	\$45.00	
Paint Materials	\$482.80	
<b>Parts &amp; Material Total</b>		\$2,245.38
Tax on Parts & Material	@ 5.600%	\$125.74

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$54.00	4.4	41.2	45.6	\$2,462.40
Mech/Elec (ME)	\$98.00				
Frame (FR)	\$54.00		4.0	4.0	\$216.00
Refinish (RF)	\$54.00	13.9	0.3	14.2	\$766.80
Paint Materials	\$34.00				
<b>Labor Total</b>				63.8 Hours	\$3,445.20
Tax on Labor			@ 5.600%		\$192.93
Sublet Repairs					\$125.00
<b>Gross Total</b>					\$6,134.25
<b>Net Total</b>					\$6,134.25

Alternate Parts Y/06/00/00/06/00 CUM 06/00/00/06/00 Zip Code: 53227 Audatex Host

Audatex Estimating 6.0.217 ES 01/08/2010 05:01 PM REL 6.0.217 DT 12/01/2009  
Copyright (C) 2009 Audatex North America, Inc.

2.2 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

**Op Codes**

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = Replace Recycled
TE = Partial Replace Price	PM = Replace PXN Reman/Rebld	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TT = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2009 Audatex North America, Inc.  
Audatex Estimating is a trademark of Audatex North America, Inc.