
WEST SILVER SPRING DRIVE




WEST SHERIDAN AVENUE






W SILVER SPRING DR



24TH STREET




W SILVER SPRING DR



24TH STREET



W SILVER SPRING DR



24TH STREET





Photo 1 - Building Engineer - 1929-37 locked storage area to be adaptively reused



Photo 2 - Historic Main Entry - 1929-37 Building to be adaptively reused




Photo 3 - Terrazzo stairs and flooring - 1929-37 Building





Photo 4 - Historic millwork and cabinetry - 1929-37 building - to be sanded and restained





Photo 5 - Historic millwork and cabinetry - 1929-37 building - to be sanded and restained



Photo 6 - Historic millwork and storage - 1929-37 building - to be sanded and restained



Photo 7 - Historic millwork and storage - 1929-37 building - to be sanded and restained





Photo 8 - Windows looking into Gym - 1943 Gym Addition





Photo 9 - Transom windows above door - 1943 Gym Addition





Photo 10 - Historic millwork and storage - 1929-37 building - to be sanded and restained