

City of Milwaukee  
Department of Public Works — Bureau of Forestry  
DEAD/HAZARDOUS TREE INVESTIGATION REPORT

TO: (Owner, Agent)

Shemika N. Jones

ADDRESS:

4515 W. Capitol Dr.

Milwaukee WI 53216 0000

In accordance with Sections 116-53 & 116-66 to 116-68 of the Milwaukee Code of Ordinances,

the property at: 4515 W. Capitol  
[address of tree location(s)]

having Tax Key No. 2670330100, was inspected and the following was noted:

1. Dead tree(s) — must be entirely removed to ground.

2. Hazardous tree(s):

A. Must be entirely removed to ground due to: large trunk wound with decay, dead branches, tree cavities in top of tree and retrenchment

B. Must remove dead/hazardous branches from tree(s) in tree.

C. Must repair tree defect by bolting & cabling

[  Suggest that tree(s) with tag # \_\_\_\_\_ be entirely removed to ground for the following reason(s):  
\_\_\_\_\_ ]

Tree species: Silver Maple

Diameter(s): 44.0"

Tree Tag Number(s): # 123

Location(s) on property: lot west of address



MAP

W. Capitol Drive

4515

HAZARDOUS TREE

Alley

Section # 267 District # \_\_\_\_\_

Survey Date: 05-01-2024

Survey Crew: C.S.

Notification Date: \_\_\_\_\_

Compliance Check: \_\_\_\_\_

Completion Date: \_\_\_\_\_

Inspected By: \_\_\_\_\_

Contract No.: \_\_\_\_\_

File No.: PWCF-24-01165