is in Response to the derial letter I received for a Claim against - City tow lot for damage si to my Vehicle in September 2004. Quin # 04-5-406. D'in appe this decision because the to my vehicle was not procesusti The card can has been deened andrivable, which was not the case prior to being towe. It was being morel from ODD to even every right to arrow Creating were tielets while I was in the process I getting the existing tielets + the enimor test passed. There was some significant damage on the hood 4 to the left drant and 86 the

Vehicle, but the grant gill 4 license plato bracket was in place @ time of towing. This was not when vehicle was pieled up from lot. I am strongly hoping that you reconsider It your origin decision because the city tow lot did danage my vehicle to the point of not being able to drive it. The estimates were received from local repair shops because it is extremely Dangerous to drive which too far. I min the process De paying the citation, which got it tower Tout I should not have to pay do danage to car that I'm not responded for Sjeet want my cardired so I can pass commine + continually be a law aloiding citizen + follow the rules to the city is right parlings

laws. Again I would appreciat
your reconsideration in this
matter. Even if it means conprisi
repairs and till take care of
the grill & bracket, please know
the grill & bracket, please know my car is not drivable & there
was not an issue with that
before.
Markeyou
Shaure Bond

11/1/04

Dear City Clerk,

this letter is to inform you of damage that was done to my vehicle on or around September 28, 2004 lay the Milwaulee City tow lot.

Damage was done to the front end of the rehicle. The dront plats of bracket was torned of the front opill was broken in pieces, Bloo upon driving from tow lot to home notice that can was shifting to one eight because upon inspection, found that a tie rod was broken of car is undrivable. Please find attacked two estimates with approximate estimates to rectify damage.

Bloo enclared with front end repair should be a front wheel alighned which will be @ Current nearlest price @ Milas. to fix danage \$900.00 please. Attached also is original Daine Gile Septenber 28 a tow lot. Tow # is 120142 Verielo is describe as a 1991 Chey lumina, tan in color w/ black carries top. Noticebb previous dancge to dratlights flett side) + hood - no fault of toward. I appreciate Your Consideration in expediting my request as soon as possible Manlyay Shows Bond

9657 w. Beatrice St. #4 (Hone #) 414-355-8098, (Cell #)414-687-5147

City of Milwaukee Tow Lot

COMPLAINT AND INVESTIGATION FORM

-CITY USE ONLY. TOW# 201426	TOW LOT LOCATION	DATE: 9-28-04 ID# 08
NAME: Shawne Bond ADDRESS: 9657 W. Beatrice	CITY OF MILW TOW LOT	DATE ISSUED: 9/28/04/ 1ST. CITIZEN COMPLAINT X
PHONE NO: 4/4-355-8098	VEHICLE TOWING	2ND. CITIZEN COMPLAINT

CIRCLE THOSE THAT APPLIES

COMPLAINT * VEHICLE MISSING	ITEMS * DAMAGES TO VEHICLE
(FOR MISSING ITEMS OR DAMAGES TO VEHICLE, A	ALSO COMPLETE THE OTHER SIDE OF THIS PAGE)
CITIZEN'S	STATEMENT
Tironse Plato Off & C. Orole in Dieces	asing around plato
	<u> </u>
haune Bow	9/20/01/
SIGNATURE	DATE
	N RESULTS
TO FILE A CLAIM FOR *DAMAGE TO OR THEFT FROM *	
TOUR VEHICLE	2 %
WRITE A DETAILED LETTER AND SEND TO: CITY CLERK'S OFFICE	7. 8
200 EAST WELLS STREET	- in the second
CITY HALL, ROOM 205 MILWAUKEE, WI 53202	3 2 53
(414) 286 - 2221	γ
#1201426	DATE

LIST ITEMS I	MISSING	FROM	VEHICLE		
		· · · · · · · · · · · · · · · · · · ·			

	% \$	<u> </u>			
	F . 1				<u></u>
	y stage			·	
LIST DAMAGES TO VEHICL		CIRCLE	AREAS OF	DAMA	GES
USING THE DIA	GRAM A	AT THE	BOTTOM		
that license plate	<u>o - Or</u>	O be	hine y	electo?	-
Carina_around Pla	20- F	Broke	in pi	oces s	<u>+ </u>
plato detatached o	rom	car	,		
			3	3	
NOTES:	<u> </u>	PASSENGER SIDE [FIIGHT]		•	
					R
· m lobins) 0 (")	13 .	14	16	E .	E A
rul balan N					R
Draw O'		ORIVER SIDE	*	*	
Casing around	3		******* *	7	*
Plato broke					
Casine around Plato broke in pieces			INFORMATI		B.
		w */* #	е		
		Date			



MIDAS MUFFLER

9005 W. BROWN DEER RD. MILWAUKEE, WI 53224 (414) 355-6234

ESTIMATE

#041029004 10/29/2004, 12:54 pm

MIKE BOND 9657 W BEATRICE MILWAUKEE, WI 53224 HOME: 414-355-8098

1991 CHEVROLET LUMINA

638 BRR (WI)

ODOM IN/OUT: 132092 / 132092

3.1L V6 Cyl.

Sales Person: 100:MARK W

140:LIONEL

Qty	Item Number	Description	R/S	ST	Each	Misc	Extended
1	AZES2912R	TIE ROD END-LINK	S	RO-	40.99		40.99
0.5	LABOR	AZES2912R	S	R	68.50		34.25
1	AZES3103	TIE ROD END-LINK	s	RO-	59.95		59.95
1	LABOR	AZES3103	S	R	68.50		68.50

Parts 100.94 Labor 102.75 State Sales Tax 10.19 **County Sales Tax** 1.23 **Grand Total** 215.11

WORK AUTHORIZATION

This Estimate of Repairs is based upon our inspection at this time and does not cover additional parts and/or labor that may be required after the work has been started. After the work has been started, worn or damaged parts, which are not evident on first inspection, may be discovered. This Estimate of Repairs cannot cover such contingencies in cases which additional work is deemed necessary; customer authorization will be secured prior to commencement of that additional work.

I hereby authorize the repairs shown on this estimate to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. We are not responsible for unavailability of parts (or) delays in parts shipments beyond our control.

Х								
I hereby unders	stand that payment	is due when the	e vehicle is picke	ed up or delive	red, and that if	any payment is :	not made when due t	the
							of collection, incl	
	orney fees, in the					• -		
X	*****							
				RTS WILL BE RET	URNED TO YOU IF	YOU REQUEST THEM	WHEN THE REPAIRS A	RE
ORDERED. (YOU M	MAY INSPECT THOSE	PARTS, WHICH MUS	ST BE RETURNED TO	THE MANUFACTUR	er or pay any ap	PLICABLE CORE VAI	LUE).	
CHECK ONE: ()	Please return r	eplaced parts.	() I do not want	replace parts.				
X								
* ADDITIONAL AU	THORIZED COSTS *							
DESCRIPTION	AMOUNT	PHONE	writing	DATE	TIME			
Х								
PRICE OUOTATION	- THIS PRICE FOR	THE AUTHORIZED	REPAIRS WILL NOT	BE EXCEEDED IF	THE MOTOR VEHIC	LE IS DELIVERED T	O THE SHOP WITHIN	RIVE

Motor vehicle repair practices are regulated by chapter ATCP 132, Wis. Adm. Code, administered by the Bureau of Consumer Protection, Wisconsin Dept. of Agriculture, Trade and Consumer Protection, P.O. Box 8911, Madison, Wisconsin 53708-8911.

CRYSTAL AUTO BODY, INC. 8722 N. GRANVILLE RD MILWAUKEE, WI. 53224

PHONE: 355-6647 BILL OR BOB FAX: 355-2266 COMPLETE COLLISION REPAIR EXPERT REFINISHING

CD LOG NO 4718-1 DATE 10/29/04

SHOP: CRYSTAL AUTO BODY INC. ADDRESS: 8722 NORTH GRANVILLE RD.

CITY STATE: MILWAUKEE, WI

ZIP: 53224-

INSP DATE:

CONTACT:

10/29/04 BILL ZOESCH

HOME PHONE: (414)355-8098

PHONE 1: PHONE 2:

(414) 355-6647 (414) 355-2269

FAX:

(414)355-2266

OWNER: BOND, MICHEAL ADDRESS: 9657 W. BEATRICE ST

CITY STATE: MIL, WI ZIP: 53224-

POINT OF IMPACT: 3

LIC#:

STATE:

VIN: 2G1WL54T6M9211159

BODY COLOR: WHITE

CONDITION:

MILEAGE:

ACCTNG CTL#:

*=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS
EC=REPLACE ECONOMY UC=RECONDITIONED PRT UM=REMAN/REBUILT PRT
EU=REPLACE SALVAGE EP=REPLACE PXN PC=PXN RECONDITIONED

PM=PXN REMAN/REBUILT IT=PARTIAL REPAIR

BR=BLEND REFINISH

SB=SUBLET

P=CHECK

UP=UNRELATED PRIOR

TE=PARTL REPL PRICE

I=REPAIR

TT=TWO-TONE N=ADDITIONAL LABOR

AA=APPEAR ALLOWANCE

ET=PARTL REPL LABOR L=REFINISH

CG=CHIPGUARD

RI=R&I ASSEMBLY RP=RELATED PRIOR

THANK YOU FOR STOPPING AT CRYSTAL AUTO BODY. EXPECT QUALITY!!!!

SUBJECT TO TEARDOWN. POSSIBLE SUSPENSION DAMAGE

WE WORK WITH ALL INSURANCE COMPANIES.

ALL NEW O.E.M. PARTS.

POSSIBLE UNDERBODY DAMAGE

1991 CHEVROLET LUMINA STD 4DOOR SEDAN 6CYL GASOLINE 3.1

CODE: U2423A/B OPTNS F/240

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

AUTOMATIC TRANS

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ% B%	HOURS	R
				which which which which which which which was been severe				***
	0025		BRKT, FRONT LIC PLATE	10079077 GM PART	21.15		0.2	
E	0028	01	GRILLE ASSEMBLY	10082601 GM PART	64.40		0.7	
L	0028	13	GRILLE ASSEMBLY	REFINISH			1.2	4

1991 CHEVROLET LUMINA STD 4DOOR SEDAN CD LOG NO 4718-1

E	0031	EMBLEM, GRILLE	10256811 GM PART	17.97	0.2 1
I	0083	PANEL, HOOD	REPAIR		1.5*1
L	0083	PANEL, HOOD	REFINISH	•	3.4 4

6 ITEMS

MC MESSAGE(S)

01 CALL DEALER FOR EXACT PART NUMBER / PRICE

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS PAINT MATERIAL PARTS & MATERIAL TOTAL TAX ON PARTS & MATERIAL	<u>e</u>		5.600%	103.52 119.60 223.12 12.49
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	46.00	1.1	1.5	119.60
2-MECH/ELEC	65.00			
3-FRAME	48.00			211 60
4-REFINISH	46.00	4.6		211.60
5-PAINT MATERIAL	26.00			331.20
LABOR TOTAL TAX ON LABOR		@	5.600%	18.55
TAX ON LABOR SUBLET REPAIRS		e	3,0008	10.00
TOWING				
STORAGE				
GROSS TOTAL				585.36
NET TOTAL				585.36

ADP SHOPLINK U6540 ES CD LOG 4718-1 DATE 10/29/04 12:03:14AM R6.35 CD 10/04 HOST LOG

(C) 1998 - 2004 ADP CLAIMS SOLUTIONS GROUP, INC.

1.3 HRS WERE ADDED TO THIS EST. BASED ON ADP TWO-STAGE REFINISH FORMULA.