

RECEIVED

MAY 12 2017

OFFICE OF
CITY ATTORNEY

I Walter R Ransay

Requesting a hearing within 21 days

of the postmarked date

of this letter to the

C.I. File No. 1030-2017-929

P.S. Grant - Langley

City Attorney.

MAY 8 - 2017

Walter R Ransay

CITY OF MEMPHIS
2017 MAY -9 PM 1:50
CITY CLERK'S OFFICE

RECEIVED


MAY 12 2017

OFFICE OF
CITY ATTORNEY

Walter Romay
2795 N State St
Milwaukee WI 53223
App 222
City, Clerk

200 East Wells St Room 205

App 422 WI 53202



MILWAUKEE WI 530

06 MAY 2017 PM 6 L

CITY OF MILWAUKEE

2017 APR 24 P 2:10

To whom it may Concern
 I walter ramsey, was going
 North on 23rd and State in the
 left lane. The truck I was driving
 behide suddenly stopped. The then man
 got out of the city vechical and
 procced to motion me arand the
 vechicals right side. As I proessed
 to pull aroud, I noticed cars on
 the right side. ~~the~~ while trying to
 pull between the truck and cars
 on the right side of me. My Left
 door on my ^{Driving} ~~right~~ side rear was
 scrated by the city truck.

the fact there were cars on the
 right side was not mentioned
 in the police report.

RECEIVED

APR 25 2017

OFFICE OF
CITY ATTORNEY

414 699 5273

I am

Left from

Right ^{to} ?
to the

Walter Ramsey

B R A E G E R
4100 S. 27TH STREET
MILWAUKEE, WI 53221
PHONE: (414) 281-0454 FAX: (414) 921-9720
TIN 39-0394520

*** PRELIMINARY ESTIMATE ***

03/28/2017 02:12 PM

Owner

Owner: Walter Ramsey
Address:

Work/Day: (414)699-5273

Inspection

Inspection Date: 03/28/2017 02:13 PM
Primary Impact: Left Side

Inspection Type:
Secondary Impact:

Appraiser Name: Alex Sanchez

Appraiser License # :

Repairer

Repairer: 27th Street Auto Body
Address: 4100 S. 27th Street

Contact: Alex Sanchez
Work/Day: (414)281-0454
Home/Evening: (414)281-5000x3322
FAX: (414)921-9720

City State Zip: Milwaukee, WI 53221
Email: asanchez@braeger.com

Target Complete Date/Time:

Days To Repair: 4

Vehicle

OEM Part Price Quote ID: ****

2016 Chevrolet Cruze Limited 1LT 4 DR Sedan
4cyl Gasoline Turbo 1.4
6-Speed Automatic

Lic.Plates: 891-ZKE
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: red
Ext. Refinish: Two-Stage

Lic State: WI
VIN: 1G1PF5SB7G7134457
Mileage: 35,001
Mileage Type: Actual
Code: U2373B
Int. Color:
Int. Refinish: Two-Stage

Options

2nd Row Head Airbags
Alarm System
Auto Headlamp Control
Carpeting
Cruise Control
Dual Airbags
Floor Mats
IPOD Control
Keyless Entry System
Leather Steering Wheel

AM/FM CD Player
Aluminum/Alloy Wheels
Auxiliary Audio Input
Center Console
Digital Clock
Electric Steering
Halogen Headlights
In-Vehicle WiFi
Knee Air Bags
Lighted Entry System

Air Conditioning
Anti-Lock Brakes
Bucket Seats
Compact Spare Tire
Driver Information Sys
Electronic Compass
Head Airbags
Intermittent Wipers
LED Daytime Running Lts
MP3 Decoder

OnStar System	Power Brakes	Power Door Locks
Power Mirrors	Power Windows	Pwr Accessory Outlet(s)
Rear Side Airbags	Rear Window Defroster	Rem Trunk-L/Gate Release
Side Airbags	SiriusXM Satellite Radio	Split Folding Rear Seat
Stability Cntrl Suspensn	Strg Wheel Radio Control	Tachometer
Theft Deterrent System	Tilt & Telescopic Steer	Tinted Glass
Tire Pressure Monitor	Traction Control System	Trip Computer
USB Audio Input(s)	Velour/Cloth Seats	Wireless Phone Connect

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Rear Doors									
1	I	289		Pnl,Rear Door Outer LT	Repair			3.0*	SM
2	L	289	13	Pnl,Rear Door Outer LT	Refinish			3.2	RF
					2.2 Surface				
					0.6 Two-stage setup				
					0.4 Two-stage				
3	RI	252		W/Strip,Belt Outer LT	R & I Assembly			0.2	SM
4	RI	309		Pnl,Inner Door Trim LT	R & I Assembly			0.4	SM
5	RI	327		Handle,RR Door Outer LT	R & I Assembly			0.3	SM
Quarter And Rocker Panel									
6	BR	420		Panel,Quarter LT	Blend Refinish			1.3	RF
					0.9 Blend				
					0.4 Two-stage				
7	E	1288		Ret,Bodyside Cladding LT	94530742 GM Part	\$7.83			SM
				Quantity of 3 @ \$2.61 each					
8	RI	339		Applique,Qtr Panel LT	R & I Assembly			0.2	SM
9	E	229		Tape,Quarter Panel LT	22907771 GM Part	\$8.72		0.6	SM
Rear Body, Lamps And Floor Pan									
10	RI	533		Taillamp Assembly,Otr LT	R & I Assembly			0.3	SM
Manual Entries									
11	SB			HAZARD. WSTE. REM.	Sublet Repair	\$3.00*			SM
12	EC			CORROSION PROTECTION	Replace Economy			0.2*	RF
13	I			Rear Cover LT Drop	Repair			0.5*	SM*
13	Items								

MC	Message
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$16.55
Paint & Materials	4.7 Hours @ \$38.00	\$178.60
Parts & Material Total		\$195.15
Tax on Parts & Material	@ 5.600%	\$10.93

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$58.00	2.0	3.5	5.5	\$319.00
Mech/Elec (ME)	\$102.00				
Frame (FR)	\$58.00				
Refinish (RF)	\$58.00	4.7		4.7	\$272.60

Labor Total		10.2 Hours		\$591.60
Tax on Labor	@ 5.600%		\$33.13	
Sublet Repairs			\$3.00	
Tax on Sublet	@ 5.600%		\$0.17	
Gross Total				\$833.98
Net Total				\$833.98

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 53221 Audatex Host
 OEM Part Prices DT 03/28/2017 02:13 PM EstimateID 276066481370841088 QuoteID ****
 Rate Name Default


Audatex Estimating 8.0.134 ES 03/28/2017 02:15 PM REL 8.0.134 DT 02/01/2017 DB 03/15/2017
 © 2017 Audatex North America, Inc.

1.4 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.


Op Codes

- | | | |
|----------------------------|---|--------------------------------|
| * = User-Entered Value | ^ = Labor Matches System Assigned Rates | E = Replace OEM |
| NG= Replace NAGS | EC = Replace Economy | OE = Replace PXN OE Srpls |
| UE = Replace OE Surplus | ET = Partial Replace Labor | EP = Replace PXN |
| EU = Replace Recycled | TE = Partial Replace Price | PM = Replace PXN Reman/Reblt |
| UM= Replace Reman/Rebuilt | L = Refinish | PC = Replace PXN Reconditioned |
| UC = Replace Reconditioned | TT = Two-Tone | SB = Sublet Repair |
| N = Additional Labor | BR = Blend Refinish | I = Repair |
| IT = Partial Repair | CG= Chippguard | RI = R & I Assembly |
| P = Check | AA = Appearance Allowance | RP = Related Prior Damage |



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2017 Audatex North America, Inc.
 AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



J9L121PTKB
170661033

Wisconsin Motor Vehicle
Crash Report

MILWAUKEE POLICE DEPARTMENT
749 WEST STATE STREET
MILWAUKEE, WI 53201
(414) 933-4444

J9L121PTKB

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy L. JOHNSON	
Crash Date 03/07/2017		Crash Time 10:20 AM		Date Arrived 03/07/2017		Time Arrived 10:30 AM	
Date Notified 03/07/2017		Time Notified 10:24 AM		Total Units 02		Total Injured 00	Total Killed 00
<input type="checkbox"/> On Emergency	<input type="checkbox"/> Hit and Run	<input type="checkbox"/> Lane Closure		<input type="checkbox"/> Work Zone		<input type="checkbox"/> Trailer or Towed	
<input checked="" type="checkbox"/> Government Property		<input checked="" type="checkbox"/> Active School Zone		School Bus Related No		Tags	
<input checked="" type="checkbox"/> Reportable		Crash Type DT4000 (Standard Crash)		<input type="checkbox"/> Amended		<input type="checkbox"/> Secondary Crash	

Description

Diagram		Reconstruction By	
		Photos By	
		Additional Information None	

Narrative: I, a sworn law enforcement officer, agree that I have not added any CJIS data in this report.
UNIT 2 LEGALLY PARK WITH IT'S OUTRIGS EXTENDED, UNIT 1 ATTEMPTED TO DRIVE PASS ON THE RIGHT SIDE AND SIDESWIPE THE RIGHT REAR BUMPER OF UNIT 2

Location

ON N 23RD ST 138 FT S OF USH18 EB IN THE CITY OF MILWAUKEE IN MILWAUKEE COUNTY	Latitude	Longitude
	43.043877889	-87.941551804
	X Coordinate	Y Coordinate
	423310.0625	4766117.5
Structure Type		