

Menu Reports Help

File Date: [06/06/2018](#)

Application Status: [Open](#)

Description of Work: [Exterior Of Building In Disrepair| Excavation between properties exposing nei](#)

Case Detail: [Detail](#)

Case Type: [Residential Case](#)

Address: [125 E LLOYD ST, MILWAUKEE, WI 532123211](#)

Owner Name: [JOSE J MAZ](#)

Owner Address: [PO BOX 64047, MILWAUKEE, WI 53204](#)

Application Name:

Violator Name: Please see the Case Summary page for a complete list of violators.

Parcel No: [3530488000](#)











125 E LLOYD ST // 6-20-18 // CHALSTROM // INIT INSP PICS





