

J.C. E. W. - At. Rm 305

708 City Cr.

On July 27th around 5:50pm I was parked in front of a clients house

Address: 4714 N. 46th st., Milwaukee, WI ⁵³²¹⁸

And a very large part of the tree fell from the very top of the tree onto my truck (2017 Chevrolet Silverado LT VIN# 1GCVKREC3HZ271262 Black in color).

We called it in and was given the Report # 7087201 in operator 21.

It left damage to passenger side bed/bedliner and cover.

Handled claim from Forestry 62

Robert Wasley /Urban Forestry Manager
6732 N. Industrial Rd.

Milwaukee, WI 53225

414-286-5763

RWasle@Milwaukee.gov

2015
CITY
CLERK'S
OFFICE
AUG
13
D
3:44
MILWAUKEE

Thank you : Roberta Bailey

414-745-5756

(I am the one)

1105 S. 137th st.

(that turned in the)

West Allis, WI 53219

(2 estimates :)

baileyroberta19@gmail.com



Report #17087240 (Robert Wesley from forestry
sent in a 'report' as well)

COLLISION CENTER

OF

MILWAUKEE NORTH

Collision Center of Milwaukee North

Workfile ID: 1e95227b
Federal ID: 81-0947183

BMW Certified Collision Repair Center
1711 W FLORIST, MILWAUKEE, WI 53209
Phone: (414) 290-4360
FAX: (414) 290-4359

Preliminary Estimate

Robert Bailey
414-745-5756
11055 107th St 53214

Customer: Bailey, Roberta

Written By: Collette Wazniak

Insured: Bailey, Roberta

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 04 Right Qtr Post (Right
Side)

Owner:

Bailey, Roberta

(414) 745-5756 Cell

Inspection Location:

Collision Center of Milwaukee North

1711 W FLORIST

MILWAUKEE, WI 53209

Repair Facility

(414) 290-4360 Business

Insurance Company:

VEHICLE

2017 CHEV Silverado 1500 LT1 Doublecab 143.5" WB 4WD 4D P/U 8-5.3L Flex Fuel Direct Injection Black

VIN: 1GCVKREC3HZ271262

Interior Color: Black

Mileage In: 201,805

Vehicle Out:

License:

Exterior Color: Black

Mileage Out:

State: WI

Production Date:

Condition:

Job #:

TRANSMISSION

Automatic Transmission

CONVENIENCE

Air Conditioning

Search/Seek

Communications System

Overdrive

CD Player

Hands Free Device

4 Wheel Drive

Auxiliary Audio Connection

Xenon or L.E.D. Headlamps

POWER

Power Steering

SAFETY

Drivers Side Air Bag

SEATS

Power Brakes

Passenger Air Bag

Reclining/Lounge Seats

Power Windows

Anti-Lock Brakes (4)

WHEELS

Power Locks

4 Wheel Disc Brakes

Aluminum/Alloy Wheels

Power Mirrors

Traction Control

PAINT

Heated Mirrors

Stability Control

TRUCK

DECOR

Front Side Impact Air Bags

Rear Step Bumper

Dual Mirrors

Head/Curtain Air Bags

Get live updates at www.carwise.com/e/58Req

Preliminary Estimate

Customer: Bailey, Roberta

2017 CHEV Silverado 1500 LT1 Doublecab 143.5" WB 4WD 4D P/U 8-5.3L Flex Fuel Direct Injection Black

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	PICK UP BOX						
open	Repl	Cover Chevrolet	22878336	1	310.00		
3	#	Corrosion Protection		1	10.00	0.3	
4	*	Rpr Box assy Chevrolet				<u>12.0</u>	17.0
5	*	Add for Clear Coat					6.8
6	R&I	RT Wheelhouse liner Chevrolet				0.3	
7	*	R&I RT Side rail				0.5	
8	REAR LAMPS						
9	R&I	RT Tail lamp assy w/o LED				0.3	
10	REAR BUMPER						
11	R&I	R&I bumper assy				2.4	
12	MISCELLANEOUS OPERATIONS						
13	#	Refn De-nib & Polish					7.4
14	#	Refn Wet / Dry Sand and buff					1.2
15	#	Tint Color		1			0.5
16	#	Spray out card for color match		1			0.5
17	#	Repl Pre-Scan		1		0.5 M	
18	#	Repl Post-Scan		1		0.5 M	
19	#	Hazardous Waste Disposal		1	10.00		
20	#	**POSSIBLE HIDDEN DAMAGES - ADDITIONAL CHARGES MAY APPLY**		1			
SUBTOTALS					330.00	16.8	33.4

NOTES

Prior Damage Notes:

Preliminary Estimate

Customer: Bailey, Roberta

2017 CHEV Silverado 1500 LT1 Doublecab 143.5" WB 4WD 4D P/U 8-5.3L Flex Fuel Direct Injection Black

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			330.00
Body Labor	15.8 hrs	@ \$ 85.00 /hr	1,343.00
Paint Labor	33.4 hrs	@ \$ 85.00 /hr	2,839.00
Mechanical Labor	1.0 hrs	@ \$ 250.00 /hr	250.00
Paint Supplies	33.4 hrs	@ \$ 55.00 /hr	1,837.00
Body Supplies	13.0 hrs	@ \$ 10.00 /hr	130.00
Subtotal			6,729.00
Sales Tax	\$ 6,729.00	@ 5.9000 %	397.01
Grand Total			7,126.01
Deductible			0.00
CUSTOMER PAY			0.00
INSURANCE PAY			7,126.01

MyPriceLink Estimate ID / Quote ID:

1378107787589984256 / 146732332

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

Preliminary Estimate

Customer: Bailey, Roberta

2017 CHEV Silverado 1500 LT1 Doublecab 143.5" WB 4WD 4D P/U 8-5.3L Flex Fuel Direct Injection Black

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1GH14, CCC Data Date 07/17/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.
X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.
M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.

CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber.

D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part.

O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.



CRASH CHAMPIONS #0600

WAUWATOSA

We Believe The Difference is Trust
6242 W State Street, Wauwatosa, WI 53213
Phone: (414) 475-5926

Workfile ID: 5b1f3832
Federal ID: 47-1529314
State EPA: WIR000103960

Estimate

RO Number:

Customer:	Insurance:	Adjuster:	Estimator:	Armando Munoz
Baily, Roberta	CUSTOMER PAY	Phone:	Create Date:	8/5/2025
		Claim:		
		Loss Date:		
(414) 745-5756		Deductible:		

2017 CHEV Silverado 1500 LT1 Doublecab 143.5" WB 4WD 4D P/U 8-5.3L Flex Fuel Direct Injection

VIN: 1GCVKREC3HZ271262	Interior Color:	Mileage In:	Vehicle Out:
License:	Exterior Color:	Mileage Out:	
State: WI	Production Date:	Condition:	Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	E01		CAB						
2	E01	Remove/Install	RT Step bar chrome				0.5T	Body	
3	E01	Repair	RT Uniside assy				1.0T	Body	6.8T
4	E01		Add for Clear Coat						2.7T
5	E01		PICK UP BOX						
6	E01	Remove/Replace	RT Decal "4X4" Chevrolet	1	106.50T	OEM	0.3T	Body	
7	E01	Remove/Replace	RT Outer panel Chevrolet	1	1,124.32T	OEM	7.5T	Body	3.3T
8	E01		Overlap Major Non-Adj. Panel						(0.2)T
9	E01		Add for Clear Coat						0.6T
10	E01		Add for Inside						1.7T
11	E01	Remove/Install	R&I tailgate assy				0.0T	Body	
12	E01	Remove/Install	RT Wheelhouse liner Chevrolet				0.0T	Body	
13	E01	Remove/Install	RT Upper molding Chevrolet				0.3T	Body	
14	E01	Remove/Install	RT Deflector Chevrolet				0.2T	Body	
15	E01	Remove/Install	RT Protector rear Chevrolet				0.2T	Body	
16	E01	Remove/Install	R&I box assy				2.5T	Body	
17	E01	Remove/Replace	Tonneau cover Chevrolet	1	495.00T	OEM	1.0T	Body	
18	E01	Remove/Replace	RT Upper molding Chevrolet	1	256.83T	OEM	0.3T	Body	
19	E01		REAR LAMPS						
20	E01	Remove/Install	RT License lamp				0.2T	Body	
21	E01	Remove/Install	LT License lamp				0.2T	Body	
22	E01	Remove/Install	RT Tail lamp assy w/o LED w/o High Desert pk				0.0T	Body	
23	E01		REAR BUMPER						
24	E01	Remove/Install	R&I bumper assy				2.4T	Body	
25	E01	Remove/Install	Deduct for Overlap				(0.8)T	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Estimate

RO Number:

2017 CHEV Silverado 1500 LT1 Doublecab 143.5" WB 4WD 4D P/U 8-5.3L Flex Fuel Direct Injection

26	E01	VEHICLE DIAGNOSTICS		
27	E01	Repair	Pre-repair scan	0.5T Mech
28	E01	Repair	Post-repair scan	0.5T Mech

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					1,982.65
Labor, Body			86.00	15.8	1,358.80
Labor, Refinish			86.00	14.9	1,281.40
Labor, Mechanical			165.00	1.0	165.00
Material, Paint			62.00	14.9	923.80
Subtotal					5,711.65
Sales Tax					336.99
Grand Total					6,048.64
Net Total					6,048.64

Estimate Version	Total \$
Original	6,048.64

Insurance Total \$:	6,048.64
Received from Insurance \$:	0.00
Balance due from Insurance \$:	6,048.64
Customer Total \$:	0.00
Received from Customer \$:	0.00
Balance due from Customer \$:	0.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural