At this time I am requesting a hearing, after my claim was denied. So that evidence and witnesses can be interviewed. I am also asking for discovery in this investigation. That your investigator never contacted me.

Sincerely Jason Craig 2625 s 69th Milwaukee, WI. 53219

To whom it may concern,

2007 SET 26 AM 11: 48

RONALD eri

ASSARDT

On July 5, 2007 at approximately 1:55 a.m. I with a passenger was pulled over because my car backfired due to a mechanical defect. I was surrounded by gunpoint and then we both were handcuffed and put in a squad car.

At this time an officer with a shotgun and flashlight went to the opened drive side door and checked the vehicle.

They proceeded to open the back hatch forcing it pass its mechanical limitations, thus fore causing major damage to the roof of the car frame.

This was excessive force.

You can see the whole interior of the car from any door that is open.

There was no cause for the matter of how they searched the car.

They did not find anything upon their search, I would expect to be treated like this in third world country.

The damage EST of \$1,929.89

Phone # 414-

Jason K Craig

1987 ford mustang gt three door

238-8900 2625 S 69th Milwaukee WI 53219 from hing

BRAEGER COLLISION CENTER 4201 SOUTH 27TH STREET

GREENFIELD, WI 53221

PHONE: 414-281-3370 FAX: 414-761-4571 FEDERAL TAX ID #: 39-1868407

CD LOG NO 16042-1 DATE 07/31/07

PHONE 1:

SHOP: BRAEGER COLLISION CENTER INSP DATE: 07/31/07

ADDRESS: 4201 S 27TH STREET CONTACT: ALEX SANCHEZ

CITY STATE: GREENFIELD, WI

(414)281-6100 EXT 102 ZIP: 53221-PHONE 2: (414)281-3370

FAX: (414)761-4571

CRAIG, JASON OWNER: HOME PHONE: (414)828-8624

ADDRESS: 2625 S 69TH CITY STATE: MILWAUKEE, WI

ZIP: 53219

POINT OF IMPACT: 13

LIC#: 270-LED STATE: WI VIN: 1FABP42E5HF251650

BODY COLOR: GREEN METALLIC MILEAGE:

CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS

UC=RECONDITIONED PRT

EP=REPLACE PXN

EC=REPLACE ECONOMY

UE=REPLACE OE SURPLUS

UM=REMAN/REBUILT PRT

EU=REPLACE SALVAGE

OE=REPLACE PXN OE SRPLS

PC=PXN RECONDITIONED

TE=PARTL REPL PRICE

ET=PARTL REPL LABOR PM=PXN REMAN/REBUILT
IT=PARTIAL REPAIR

I=REPAIR L=REFINISH BR=BLEND REFINISH TT=TWO-TONE CG=CHIPGUARD SB=SUBLET

N=ADDITIONAL LABOR RI=R&I ASSEMBLY . P=CHECK

AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

1987 FORD MUSTANG GT 2DOOR HATCHBACK 8CYL GASOLINE 5.0

CODE: P1243B/A OPTNS I/24JN

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

TINTED GLASS TILT STEERING WHEEL

OP	GDE	MC	DESCRIPTION		MFG.PART NO.	PRICE	&U&	В%	HOURS R
							- - -		
I	0341		PANEL, ROOF		REPAIR			٠	8.0*1
L	0341	13	PANEL, ROOF		REFINISH				4.0 4
I	0479		SHELL, TAILGATE		REPAIR				5.0*1
L	0479		SHELL, TAILGATE		REFINISH				2.9 4
\mathbf{E}	0481	02	HINGE, TAILGATE	$\mathtt{L}\mathtt{T}$	E7ZZ6142700A	86.52			1.1 1
${f L}$	0481		HINGE, TAILGATE	$_{ m LT}$	REFINISH				0.4 4
\mathbf{E}	0482	#	HINGE, TAILGATE	RT	E7ZZ6142700A	86.52			0.6 1
			# = 01, 02						
L	0482		HINGE, TAILGATE	RT	REFINISH			٠	0.4 4

SB 0497		R 125.00*	1
	PREMIER AUTO GLASS R&I FOR REFINISH		
EC 0498	SEALANT KIT, T/GATE GLS ECONOMY PART	25.00*	INC*1
RI 0528	02 SPOILER, TAILGATE R&I ASSEMBLY		1.0 1
L M15	COLOR TINT REFINISH		1.0*4*
I M17	COVER CAR EXTERIOR SUBLET REPAIR	R 5.50*	0.3*1*
I M60	HAZARD. WSTE. REM. SUBLET REPAIR	3.00*	*1*

14 ITEMS

MC MESSAGE(S)

- 01 CALL DEALER FOR EXACT PART NUMBER / PRICE
- 02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO
- 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS OTHER PARTS PAINT MATERIAL PARTS & MATERIAL TOTAL TAX ON PARTS & MATERIAL				5.600%	173.04 25.00 261.00 459.04 25.71
LABOR	RATE	REPLACE	HRS	REPAIR HRS	
1-SHEET METAL	50.00,		2.7	13.3	800.00
2-MECH/ELEC	80.00				
3-FRAME	50.00				
4-REFINISH	50.00		8.7		435.00
5-PAINT MATERIAL	30.00				
LABOR TOTAL					1,235.00
TAX ON LABOR		6		5.600%	69.16
SUBLET REPAIRS					133.50
TAX ON SUBLET		6		5.600%	7.48
TOWING					
STORAGE					
GROSS TOTAL					1,929.89
NET TOTAL					1,929.89

SHOPLINK UG443 ES CD LOG 16042-1 DATE 07/31/07 03:33:31PM R6.37 CD 07/07 HOST LOG

(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

1.9 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

EWALD'S VENUS FORD 1/2 MILE EAST OF THE AIRPORT ON LAYTON 2727 E. LAYTON AVE. CUDAHY, WI 53110 PHONE AND FAX: (414) 481-8500 TAX ID# 20-1525184

CD LOG NO 1517-1 DATE 08/08/07

08/08/07

SHOP: EWALD'S VENUS FORD ADDRESS: 2727 EAST LAYTON AVENUE INSP DATE: CONTACT: RICK MASCARETTE CITY STATE: CUDAHY, WI PHONE 1: (414)481-8500 (414)482-7591 ZIP: 53110-FAX:

OWNER: CRAIG, JASON

POINT OF IMPACT: 0

VIN: LIC#: STATE: 1FABP42E5HF251650

BODY COLOR: MILEAGE: CONDITION: ACCTNG CTL#:

*=USER-ENTERED VALUE E=REPLACE OEM NG=REPLACE NAGS EC=REPLACE ECONOMY

UE=REPLACE OE SURPLUS

UM=REMAN/REBUILT PRT

EU=REPLACE SALVAGE

OE=REPLACE PXN OE SRPLS

PC=PXN RECONDITIONED UC=RECONDITIONED PRT EP=REPLACE PXN PM=PXN REMAN/REBUILT TE=PARTL REPL PRICE ET=PARTL REPL LABOR IT=PARTIAL REPAIR I=REPAIR L=REFINISH BR=BLEND REFINISH

TT=TWO-TONE CG=CHIPGUARD SB=SUBLET RI=R&I ASSEMBLY N=ADDITIONAL LABOR P=CHECK

AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

1987 FORD MUSTANG GT 2DOOR HATCHBACK 8CYL GASOLINE 5.0

CODE: P1243B/A OPTNS I/24JN

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

TINTED GLASS TILT STEERING WHEEL

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	АJ%	Въ	HOURS R
I	0341		PANEL, ROOF	REPAIR				8.0*1
L	0341	13	PANEL, ROOF	REFINISH				4.0 4
I	0479		SHELL, TAILGATE	REPAIR				5.0*1
L	0479		SHELL, TAILGATE	REFINISH				2.9 4
		PZ	AINT UPPER ONLY					
EC	M14		CORROSION PROTECTION	ECONOMY PART	10.00*			0.3*1*
N			COVER CAR	ADDNL LABOR OPERA	10.00*			1*
N	-		TINT COLOR TO MATCH	ADDNL LABOR OPERA				1.5*4*

7 ITEMS

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES	;			
OTHER PARTS				20.00
PAINT MATERIAL				252.00
PARTS & MATERIAL TOTAL		•		272.00
TAX ON PARTS & MATERIAL	. @		5.600%	15.23
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	0.3	13.0	665.00
2-MECH/ELEC	85.00			
3-FRAME	50.00			
4-REFINISH	50.00	6.9	1.5	420.00
5-PAINT MATERIAL	30.00			
LABOR TOTAL				1,085.00
TAX ON LABOR		@	5.600%	60.76
SUBLET REPAIRS	,			
TOWING				
STORAGE				
GROSS TOTAL				1,432.99
NET TOTAL				1,432.99

SHOPLINK U0633 ES CD LOG 1517-1 DATE 08/08/07 05:37:44PM R6.37 CD 06/07 HOST LOG

(C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

1.7 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Jason Caig 26255.69 th 771/2. LT 5321

MILWAUKEE WI 532

25 SEP-2007 PM 5 T

City Clerk
Att No Claims
200 E. Wells Street Roan 205
2011. WIT. 53202-3567

20202120222