

Goyke - Photos 3, 4, +5 - Porch Repair

Photos show missing or/and rotten porch railings, and  
spindals. Also visible are areas of rot on the column fascia,

