

CITY OF MILWAUKEE

2001 MAY -8 PM 3:36

RONALD D. LEONHARDT  
CITY CLERK

TO

Whom This may concern,  
we wish to have an appeal  
File no - 01-~~V~~88 regarding  
Karl Burg, 1323 EAST Colorado St  
Mil, Wis, 53207,

Thank you  
+ Goddess

Karl Burg

PS, yes we would like to  
request a hearing, and if  
you can, Any - wed - Thurs, Fri,  
Angam

Thank you,

CITY OF MILWAUKEE

2001 FEB 16 PM 1:02

ADAM D. LEONHARDT  
CITY CLERK

2-14-01

✓

ATTNANT: KARL R. BURG  
ADDRESS: 1323 E. COLORADO ST  
MILW WI 53207

Amount: \$760.00 for DAMAGES to  
1994 FORD ESCORT

PHONE: 489-9466 WED-THUR-FRI  
WORK: 282-5000 MON-TUES

ACCIDENT CIRCUMSTANCES

DATE OF INCIDENT: FEB-07-2001

ACCIDENT TOOK PLACE 13<sup>th</sup> ST + ORGAN ST

I WAS TRAVELING SOUTH THROUGH  
INTERSECTION ON 13<sup>th</sup> ST. TRAFFIC LIGHT  
TURNED YELLOW. CITY TRUCK NORTH-  
-BOUND MADE LEFT TURN AND STRUCK  
THE BACK PART (BUMPER-TAIL LIGHT-  
-PANEL) OF MY CAR.

CITY TRUCK # 30160

Karl Burg

CITY OF MILWAUKEE  
RECEIVED  
OFFICE OF  
CITY ATTORNEY  
01 FEB 16 PM 1:02



# FOSTER



WE SERVICE ALL MAKES AND MODELS

3636 SOUTH 27TH STREET • MILWAUKEE, WISCONSIN 53221  
(414) 282-5000 • FAX (414) 282-5855

42

Name Karl Burg

Date 2-13-01

Address 1323 E COLORADO ST #1

Phone 489-9466

MILW WI 53

Ins. Claim # \_\_\_\_\_

YEAR-MODEL-COLOR		MAKE OF CAR	BODY TYPE	LICENSE NO.	SERIAL NO.	MILEAGE		
94 FORD		ESCORT	LX 2DR	TUS 924	1FARP1155RW19864			
REPAIR	REPLACE				SUBLET WORK	PARTS & MATERIALS	LABOR	REFINISHING
✓		DAMAGE TO LEFT 1/4 PANEL					8.0	2.5
	✓	LR TAIL LAMP				9152	.3	
		COLOR TINT & CLEAR COAT						1.5
		POLISH REAR BUMPER COVER					.5	
		PAINT & MATERIALS			84 <sup>00</sup>			
* NOTE: SOME RUST NEAR DAMAGED AREA //								
		TOWING						

SUB-TOTALS	84 <sup>00</sup>	9152	369 <sup>00</sup>	168 <sup>00</sup>
------------	------------------	------	-------------------	-------------------

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH ARE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED. NATURALLY, THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS FOR IMMEDIATE ACCEPTANCE.

TOTAL	713 <sup>12</sup>
SALES TAX	39 <sup>93</sup>
GRAND TOTAL	# 753 <sup>05</sup>

THIS WORK AUTHORIZED BY \_\_\_\_\_

BRAEGER FORD BODY SHOP  
 3804 SOUTH 27TH STREET  
 MILWAUKEE, WI 53221  
 OFFICE: 414-281-6100 FAX: 414-281-1415  
 FEDERAL ID # 39-1868407

CD LOG NO 5112-1 DATE 02/14/01

SHOP: BRAEGER FORD BODY SHOP INSP DATE: 02/14/01  
 ADDRESS: 3804 SOUTH 27TH STREET CONTACT: STEVE GROTH  
 CITY STATE: MILWAUKEE, WI PHONE 1: (414)281-6100 EXT 162  
 ZIP: 53221- FAX: (414)281-1415

OWNER: BURG, KARL HOME PHONE: (414)489-9466  
 ADDRESS: 1323 E COLORADO ST.  
 APT. 1  
 CITY STATE: MILWAUKEE, WI

POINT OF IMPACT: 7

LIC#: STATE: VIN: 1FARP11J5RW198364  
 BODY COLOR: BLACK MILEAGE:  
 CONDITION: GOOD ACCTNG CTL#:

DRIVEABLE: Yes VEH. INSP#:

\*=USER-ENTERED VALUE E=NEW PART EC=ECONOMY PART  
 EU=SALVAGE PART EP=SEE PX REPORT ET=LABOR PARTIAL REPLACE  
 IT=LABOR PARTIAL REPAIR I=REPAIR/ALIGN/SUBLET L=REFINISH  
 N=ADDNL LABOR OPERATION P=CHECK TE=PART/PARTIAL REPLACE  
 AA=APPEARANCE ALLOWANCE RP=RELATED PRIOR DAMAGE UP=UNRELATED PRIOR DAMAGE  
 RI=R&I ASSEMBLY

NOTE: POSSIBLE HIDDEN DAMAGE

1994 FORD ESCORT LX 2DR HATCHBACK P1542B/D OPTNS B/24

OPTIONS: TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	HOURS	R
I	0389		PANEL, QUARTER	LT REPAIR			8.0	*1
L	0389	09	PANEL, QUARTER	LT REFINISH			4.0	4
E	0431		EXTN, QUARTER PANEL	LT F1CZ5828011A	26.65		0.3	1
L	0431		EXTN, QUARTER PANEL	LT REFINISH			0.4	4
EU	0559		TAILLAMP ASSEMBLY	LT SALVAGE PART	50.00*	+20	0.4	1

SMART PARTS CORY REF # 211547

5 ITEMS

MC MESSAGE(S)  
 09 INCLUDES 0.6 HOURS MAJOR PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES  
 GROSS PARTS

26.65

1994 FORD ESCORT LX 2DR HATCHBACK  
CD LOG NO 5112-1

OTHER PARTS				50.00
LINE ITEM MARKUP				10.00+
PAINT MATERIAL				92.40
PARTS TOTAL				179.05
TAX ON PARTS & MATERIAL @			5.600%	10.02

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	42.00	0.7	8.0	365.40
2-MECH/ELEC	63.19			
3-FRAME	42.00			
4-REFINISH	42.00	4.4		184.80
5-PAINT MATERIAL	21.00			
LABOR TOTAL				550.20
TAX ON LABOR @			5.600%	30.82
SUBLET REPAIRS				
TOWING				
STORAGE				

GROSS TOTAL 770.09

NET TOTAL 770.09

ADP SHOPLINK U4325 ES CD LOG 5112-1 DATE 02/14/01 11:27:53AM R6.1 CD 02/01  
PXN:N/00/00/00/00 CUM:/// HOST LOG  
COPYRIGHT 1999, AUTOMATIC DATA PROCESSING, INC.

1.3 HOURS WERE ADDED TO THIS ESTIMATE BASED ON ADP'S TWO-STAGE REFINISH  
FORMULA: 20% OF REFINISH HOURS, AFTER OVERLAP, PLUS 0.6 HOURS FOR THE FIRST  
MAJOR PANEL, WHERE NOTED.

# MILWAUKEE POLICE DEPARTMENT DRIVER INFORMATION EXCHANGE NON-REPORTABLE ACCIDENT

IMPORTANT  
INSTRUCTIONS  
ON REVERSE SIDE

DATE: 02-07-01 TIME: 3:45 PM LOCATION: S. 13<sup>TH</sup> ST AT W. MORGAN AVE UNIT #2 DIST: 2

UNIT #1 DRIVER #1: NAME KALIAKOWSKI, KEVIN T D.O.B. 08-27-64  
 ADDRESS: 4326 S. 31<sup>ST</sup> MILWAUKEE, WI 53207  
 OWNER: CITY OF MILWAUKEE  
 PHONE: 744-7003 INSURANCE CO: SELG INSURANCE  
 YEAR: 1993 MAKE: JALITANA COLOR: YEL  
 TYPE: TRUCK PLATE # 1R0T3 STATE: WI  
 DAMAGE: NONE  
 DRIVERS LICENSE # K452-5186-1309-00 w/07

UNIT #2 DRIVER #2: NAME BURKE, KAREL R D.O.B. 11-5-63  
 ADDRESS: 1373 I Colorado St / Milwaukee 53207  
 OWNER: SARLIS  
 PHONE: 429-9466 INSURANCE CO: Amc. Family  
 YEAR: 1997 MAKE: FORD COLOR: BLK  
 TYPE: car PLATE # TUS-92Y STATE: WI  
 DAMAGE: CRASH INTO PHONE booth  
 DRIVERS LICENSE # EX-20-5166-3405-00 w/08

OTHER PROPERTY: \_\_\_\_\_ OWNER: \_\_\_\_\_ ADDRESS: \_\_\_\_\_ PHONE: \_\_\_\_\_  
 WITNESS NAME: \_\_\_\_\_ ADDRESS: \_\_\_\_\_ PHONE: \_\_\_\_\_

SHORT NARRATIVE: UNIT #1 1/3 ON S. 13<sup>TH</sup> ST  
MAKING LEFT TURN ONTO W. MORGAN  
COLLIDED WITH UNIT #2 5/8 ON S. 13<sup>TH</sup>  
CRASH THROUGH PHONE SIGN.

MANNER OF COLLISION	1 No Contact	2 Rear End	3 Head On	4 Rear to Rear	Direction of Travel Before Accident:
	5 Angle	6 Side Swipes	7 Side Swipes	8 Other	
WHAT DRIVERS WERE DOING	10 Backing	ROAD-CONDITION			Unit 2 <input checked="" type="checkbox"/> S
	11 Changing Lanes	1 Dry	2 Wet	3 Snow/Slush	4 Ice
12 Overtake Left	13 Overtake Right	5 Sand/Mud/Dirt/Oil	6 Other	7 Unknown	8 Other
14 U-Turn	15 Turn On Red	9 Illegally Parked	16 Merging	17 Negotiating Curve	18 Other
16 Merging	17 Negotiating Curve	18 Other			

DISTRIBUTION: DAVID LEMNUZZIK OFFICER (PRINT) PAYROLL # 60213 DISTRICT 19  
 WHITE - DRIVER PINK - DRIVER