

Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

Property

4471 N. 25TH ST. Garden Homes Historic District

Description of work Applicant rebuilt front porch without a Certificate of Appropriateness. Porch guard rails,

handrails and skirting will be changed to meet guidelines and building codes.

Date issued

5/29/2015

PTS ID 103197 COA

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

All work will be carried out according to attached drawings. No additional features of the house are to be removed or replaced without consultation with Historic Preservation staff and a Certificate of Appropriateness.


Decay resistant wood should be used to ensure the longetivity of the porch. Such woods as western red cedar, redwood, or domestic spanish cedar are appropriate. Wood should be smooth and free of knots. All wood to be painted after porch alterations are made.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Carlen Hatala of the Historic Preservation staff as follows: Phone: (414) 286-5722 Fax: (414) 286-3044 E-mail: chatal@milwaukee.gov.


If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, www.milwaukee.gov/build, or call (414) 286-8210.

Cel Aleta City of Milwaukee Historic Preservation Staff

Copies to: Development Center, Ald. Ashanti Hamilton, Contractor, Inspector Construction Inspector (286-2513)





4471 North 25th Street showing porch that was built without a Certificate of Appropriateness



Porch gaard rails to be removed and replaced with appropriate ones. Skirting to be framed. Handrails down the steps to be rebuilt.

Porches






Skirting, such as this lattice panel, enclosed the area beneath the porch floor. It should always be installed with a continuous board frame around it that is wide enough to cover the rough framing lumber that supports the porch deck.


Do not it The roug through

Porch skirting is meant to give the porch a finished look and provide strength to the skirting.





This is an appropriate hand rail for the steps. Square picket balusters are to be spaced 1-1/4 inch apart. Newel should be square to match original designs.

See 4381 North 26th Street



Top rail for both guardrails and handrails has to be graspable and shaped as in drawing. Bottom rail needs beveled edges to shed water and avoid rot.





The house at 4381 North 26th Street was restored to near original appearance. Applicant can copy measurements from this porch to use for handrails and guardrails and newels at the steps.