


State Farm Insurance Companies



08-5-303

June 25, 2008

State Farm Insurance
Subrogation Services
PO Box 2371
Bloomington, IL 61702-2371

City Of Milwaukee/City Clerk's Office
Attn: Robert Overholt Claim #08S303
200 E Wells St Rm 205
Milwaukee, WI 53202

RE: Claim Number: 49-5017-181
Our Insured: Marande Buck
Date of Loss: January 23, 2008

Dear Mr. Overholt:

I have enclosed our sub demand packet per your request on June 25, 2008. If you have additional questions please give me a call.

Sincerely,

Demetria K. King
Claim Processor
(877) 457-8276, Team 60
State Farm Fire and Casualty Company

2008 JUN 30 AM 11:00
OFFICE OF
CITY ATTORNEY
CITY OF MILWAUKEE
RECEIVED



RBZ0006Z
date: 06-25-08

page: 1

route to: Scott Karr

STATE FARM FIRE AND CASUALTY COMPANY

AUTO PAYMENTS BY COL

claim number
49-5017-181
named insured
BUCK, MARANDE

policy number
0765-577-49
date of loss
01-23-08

COL 403

C denotes consolidated payment
P denotes previous data

E denotes EFT payment

COL: 403 indemnity: 8,202.30 dir rcov: 0.00 expense: 0.00

payment number	payee	amount	status	COL	pay cd	rsn	reporting party
105632847J	AMERICREDIT FIN	105.60	PAID	403	1		Named Insu
105314060J	AMERICREDIT FIN	8,096.70	PAID	403	2		Named Insu

STATE FARM INSURANCE COMPANIES
500 SOUTH 84TH STREET LINCOLN, NE 68510-2611
SUPPLEMENT FAX: (MN,WI) 800-230-1949
SUPPLEMENT FAX: (IA,NE,ND,SD) 800-455-9697
*** ESTIMATE ***

01/28/2008 11:12 AM

Owner
Owner: MARANDE BUCK
Address: 1732 N PROSPECT AVE APT
City State Zip: MILWAUKEE, WI 53202
Home/Day: (414)264-7156
Control Information
Claim # : 49-5017-18101
Loss Date/Time: 01/23/2008 06:00 AM
Loss Type: Collision
Deductible: \$500.00

Insured: BUCK, MARANDE

Claim Rep: Ginger Lauby
Work/Day: (402)327-3245

Inspection
Inspection Date: 01/25/2008 07:04 AM
Inspection Type: Field
Address: 3811 W. LINCOLN AVE.
City State Zip: MILWAUKEE, WI 53202
Primary Impact: Left Rear Corner
Secondary Impact: Left Front Corner
Driveable: No
Appointment Date/Time: 01/28/2008 08:00 AM

Appraiser Name: State Farm Insurance
Contact: Al S Loper
Address: 245 S Executive Dr 200
City State Zip: Brookfield, WI 53005

Repairer
Remarks
SMART PARTS QUOTE #684130 Lt rr suspension 414-282-3333

Vehicle
2003 Chevrolet Malibu STD 4 DR Sedan
6cyl Gasoline 3.1
4 Speed Automatic
Lic.Plate: 723 MLB Lic State: WI
Lic Expire: VIN: 1G1ND52J73M620492
Prod Date: Mileage: 0
Veh Insp# : Mileage Type: Non Readable
Condition: Code: U2633A

Options
Air Conditioning Center Console Compact Disc Player
Cruise Control Digital Clock Dual Airbags
Intermittent Wipers Lighted Entry System Power Brakes
Power Door Locks Power Mirrors Power Steering
Power Windows Rear Window Defroster Rem Trunk-L/Gate Release
Tachometer Theft Deterrent System Tilt Steering Wheel

2003 Chevrolet Malibu STD 4 DR Sedan 01/28/2008 11:33 AM

Claim # : 49-5017-18101 01/28/2008
 Tinted Glass Velour/Cloth Seats
 Damages

Ln#	Op	GDE	Description	MFR.Part No.	Price	AJ%	B%	HRS	R
1	EU	6	Bumper Assembly, Fron	RECYCLED PART MC 46	350.00*	+25.00		3.1	SM
			>> Auto Paradise						
2	L	6	Cover,Front Bumper	Refinish 2.6 Surface				2.6	RF
3	PC	41	Headlamp Assy, Hal	LT RECOND PART	123.45			INC	SM
4	N	973	Headlamps Aim	ADDITIONAL OPERA				0.4	SM
5	E	63	Panel,Headlamp Mtg	22609040 GM Part	194.08			0.5	SM
6	E	55	Lamp,Side Marker	LT 16522557 GM Part	11.06			0.2	SM
7	E	1004	Bulb,Side Marker	LT 9441837 GM Part	0.78			INC	SM
8	E	124	Socket,Frnt Sd Mar	LT 12083007 GM Part	19.27				SM
9	E	83	Panel,Hood	22601675 GM Part	251.34			0.9	SM
10	L	83	Panel,Hood	Refinish 2.9 Surface 1.2 Edge				4.1	RF
11	E	79	Reinf,Inner Fende	LT 22677003 GM Part MC 07	38.51			3.1	SM
12	L	79	Reinf,Inner Fende	LT Refinish 0.4 Surface				0.4	RF
13	E	103	Fender,Front	LT 22602679 GM Part	95.95			2.2	SM
14	L	103	Fender,Front	LT Refinish 1.8 Surface 0.5 Edge				2.3	RF
15	E	246	Guard,Fender Mud	LT 12365211 GM Part	17.95			INC	SM
16	E	151	Skirt,Inner Fende	LT 22603519 GM Part	44.29			INC	SM
17	E	111	Shield,Front Spla	LT 22610205 GM Part	27.01			INC	SM
18	PC	952	Cover,Rear Wheel	LT RECOND PART	36.84				SM
19	EU	970	Susp Assembly,Rea	LT RECYCLED PART	205.00*	+25.00		1.5	ME
			>> w/steel wheel						
20	L	M14	Corrosion Protection	Refinish				0.3*	RF
21	EC	M17	Cover Car Exterior	** NON-OEM PART	5.00*				SM
22	I	M25	Tire-Left Rear,Balan	Repair				0.2*	SM
23	N	M60	Hazardous Waste Remo	ADDITIONAL OPERA	3.00*				SM
24	L		Mask Jams	Refinish				0.3*	RF*
25	I		Aligment, Trust Angl	Sublet Repair	49.95*				ME*
26	I		Wire Repair	Sublet Repair	3.00*			0.5*	ME*

26 Items

MC Message
 07 STRUCTURAL PART AS IDENTIFIED BY I-CAR
 46 PRINTABLE ALTERNATE PARTS COMPARE

Estimate Total & Entries

Gross Parts									\$700.24
Other Parts									\$723.29
Paint Materials									\$300.00
Line Item Markup									\$138.75
Parts & Material Total									\$1,862.28
Tax on Parts & Material				@	5.600%				\$104.29
Labor	Rate		Replace Hrs	Repair Hrs	Total Hrs				
Sheet Metal (SM)	\$50.00		10.0	0.6	10.6			\$530.00	
Mech/Elec (ME)	\$85.00		1.5	0.5	2.0			\$170.00	
Frame (FR)	\$50.00								
Refinish (RF)	\$50.00		10.0		10.0			\$500.00	

2003 Chevrolet Malibu STD 4 DR Sedan 01/28/2008 11:33 AM

Claim # : 49-5017-18101 01/28/2008
 Paint Materials \$30.00
 Labor Total 22.6 Hours \$1,200.00
 Tax on Labor @ 5.600% \$67.20
 Sublet Repairs \$52.95
 Tax on Sublet @ 5.600% \$2.97
 Gross Total \$3,289.69
 Less: Deductible \$500.00-
 Net Total \$2,789.69
 Alternate Parts Y/03/02/00/01/00 CUM 03/02/00/01/00 Zip Code: 53186 Default

Audatex Estimating 5.0.322 ES 01/28/2008 11:33 AM REL 5.0.322 DT 01
 /01/2008 DB 01/15/2008
 Copyright (C) 2007 Audatex North America, Inc.

THIS IS AN ESTIMATE. REPAIR FACILITES MUST INSPECT THE VEHICLE TO DETERMINE RY
 IF ANY REPAIRS NOT LISTED ARE REQUIRED, AND TO CONTACT STATE FARM BEFORE
 MAKING SUCH REPAIRS. REPAIRER ALSO IS RESPONSIBLE FOR CONDUCTING ANY NECESSARY
 INSPECTION AND SAFETY CHECKS PRIOR TO AND AFTER COMPLETING REPAIRS.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT
 PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR
 VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY
 THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE
 MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = ** NON-OEM PART	ET = Partial Replace Labo	EP = ** NON-OEM PART
EU = RECYCLED PART	TE = Partial Replace Pric	PM = REMAN/REBUILT PART
UM = REMAN/REBUILT PART	L = Refinish	PC = RECOND PART
UC = RECOND PART	TT = Two-Tone	SB = Sublet Repair
N = ADDITIONAL OPERATION	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	RP = RP-RELATED PRIOR	

This report contains proprietary information of Audatex and may not
 be disclosed to any third party (other than the insured, claimant
 and others on a need to know basis in order to effectuate the claim
 s process) without Audatex's prior written consent.
 Copyright (C) 2007 Audatex North America, Inc.

2003 Chevrolet Malibu STD 4 DR Sedan 01/28/2008 11:33 AM
 Page 3 of 3

QUALITY REPLACEMENT PARTS REPORT

Vehicle
 2003 Chevrolet Malibu STD 4 DR Sedan
 6cyl Gasoline 3.1
 4 Speed Automatic

Options

Air Conditioning	Center Console	Compact Disc Player
Cruise Control	Digital Clock	Dual Airbags
Intermittent Wipers	Lighted Entry System	Power Brakes
Power Door Locks	Power Mirrors	Power Steering
Power Windows	Rear Window Defroster	Rem Trunk-L/Gate Release
Tachometer	Theft Deterrent System	Tilt Steering Wheel
Tinted Glass	Velour/Cloth Seats	

Ln#	Part Description	Supplier Part Number	Sub OEM Part	Supp code	C	S
3	Headlamp Assy, Hal LT	22604269		22618782 >	4	R 3
		22604269		22618782 >	5	M 3
		22618782		22618782	6	M 3
16	Cover, Rear Wheel LT		H7S	9593496 >	2	R 3
		FWC03233U20		9593496 >	3	R 3
		3233		9593496	1	R 3
		3233		9593496	7	R 3

> = ESTIMATE TOTAL IS BASED ON PRICE QUOTED BY THIS SUPPLIER

Key to Classification / Source Codes

CLS = Classification Code
 C - CAPA CERTIFIED PART QUOTED BY LISTED SUPPLIER
 M - REMANUFACTURED / REBUILT PART
 R - RECONDITIONED PART
 S - OEM SURPLUS PART

SRC = Source Code

1 - NON ORIGINAL EQUIPMENT MANUFACTURER PART
 3 - ORIGINAL EQUIPMENT MANUFACTURER (OEM) PART

Detailed Distributor List

1	PXN1307	WHEEL INNOVATIONS 4301 UNIVERSITY BLVD S JACKSONVILLE, FL 32216	(800) 624-7179 (904) 565-1994
2	PXN3588	WHEELS TO THE WORLD 680 AMERICANA DRIVE # 57 ANNAPOLIS, MD 21403	(800) 334-9433 (410) 295-5602
3	PXN4892	KEYSTONE AUTO RCND 9532 WEST CARMEN AVENUE MILWAUKEE, WI 53225	(800) 924-8230 (414) 463-1019
4	PXN6809	R P W HEADLAMPS RCND 1809 N 9TH ST PO BOX 125 INDIANOLA, IA 50125	(800) 336-4028 (515) 961-0517
5	PXN9064	R P W HDLMPS RMFD 1809 N 9TH ST PO BOX 125 INDIANOLA, IA 50125	(800) 336-4028 (515) 961-0517
6	PXN9408	AUTOSOURCE 112 DIXIE DRIVE WOODSTOCK, GA 30189	(678) 494-2340
7	PXN9954	ANNIE'S H/C & WHEELS	(800) 624-7179

01/28/2008 11:33 AM

2003 Chevrolet Malibu STD 4 DR Sedan
4301 UNIVERSITY BLVD S
JACKSONVILLE, FL 32216

Audatex Estimating 5.0.322 ES 01/28/2008 11:33 AM REL 5.0.322 DT 01
/01/2008 DB 01/15/2008
Zip Code: 53186 Search Area: Default
Copyright (C) 2007 Audatex North America, Inc.

This report contains proprietary information of Audatex and may not
be disclosed to any third party (other than the insured, claimant
and others on a need to know basis in order to effectuate the claim
s process) without Audatex's prior written consent.
Copyright (C) 2007 Audatex North America, Inc.
Audatex Estimating is a trademark of Audatex North America, Inc.

01/28/2008 11:33 AM
Page 2 of 2



RBZ00032
date: 06-25-08
time: 12:31 PM

route to: Karr, Scott

STATE FARM FIRE AND CASUALTY COMPANY
VEHICLE DAMAGE REPORT

claim number
49-5017-181

date of loss
01-23-08

```

*****
* Estimate Vehicle Info
*
*      Vehicle Owner: BUCK, MARANDE
*      Vehicle Description: 03 CHEVROLET MALIBU SEDAN BLACK
*
*****

```

FOREST HOME AUTO BODY
3135 W. FOREST HOME AVENUE
MILWAUKEE, WISCONSIN 53215
OFFICE: 414-384-6360 FAX: 414-384-6354
FEDERAL ID # 39-1897933

CD LOG NO 9915-1 DATE 02/01/08

SHOP: FOREST HOME AUTO BODY, INC.
ADDRESS: 3135 WEST FOREST HOME AVE.
CITY STATE: MILWAUKEE, WI
ZIP: 53215-

INSP DATE: 01/30/08
CONTACT: MARTY/DEBBIE ZABEL
PHONE 1: (414)384-6360
FAX: (414)384-6354

OWNER: BUCK, MARANDE
ADDRESS: 1732 N PROSPECT AVE APT
CITY STATE: MILWAUKEE, WI
ZIP: 53202-1937

HOME PHONE: (414)264-7156
CELL PHONE: (414)460-8425

CLAIM#: 49-5017-18101
INSURED: BUCK, MARANDE
LOSS DATE: 01/23/08
POINT OF IMPACT: 5

CLAIM REP: LAUBY, GINGER
TYPE OF LOSS: COLLISION

DAYS TO REPAIR: 8

INS. CO: STATE FARM
ADDRESS: 3135 W. FOREST HOME AVE
CITY STATE: MILWAUKEE, WI
ZIP: 53215-2841
EMAIL: FORESTAB@SBCGLOBAL.NET

CONTACT: LAUBY, GINGER
PHONE 1: (414)384-6360
CELL PHONE: (414)687-0689
FAX: (414)384-6354

LIC#: 723-MLB STATE: WI
BODY COLOR: BLACK
CONDITION:

VIN: 1G1ND52J73M620492
MILEAGE:
ACCTNG CTL#:

DRIVEABLE: NO

VEH. INSP#:

*=USER-ENTERED VALUE
EC=QUALITY REPLACEMENT PART
UC=RECONDITIONED PRT
EP=SEE PX REPORT
PM=PXN REMAN/REBUILT
IT=LABOR/PARTIAL REPAIR
BR=BLEND REFINISH
SB=SUBLET
P=CHECK
UP=UNRELATED PRIOR DAMAGE

E=NEW PART
UM=REMAN/REBUILT PRT
OE=DISABLED
TE=PART/PARTIAL REPLACE
I=REPAIR
TT=TWO-TONE
N=ADDITIONAL OPERATION
AA=APPEARANCE ALLOWANCE

NG=REPLACE NAGS
UE=DISABLED
EU=QUALITY RECYCLED PART
PC=PXN RECONDITIONED
ET=LABOR/PARTIAL REPLACE
L=REFINISH
CG=CHIPGUARD
RI=R&I ASSEMBLY
RP=RELATED PRIOR DAMAGE

PRELIMINARY ESTIMATE
SALVAGE...SMART PARTS QUOTE #684130
DRIVEABLE...NO
ESTIMATED DOWN TIME...8 DAYS
REAR SUSPENTION-OPEN

2003 CHEVROLET MALIBU STD 4DOOR SEDAN
 CD LOG NO 9915-1

2003 CHEVROLET MALIBU STD 4DOOR SEDAN 6CYL GASOLINE 3.1
 CODE: U2633A/G OPTNS M/24EFGI

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES
 POWER DOOR LOCKS
 HEATED BACK GLASS

TWO-STAGE - INTERIOR SURFACES
 POWER WINDOWS
 CRUISE CONTROL

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
EU	0006		BUMPER ASSEMBLY, FRONT	RECYCLED PART	350.00*	+25		3.0	1
L	0006	13	COVER, FRONT BUMPER	REFINISH				3.7	4
				2.6 SURFACE					
				0.6 TWO STAGE SETUP					
				0.5 TWO STAGE					
UC	0041	46	HEADLAMP ASSY, HALOG LT	RECOND PART	123.45*			INC	1
N	0973		HEADLAMPS AIM	ADDITIONAL OPERAT				0.4	1
E	0063	46	PANEL, HEADLAMP MTG	22609040 GM PART	194.08			0.5	1
E	0055	46	LAMP, SIDE MARKER LT	16522557 GM PART	11.06			0.2	1
E	1004		BULB, SIDE MARKER LT	9441837 GM PART	.78			INC	1
E	0124		SOCKET, FRT SD MARKE LT	12083007 GM PART	19.27				1
E	0083	46	PANEL, HOOD	22601675 GM PART	251.34			0.9	1
L	0083		PANEL, HOOD	REFINISH				4.9	4
				2.9 SURFACE					
				1.2 EDGE					
				0.8 TWO STAGE					
I	0073	07	PANEL ASSEMBLY, RAD SUP	REPAIR				3.5*	1
L	0073		PANEL ASSEMBLY, RAD SUP	REFINISH				1.8	4
				1.5 SURFACE					
				0.3 TWO STAGE					
E	0079	07	REINF, INNER FENDER LT	22677003 GM PART	38.51			3.1	1
L	0079		REINF, INNER FENDER LT	REFINISH				0.5	4
				0.4 SURFACE					
				0.1 TWO STAGE					
E	0103	46	FENDER, FRONT	LT 22602679 GM PART	95.95			2.2	1
L	0103		FENDER, FRONT	LT REFINISH				2.8	4
				1.8 SURFACE					
				0.5 EDGE					
				0.5 TWO STAGE					
E	0246		GUARD, FENDER MUD	LT 12365211 GM PART	17.95			INC	1
E	0151	46	SKIRT, INNER FENDER	LT 22603519 GM PART	44.29			INC	1
E	0111	46	SHIELD, FRONT SPLASH	LT 22610205 GM PART	27.01			INC	1
E	0820		DUCT, AIR INTAKE	12563826 GM PART	36.94			0.2	2
EU	0903	46	WHEEL, REAR	LT RECYCLED PART	50.00*	+25		0.2	1
E	0952	46	COVER, REAR WHEEL	LT 9593496 GM PART	51.40				1
E	0957		CAP, WHEEL HUB REAR	LT 9594281 GM PART	62.70				1
P	0987		SUSP CHECK, 4 WHEEL	CHECK	79.00*				2
EC	0657		HUB, FRONT WHEEL	LT ** NON-OEM PART	152.00*			0.4	2
EU	0690		SUSP ASSEMBLY, FRONT	LT RECYCLED PART	205.00*	+25		1.4	2
E	0149		RESERVOIR, W/S WASHER	12365309 GM PART	27.33			0.1	1
EC	0729		HUB, REAR WHEEL	LT ** NON-OEM PART	184.00*			0.6	2
EC	M13		WHEEL BALANCE	** NON-OEM PART	15.00*				1

2003 CHEVROLET MALIBU STD 4DOOR SEDAN
 CD LOG NO 9915-1

L	M14	CORROSION PROTECTION	REFINISH		0.3*4*
EC	M17	COVER CAR EXTERIOR	** NON-OEM PART	8.00*	4*
I	M31	SET-UP FOR REALIGN.	REPAIR		2.0*3
I	M32	UBODY, REALIGN, LF	REPAIR		3.0*3
L		MASK JAMBS	REFINISH	*	0.3*4*
N		HAZARDOUS WASTE DISP	ADDITIONAL OPERAT	3.00*	4*
I		WIRE REPAIR	SUBLET REPAIR	3.00*	0.5*2*

36 ITEMS

MC MESSAGE(S)
 07 STRUCTURAL PART AS IDENTIFIED BY I-CAR
 13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE
 46 PRINTABLE PXN COMPARE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS		878.61
OTHER PARTS		1,169.45
LINE ITEM MARKUP		151.25+
PAINT MATERIAL		400.40
PARTS & MATERIAL TOTAL		2,599.71
TAX ON PARTS & MATERIAL @	5.600%	145.58

LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	50.00	10.2	3.9	705.00
2-MECH/ELEC	60.00	2.6	0.5	186.00
3-FRAME	50.00		5.0	250.00
4-REFINISH	50.00	14.3		715.00
5-PAINT MATERIAL	28.00			
LABOR TOTAL				1,856.00
TAX ON LABOR		@	5.600%	103.94
SUBLET REPAIRS				3.00
TAX ON SUBLET		@	5.600%	0.17
TOWING				280.10
TAX ON TOWING		@	5.600%	15.69
STORAGE				

GROSS TOTAL	5,004.19
LESS: DEDUCTIBLE	500.00-

NET TOTAL	4,504.19
-----------	----------

SHOPLINK U4709 ES CD LOG 9915-1 DATE 02/01/08 11:51:23AM R6.37 CD 12/07
 PXN: Y/09/00/00/09/09 CUM 09/00/00/09/09 GEOCODE 53215
 HOST LOG
 (C) 1998 - 2007 AUDATEX NORTH AMERICA, INC.

2.8 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA..

2003 CHEVROLET MALIBU STD 4DOOR SEDAN
CD LOG NO 9915-1

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL BY A STATE FARM CLAIM REPRESENTATIVE.








Page 2
April 30, 2006

Based on the assessment of liability between the parties, State Farm Fire and Casualty Company is seeking 100% of the total claim amount listed above. The amount payable to State Farm Fire and Casualty Company for this loss is \$6,750.13.

Please remit payment of this claim and include an amount needed on the payment. If you have any questions, please call and any member of Team 4 may assist you. Thank you for your cooperation.

In order to assist you in evaluating and processing the subrogation claim we are asserting, we may provide nonpublic personal information about our customer. We are sharing this information to effect, administer, or enforce a transaction authorized by the consumer. However, you are neither authorized nor permitted to: (i) use the customer information we provided for any purpose other than to evaluate and process the subrogation claim, or (ii) disclose or share the customer information we provide for any purpose other than to evaluate and process the subrogation claim.

Sincerely,


Kay Edgcomb
Claim Processor
(877) 450-8074, Team 69

State Farm Fire and Casualty Company
Enclosure(s)

COPY

April 30, 2008

State Farm Insurance
Subrogation Services
PO Box 2371
Bloomington, IL 61702-2371

Certified Mail-Return Receipt Requested

City Of Milwaukee

200 E Wells St
Milwaukee, WI 53202

RE: Claim Number: 49-5017-181
Our Insured: Marande Buck
Date of Loss: January 23, 2008
Your Insured: City of Milwaukee
Your Insured Driver: n/a
Your Claim Number:
Your Policy Number:
Loss Location: 70th St. And Adler
West Allis, WI

Dear Sir or Madam:

Facts of Loss: Insured driving south on 70th St and hit a manhole cover that wasn't secured. Missing a rubber seal. The cover hit the back left tire, and spun vehicle into oncoming traffic. Vehicle struck a utility pole on the left side

It is our understanding that you are self insured. Our investigation indicates you are responsible for this claim. Therefore, we are seeking recovery from you. This letter is to notify you of our subrogation claim and request your cooperation in settling this matter.

To assist you in your review, here is a breakdown of the amounts State Farm paid by Cause of Loss:

041/045 - Uninsured Motorist BI	\$
042 - Uninsured Motorist PD	\$
300 series/400 - Comp/Collision	\$8,202.30
501 - Rental/Loss of Use	\$
600-050 - Med Pay/PIP	\$
Other	\$
Salvage Recovery	\$-\$1,952.11
Amount State Farm Paid	\$6,250.19
Insured Deductible	\$500.00
Total Claim Amount	\$6,750.19

HOME OFFICES: BLOOMINGTON, ILLINOIS 61710

COPY

Page 2
April 30, 2008

Based on the assessment of liability between the parties, State Farm Fire and Casualty Company is seeking 100% of the Total Claim Amount listed above. The amount payable to State Farm Fire and Casualty Company for this loss is \$6,750.19.

Please remit payment of this claim and include our claim number on the payment. If you have any questions, please call and any member of Team # may assist you. Thank you for your cooperation.

In order to assist you in evaluating and processing the subrogation claim we are asserting, we may provide nonpublic personal information about our customer. We are sharing this information to effect, administer, or enforce a transaction authorized by the consumer. However, you are neither authorized nor permitted to: (1) use the customer information we provided for any purpose other than to evaluate and process the subrogation claim, or (2) disclose or share the customer information we provide for any purpose other than to evaluate and process the subrogation claim.

Sincerely,

Kay Edgcomb
Claim Processor
(877) 457-8276, Team 60

State Farm Fire and Casualty Company
Enclosure(s)

COPART AUTO AUCTIONS
P O BOX 371308
MILWAUKEE, WI 53237 1308
PHONE (414) 769-7665
TAX ID# 942867490

Date 4/21/08

Visit us at www.copart.com

FINAL SETTLEMENT STATEMENT

Copart Lot#	6732208	39 WI - MILWAUKEE	
Loss Date	1/23/08		
Called In	2/06/08		
P/U Cleared	2/13/08		SZ80 PIP003A
Pickup Date	2/13/08		JAY HOCHSTEIN
Original Title	3/10/08		STATE FARM MUTUAL AUTO INS CO
Trans Title	3/11/08		HEARTLAND CTLU CODE
Sale Document	4/03/08		P.O. BOX 82614
Loss Type	COLLISION		LINCOLN, NE 68501
Description	03 CHEV MALIBU	BLACK	
Vehicle ID#	1G1ND52J73M620492		Claim# 495017181
License#/ST	723 MLB		Policy# 076557749
Mileage	37,926		Loss Code
Pickup From	FOREST HOME AUTO BODY		Reference#
	3135 W FOREST HOME AVE		Insured MARANDE BUCK
	MILWAUKEE, WI 53215		Owner MARANDE BUCK
	(414) 384-6360		
ADVANCE CHARGES PAID BY COPART			
TOW SERVICE			282.10
TAX			15.79

TOTAL ADVANCE CHARGES			297.89
COPART SERVICE CHARGES			
PIP POOLING CHARGE			100.00

TOTAL COPART SERVICE CHARGES			100.00
TOTAL DUE COPART			397.89
PROCEEDS FROM SALE			2350.00CR *Bid Raised By Internet*

NET PROCEEDS			\$ 1952.11CR

REC'D IN CSU

APR 23 2008

SALE INFORMATION

HEARTLAND ZONE

Lot#	6732208	Sold To	67747 SCHMIDT'S NEW LONDON
Sale Date	4/18/08		415 E MAIN STREET
Sale Amount	2350.00		HORTONVILLE, WI 54944
ACV	8075.00		(920) 779-0733 RES# 004000034107001
Repair Est	5004.00	Item#	45
Return	29.1%	Proceeds Check#	4510949

Cert# 08072C5470113

Payment From Buyer

Check Date 4/21/08
Check Amount 1952.11CR USD



SHOP PHONE: 384-6360

FOREST HOME AUTO BODY
MARTY ZABEL

3135 W. Forest Home Ave.
MILWAUKEE, WISCONSIN 53215

BODY AND FENDER REPAIRS • EXPERT REFINISHING

NAME Copart
ADDRESS _____
PHONE _____ DATE WANTED _____

DATE 2-8-8
INVOICE NO _____
REGISTRATION NO _____
HOURLY RATE _____

YEAR-MODEL-COLOR	MAKE OF CAR	BODY TYPE	LICENSE NO.	SERIAL NO	MFG. PAINT NO	MILEAGE	
03	Malibu						
REPAIR	REPLACE			SUBLET WORK	PARTS AND MATERIALS	LABOR	REFINISH
		Towing		282 10			
		Marande Buck					
		03 CHEV MALIBU BLACK					
		06732208 A Advance Charges					
		TOWING					

SUBJECT TO INVOICE PRICE CHANGES SUB TOTALS

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH ARE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED. NATURALLY THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS FOR IMMEDIATE ACCEPTANCE.

TOTAL 282
SALES TAX 15
GRAND 297

Wisconsin Motor Vehicle 9GWFQNM
Accident Report MV4000e 01/2005
PK2007

POLICE # DISTRICT 3

ACCIDENT # 080230274

<input checked="" type="checkbox"/> Reportable Accident		<input type="checkbox"/> On Emergency		<input type="checkbox"/> Amended		DOT Document Number 9GWFQNM		Document Override Number	
Agency Accident Number 080230274				Police Number DISTRICT 3					
4 - Accident Date 01/22/2008		5 - Time of Accident (Military Time) 0700		6 - Total Units 01		7 - Total Injured 00		8 - Total Killed 00	
2 - County MILWAUKEE - 40		3 - Municipality MILWAUKEE - 57, CITY				11 - Accident Location INTERSECTION			
14 - On Hwy No.		14 - On Street Name 70TH ST S			14 - Bus/Fmt/Rmp		15 - Est. Dist	15 - Hwy. Dir	15 - Hwy. Dir
16 - Fr/At Hwy No.		16 - From/At Street Name ADLER ST W			16 - Business Frontage/Ramp				
17 - Structure Type		17 - Structure Number		12 - Latitude			13 - Longitude		
80 - First Harmful Event OTHER FIXED OBJECT				93 - Manner of Collision NO COLLISION WITH MOTOR VEHICLE IN TRANSPORT					
112 - Access Control NO CONTROL		113 - Road Curvature STRAIGHT		113 - Road Terrain LEVEL/FLAT		Surface Type BLACKTOP (BITUMINOUS) - 2			
115 - Traffic Way DIVIDED-HIGHWAY-MEDIAN-STRIP-WITHOUT-TRAFFIC-BARRIER									
117 - Relation To Roadway ON-ROADWAY									
114 - Light Condition DAYLIGHT			116 - Road Surface Condition SNOW/SLUSH			118 - Weather CLOUDY			
9 <input type="checkbox"/> Hit and Run	9 <input checked="" type="checkbox"/> Government Property			9 <input type="checkbox"/> Fire	9 <input type="checkbox"/> Photos Taken		9 <input type="checkbox"/> Trailer or Towed		
9 <input type="checkbox"/> Truck, Bus, or Hazardous Materials			9 <input type="checkbox"/> Load Spillage		9 <input type="checkbox"/> Construction Zone		9 <input type="checkbox"/> Names Exchanged		
101 <input type="checkbox"/> Supplemental Reports		102 <input checked="" type="checkbox"/> Witness Statements			103 <input type="checkbox"/> Measurements Taken		79 - E M S Number		

Operator/Pedestrian

Unit Status		81 - Most Harmful Event: Collision With OTHER FIXED OBJECT		23 - Dir Of Travel SOUTH		24 - Speed Limit 30	
36 - Operating as Classified D CLASS		37 - Endorsements		35 <input type="checkbox"/> Operating Commercial Motor Vehicle			
29 - Driver's License Number B2005568456209		30 - State WI	31 - Expiration Year 2010		34 - On Duty Accident		
26 - Operator/Pedestrian Last Name BUCK			25 - First Name MARANDE		25 - Middle Initial R	25 - Suffix	
32 - Date Of Birth 02/22/1984		33 - Sex FEMALE					
26 - Address Street & Number 3439 N 15TH ST					26 - PO Box		
27 - City MILWAUKEE		27 - State WI	27 - Zip Code 53206		25 - Telephone Number (414) 460-8425 EXT.		
39 - Seat Position FRONT-SEAT-LEFT-SIDE-(MC/BIKE DRIVER, TRAIN CONDUCTOR)				40 - Safety Equipment SHOULDER-BELT-AND-LAP-BELT-USED			
38 - Injury Severity N - NO APPARENT INJURY		41 - Airbag NON-DEPLOYED		42 - Ejected NOT-EJECTED		44 <input type="checkbox"/> Medical Transport	
43 - Trapped/Extricated NOT-TRAPPED		92 - Pedestrian Location		92 - Pedestrian Action			
119 - What Driver Was Doing GOING-STRAIGHT			120 - Traffic Control TRAFFIC-SIGNAL-OPERATING			62 - No. of Citations Issued 0	
64 - 1st Statute No.	64 - 2nd Statute No.	64 - 3rd Statute No.		64 - 4th Statute No.		64 - 5th Statute No.	
122 - Driver Factors NOT-APPLICABLE							
88 - Driver or Pedestrian Cond APPEARED NORMAL		89 - Substance Presence NEITHER-ALCOHOL-NOR-DRUGS-PRESENT					
90 - Alcohol Test TEST NOT GIVEN		90 - Alcohol Content			91 - Drug Test TEST-NOT-GIVEN		

OPERATOR/PEDESTRIAN 01

Wisconsin Motor Vehicle 9GWFQNM
Accident Report MV4000e 01/2005

PK2007

91 - Drugs Reported
124 - Highway Factors OTHER-DEBRIS

Vehicle

VEHICLE 01	21 - Unit Type AUTOMOBILE		Vehicle Type PASSENGER-CAR			22 - Total Occupants 1
	56 - License Plate Number 723MLB		57 - Plate Type AUT	58 - State WI	59 - Exp Year 2008	55 - Vehicle Identification Number 1G1ND52J73M620492
	50 - Year 2003	51 - Make CHEV	52 - Model MALIBU	53 - Body Style 4D	54 - Color BLK	100 - Skidmarks to Impact (FI)
	94 - Vehicle Damage REAR DRIVER SIDE, FRONT DRIVER SIDE, UNDERCARRIAGE					
	95 - Extent Of Damage SEVERE		96 <input checked="" type="checkbox"/> Vehicle Towed Due To Damage		97 - Vehicle Removed By CHI TOWING	
	123 - Vehicle Factors NOT-APPLICABLE					

Vehicle Owner

VEH OWNER 01	45 <input checked="" type="checkbox"/> Vehicle Owner Same As Operator				
	46 - Vehicle Owner Last Name BUCK		46 - First Name MARANDE	46 - Middle Initial R	46 - Suffix
	46 - Company Name				
	47 - Address Street & Number 3439 N 15TH ST			47 - PO Box	
	48 - City MILWAUKEE		48 - State WI	48 - Zip Code 53206	49 - Telephone Number (414) 460-8425 EXT.

Insurance

INS 01	63 - Liability Insurance Company STATE-FARM		60 <input checked="" type="checkbox"/> Policy Holder Same As Owner			
	61 - Policy Holder Last Name BUCK		61 - Policy Holder First Name MARANDE			
	61 - Policy Holder Company					

School Bus

BUS 01	Bus Travelling to/from <input type="radio"/> To <input type="radio"/> From	School Name	Body Make	Seating Capacity
	School District Contracted With			

Property

Organization Type GOVERNMENT	84 - Property Owner Last Name	84 - First Name	84 - Middle Initial	84 - Suffix
---------------------------------	-------------------------------	-----------------	---------------------	-------------

Wisconsin Motor Vehicle 9GWFQNM

Accident Report MV4000e 01/2005

PK2007

PROPERTY OWNER 01	84 - Company Name CITY OF MILWAUKEE		Government Property Type COUNTY/MUNICIPAL	
	85 - Address Street & Number 200 E WELLS ST		85 - PO Box	
	86 - City MILWAUKEE	86 - State WI	86 - Zip Code 53202	87 - Telephone Number (414) 286-3850 EXT.
	83 - Government Damage Tag Number			
Fixed Objects Struck				
82 - Striking Unit 1	82 - Object Struck OTHER-FIXED-OBJECT	82 - Striking Unit	82 - Object Struck	
82 - Striking Unit	82 - Object Struck	82 - Striking Unit	82 - Object Struck	
82 - Striking Unit	82 - Object Struck	82 - Striking Unit	82 - Object Struck	

Diagram and Narrative

DIAGRAM AND NARRATIVE	105 - PHOTOS BY
	<p>DIAGRAM NOT DRAWN TO SCALE</p> <p>S. 70th St.</p> <p>W. ADLER ST.</p> <p>manhole cover</p> <p>light pole</p>
<p>UNIT 1 WAS TRAVELING SOUTH ON S. 70TH STREET ENTERING THE INTERSECTION OF W. MAIN STREET WHEN SHE DROVE OVER A LOOSE MANHOLE COVER. THE COVER FLIPPED UP CAUSING HER TO LOSE CONTROL. SHE THEN MADE A WIDE ARC AND COLLIDED WITH A LIGHT POLE.</p> <p>SUPPLEMENTAL REPORT: UPON MY ARRIVAL TO THE SCENE, I OBSERVED A MANHOLE COVER APPROXIMATELY 10 FEET AWAY FROM THE MANHOLE. I THEN OBSERVED A CAR AT THE SOUTHEAST CORNER OF THE INTERSECTION WHICH CRASHED INTO A LIGHT POLE. I ROLLED THE MANHOLE COVER BACK ONTO THE HOLE AND COULD SEE THAT IT WAS LOOSE IN ITS RING. WHEN THE CITY OF MILWAUKEE DEPARTMENT OF PUBLIC WORKS RESPONDED TO THE SCENE, THEY INFORMED ME IT WAS LOOSE AND WAS NOT SITTING PROPERLY.</p> <p>A WITNESS TO THE CRASH SAID HE WAS STANDING AT THE INTERSECTION WHEN THE CRASH OCCURRED. HE SAID THE DRIVER WAS TRAVELING SOUTH ON S. 70TH STREET WHEN HE HEARD A LOUD SOUND LIKE SHE RAN INTO SOMETHING. HE SAID THE CAR THEN VEERED IN A BIG ARC AND HIT THE LIGHT POLE.</p>	

Witness

WITNESS 01	107 - Witness Last Name LASSA	107 - First Name JAMES	107 - Middle Initial R	
	108 - Address Street & Number 7008 W ADLER STREET	108 - PO Box		109 - Date of Birth 5/2/1944
	110 - City MILWAUKEE	State WI	110 - Zip Code 53214	111 - Telephone Number (414) 475-5212 EXT.

Wisconsin Motor Vehicle 9GWFQNM

Accident Report MV4000e 01/2005

PK2007

Officer Information

OFFICER INFORMATION	125 - Officer Last Name BORKOWSKI	125 - First Name JAMES	125 - Middle Initial M	131 - Officer ID 02887
	129 - Law Enforcement Agency No. 006	130 - Law Enforcement Agency Name MILWAUKEE POLICE DEPARTMENT		
	126 - Law Enforcement Agency Address Street & Number 749 WEST STATE STREET			
	127 - City MILWAUKEE	127 - State WI	127 - Zip Code 53233	125 - Telephone Number (414) 933-4444 EXT.
	132 - Date Notified 01/22/2008	133 - Time Notified (Military Time) 0713	134 - Time Arrived (Military Time) 0740	135 - Date Of Report 01/23/2008
	Agency Accident Number 080230274	Police Number DISTRICT 3	19 - Special Study	
	18 - Agency Space			

COPY

February 15, 2008

State Farm Insurance
PO Box 83106
Lincoln, NE 68501

Phone: (888) 248-6961
Fax: (800) 423-0474

Marande Buck
1732 N Prospect Ave Apt 410
Milwaukee, WI 53202-1937

RE: Claim Number: 49-5017-181
Date of Loss: January 23, 2008
Our Insured: Marande Buck

Dear Marande:

We are providing you with our claim payment for the total loss of your vehicle. As discussed earlier, your policy provides for payment of the actual cash value of your vehicle, less any applicable deductible. Actual cash value is determined by the market value, age, and condition of your vehicle at the time the loss occurred.

To assist us in determining actual cash value, we consider information obtained by our representatives, information provided by you, vehicle valuation services, and other sources. If now or later, you have additional information you wish us to consider or if you believe we have not correctly determined the actual cash value of your vehicle, please contact us at the number indicated below.

The amount payable to you was determined as follows:

Base Price	\$8,075.00
Plus: Taxes (if applicable)	+ 452.20
License (if applicable)	+ 69.50
Title Fees (if applicable)	+ 0
Actual Cash Value	=\$8,596.70
Less: Deductible	- 500.00
Owner Retained Salvage (if applicable)	- 0
Owed to Lienholder (if applicable)	- 8,096.70
Net Amount Payable to You	=\$0

HOME OFFICES: BLOOMINGTON, ILLINOIS 61710

COPY

Marande Buck
Page 2
February 15, 2008

If you have questions concerning this total loss settlement or any other aspect of your claim, please contact us.

Sincerely,

Cheryl A. Neill
Claim Processor
1-(888) 248-6961
Team #: 58

State Farm Fire and Casualty Company

Date: 2/5/2008 1:10 PM

Claim:

Preliminary Valuation Report
STATE FARM INSURANCE
222 S 84TH ST, LINCOLN NE 68510

Date: 2/5/2008
Claim:
Policy:
Customer:
Loss Date: 2/5/2008
Deductible: \$0
Payer Code:

Valuation ID: 269
Type of Loss:
Classification: Total Loss
Assessor:
Assessor ID:
Profile: NADA Central
State: WI

Vehicle: 2003 Chevrolet Malibu 4D Sed 3.1L Inj 6 Cyl 4A
VIN: 1G1ND52J73M620492
Mileage: 37,925
Condition: Good
Type: Auto
License: WI
Color:

N.A.D.A. (C)		N.A.D.A. (C)	
CENTRAL VALUES		CENTRAL VALUES	
ND5 Malibu-V6 Sedan 4D		ND5 Malibu-V6 Sedan 4D	
Base Value	\$6,975	Base Value	\$6,975
Mileage Adjustment	\$1,100	Mileage Adjustment	\$1,100
Power Windows	Standard	Power Windows	Standard
Cruise Control	Standard	Cruise Control	Standard
-----		-----	
Total Retail Value	\$8,075	Total Retail Value	\$8,075

Mitchell International Corporation warrants that this valuation is an accurate representation of the N.A.D.A. (c) value guide.

AVERAGE BOOK VALUE	\$8,075.00
Taxable Adjustments	
Taxable Adjustments Total	\$0.00
Pre-Tax Subtotal	\$8,075.00
Post-Tax Subtotal	\$8,075.00
Non-Taxable Adjustments	
Non-Taxable Adjustments Total	\$0.00
NET TOTAL	\$8,075.00

Customer: WI

Inspection Site: WI

49-5017-181

Date: 2/4/2008 3:04 PM

49-5017-181

Claim:

Preliminary Valuation Report
STATE FARM INSURANCE
222 S 84TH ST, LINCOLN NE 68510

Date: 2/4/2008
Claim:
Policy:
Customer:
Loss Date: 1/23/2008
Deductible: \$0
Payer Code:

Valuation ID: 269
Type of Loss:
Classification: Total Loss
Assessor:
Assessor ID:
Profile: NADA Central
State: WI

Vehicle: 2003 Chevrolet Malibu 4D Sed 3.1L Inj 6 Cyl 4A
VIN: 1G1ND52J73M620492
Mileage: 40,000
Condition:
Type: Auto
License: WI
Color:

N.A.D.A. (C)		N.A.D.A. (C)	
CENTRAL VALUES		CENTRAL VALUES	
ND5 Malibu-V6 Sedan 4D		ND5 Malibu-V6 Sedan 4D	
Base Value	\$7,100	Base Value	\$7,100
Mileage Adjustment	\$1,075	Mileage Adjustment	\$1,075
Power Windows	Standard	Power Windows	Standard
Cruise Control	Standard	Cruise Control	Standard
Total Retail Value \$8,175		Total Retail Value \$8,175	

Mitchell International Corporation warrants that this valuation is an accurate representation of the N.A.D.A. (c) value guide.

AVERAGE BOOK VALUE	\$8,175.00
Taxable Adjustments	
Taxable Adjustments Total	\$0.00
Pre-Tax Subtotal	\$8,175.00
Post-Tax Subtotal	\$8,175.00
Non-Taxable Adjustments	
Non-Taxable Adjustments Total	\$0.00
NET TOTAL	\$8,175.00

Customer: WI

Inspection Site: WI

ADMINISTRATIVE DATA

2003 CHEVROLET MALIBU STD 4D SEDAN

Forest Home Auto
State Farm Insurance
Milwaukee Operations Cent Branch
PO 1619
Waukesha WI 53186-1619

Claimant:
Insured:Marande Buck
Claim:49-5017-18101
Loss Date:01/23/2008
Loss Type:Collision
Policy:
Other:

Estimator Name: MARTY/DEBBIE ZABEL
Estimator Phone: 414-384-6360
Vehicle Location: FOREST HOME AUTO BODY
License Number: 723-MLB
License State: WI
License Expiration: 08/08
Specialty Plate Type: NONE
Prior Damage Amount\$: NONE
Prior Damage Desc: NONE
Supplement Amount \$: NONE
Supplement Desc: NONE
Tow / Other Charges: 280.1
Other Remarks: NONE

N.A.D.A. VALUE**

2003 CHEVROLET MALIBU STD 4D SEDAN

**N.A.D.A. Vehicle Description: 2003 CHEV Malibu-V6 Sedan 4D

N.A.D.A. values are as of January, 2008 from the Central Edition.

-----Base Value-----	\$7,100
-----Mechanical-----	
Engine:	\$0
Transmission:	\$0
-----Equipment-----	
-----Equipment Subtotal-----	\$0
-----Mileage: Not Actual-----	\$0
	=====
Adjusted Total	\$7,100

These current N.A.D.A. values are furnished under license from NADASC. All values Copyright (C) NADASC 2008.

The values in the N.A.D.A. guide assume a vehicle in clean condition. Appropriate deductions should be made to put a vehicle in salable condition.

SPECIAL NOTE ON OLDER VEHICLES: N.A.D.A.'s editors believe that most optional equipment has little or no value on older vehicles. This is especially true of options that cost relatively little to begin with and which deteriorate with age or use.

VINSOURCE ANALYSIS

2003 CHEVROLET MALIBU STD 4D SEDAN

VIN: 1G1ND52J73M620492
Decodes as: 2003 Chevrolet Malibu STD 4D Sedan
Accuracy: Decodes Correctly
History: No activity was reported

NICB REPORT

2003 CHEVROLET MALIBU STD 4D SEDAN

No NICB/ISO Activity

REPORTED PHONE NUMBER ANALYSIS

2003 CHEVROLET MALIBU STD 4D SEDAN

No Vehicles Advertised at (414) 460-8425

CONDITION ADJUSTMENT DETAIL

2003 CHEVROLET MALIBU STD 4D SEDAN

Table with 3 columns: Typical Vehicle, Loss Vehicle, Adjustment. Rows include INTERIOR (Seats, Carpets, Int Trim, Glass, Headliner), EXTERIOR (Body, Paint, Ext Trim), MECHANICAL (Engine, Transmission), TIRES (Front, Rear), and Total Condition Adjustments: \$0.

TYPICAL CONDITION STATEMENT

2003 CHEVROLET MALIBU STD 4D SEDAN

Odometer, equipment, trim level and condition must all be carefully considered on this vehicle. The vehicle's typical mileage and condition is based on comparison of dealer and private party vehicles of the same year, vehicle type and state/province. The average miles driven for this vehicle is 66,213. Numerous descriptions have been described within each condition sub-category rating and are separated by a period. Each description is meant to be independent, but can also be interpreted as an "and/or" statement.

Table with 2 columns: Condition, Description

	Condition	Description
---INTERIOR---		
Seats:	Good	No obvious damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
Carpets:	Minor Wear	Slight stains. Slight wear, usually under the pedals. Light fading. 1-3 burn marks or holes smaller than a dime. 1 tear smaller than a credit card. Molded inserts in carpet are cracked or have slight separation. Mold that can be removed with detail.
Int Trim:	Good	No obvious damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
Glass:	Good	No obvious damage. Numerous small pits. Light scratches visible on close inspection.
Headliner:	Good	No damage. Very negligible wear visible on close inspection. Soiling removable with cleaning. No fading or discoloration.
---EXTERIOR---		
Body:	Minor Damage	Noticeable or multiple parking lot dings. 1-3 dents or creases no greater than 1 credit card in size. No large impacts or collision dents. No surface rust.
Paint:	Minor Wear	Numerous small chips. 1-3 small scrapes no greater than 1 credit card in size. Discoloration that can be polished out. Checking on 1-2 panels. Subtle mismatched paint on 1-2 panels.
Ext Trim:	Good	No damage. No dents. No impact damage. Good shine on chrome or bumper covers. Color-keyed sections in good condition. 1-3 slight scratches or marks.

--MECHANICAL---

02/01/08 10:30

AUTOSOURCE VALUATION

Page 4

Via: Direct

AS Request: 21857785

Version: 1

TYPICAL CONDITION STATEMENT (continued)

2003 CHEVROLET MALIBU STD 4D

Condition

Description

Engine: Well Maintained

Engine compartment generally clean. No obvious leaks. All accessories in good working condition. Recommended maintenance performed. Service records well documented.

Transmission: Well Maintained

Transmission housing, transaxle, differential, transfer case areas generally clean. No obvious leaks. Recommended maintenance performed. Service records well documented.

-----TIRES-----

Front Tires: Good

Tires are in good condition. 30-79% of tread remains.

Rear Tires: Good

Tires are in good condition. 30-79% of tread remains.

Having a clean, well maintained vehicle will add to its market value. Prior body damage, rust, extensive interior damage or mechanical problems will all decrease the market value of this vehicle.

RECALL BULLETINS

2003 CHEVROLET MALIBU STD 4D SEDAN

Nat'l. Highway Traffic Safety Admin (US) has issued a total of 2 recall bulletins that may apply to this vehicle.

NHTSA ID Number: 02V107
Date Issued: 04/01/02
Quantity Affected: 10,168
Dates Of Manufacture: February 2002
Noncompliance: Certain passenger vehicles fail to conform to Federal Motor Vehicle Safety Standard No. 108, "Lamps, Reflective Devices, and Associated Equipment." Some of these vehicles were produced with a left low-beam headlamp that does not meet the photometric performance requirements of the standard. Light intensities below the minimum intensity requirements cause reduction in visibility down the road for the driver of the vehicle and intensities above the maximum intensity requirements cause increase in glare for drivers ahead of or approaching the vehicle.

Remedy: Dealers will inspect the left low-beam headlamp and replace the headlamp if it does not meet requirements. The manufacturer has reported that owner notification began May 23, 2002. Owners who do not receive the free remedy within a reasonable time should contact Chevrolet at 1-800-222-1020.

02/01/08 10:30

AUTOSOURCE VALUATION

Page 5

Via: Direct

AS Request: 21857785

Version: 1

RECALL BULLETINS (continued)

2003 CHEVROLET MALIBU STD 4D

NHTSA ID Number: 04V528000
Date Issued: 10/27/04
Quantity Affected: 92,863

Defect: Certain passenger vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard No.124, "accelerator control systems." In hot ambient conditions, the accelerator pedal arm may stick at the attachment to the bracket and not return to the engine idle position when the operator lifts his foot from the accelerator pedal. Failure to return to idle could result in a vehicle crash.

Remedy: Dealers will inspect the accelerator pedal arm and replace the accelerator and brake pedal assembly with a new assembly, if necessary. The manufacturer has not yet provided an owner notification schedule for this campaign. owners should contact Chevrolet at 1-800-630-2438, Pontiac at 1-800-620-7668, or Oldsmobile at 1-800-630-6537.

ORIGINAL EQUIPMENT GUIDE

2003 CHEVROLET MALIBU STD 4D SEDAN

-----Engine Options-----		-----Transmission Options-----	
* 6 Cylinder 3.1 Engine	STD	* 4 Speed Automatic	STD
-----Other Optional Equipment-----		-----Power Accessories-----	
Anti-lock Brakes	\$400	Power Drivers Seat	\$310
* Digital Clock	STD	* Power Brakes	STD
* Center Console	STD	* Power Door Locks	STD
* Dual Airbags	STD	* Power Mirrors	TYP
* Intermittent Wipers	STD	* Power Steering	STD
* Keyless Entry System		* Power Windows	TYP
* Lighted Entry System	STD	-----Convenience Options-----	
* Tachometer	STD	* Air Conditioning	STD
* Tinted Glass	STD	* Cruise Control	\$240
-----Radio/Phone/Alarm Options-----		* Rear Window Defroster	STD
* Compact Disc Player	STD	* Rem Trunk-L/Gate Release	STD
Compact Disc W/Tape	\$150	* Tilt Steering Wheel	STD
* Theft Deterrent System	STD	-----Seat Options-----	
-----Wheel Options-----		Split Folding Rear Seat	\$195
Aluminum/Alloy Wheels	\$375	* Velour/Cloth Seats	STD

-----Option Packages-----

* Preferred Equipment	\$995	Includes Cruise Control; Keyless Entry; Power Windows; Dual Power Mirrors.
-----------------------	-------	--

Base retail price: \$18,645
=====

Loss Vehicle manufacturer's suggested retail price as reported: \$19,640

Editions available for the same body style (in order of original cost,

increasing): *STD, LS

* Indicates loss vehicle equipment.

ABOUT YOUR VALUATION

2003 CHEVROLET MALIBU STD 4D SEDAN

This report contains proprietary information of Audatex and shall not be disclosed to any third party (other than the insured or claimant) without Audatex's prior written consent. If you are the insured or claimant and have questions regarding the description of your vehicle, please contact the insurance company that is handling your claim. Information within VINsource/NICB is provided solely to identify potential duplicative claims activity. User agrees to use such information solely for lawful purposes.

Tax rates contained herein are based on general sales tax data provided by Vertex Inc. Excise, use, registration, licensing and other taxes and fees that may be applicable are not included. Audatex makes no representations or warranties concerning the applicability or accuracy of such tax data.

VEHICLE INSPECTION REPORT/TOTAL LOSS SETTLEMENT REPORT

Claim No: 49-5017-18101	Rep: _____	Claim Unit: _____
Owner: BUCK	Rep Phone: _____	Rep Fax: _____
Insured: MARANDE BUCK	Loss Code: _____	Date of Loss: 01/23/08
		Date Report.: _____
Location Address:	Phone: _____	Storage: \$ _____/day
N/A,		Towing : \$ _____
Cause of Loss:		Stock # _____
*Collision _Theft _Flood _Vandalism _Hail _Fire _Other: _____		

 VEHICLE DESCRIPTION

2003 Chevrolet Malibu STD 4D Sedan Lic. Plt:723-MLB Exp.:
 VIN: 1G1ND52J73M620492 Color: Ext. Black Int. St:WI
 Engine Disp. 3.1 No. Cyl. 6 *Gas Diesel Turbo/Supercharged Electric
 Trans: *Auto Manual Speeds: 3 *4 5 6 7 8 9 10
 Mileage: Tires Mfg: %Wear: LF 45% LR 45% SP %
 0 Size: RF 45% RR 45%

 Cab Type: Reg Cab Ext.Cab Crew Cab Load/Rating: 1/2 Ton 3/4 Ton 1 Ton
 Box Size: Box Type: Styleside Stepside
 Van Type Passenger Cargo Regular Extended Conversion Name: _____

VEHICLE EQUIPMENT

ACCESSORIES	OTHER ACC.	SEATS	ROOF	BUMPERS	OTHER
*Pwr Steer	AM Radio	Power Seat	Vinyl Top	Rear Step	Grille Grd
*Pwr Brakes	*AM/FM Stro	Du Pwr Seat	Luggage Rck	Tube	Fog Lights
*Pwr Windows	AM/FM Cass	Heated Seat	Roll/LteBar	Chrome	Winch
*Pwr Locks	AM/FM CS/CD	Lumbar Adj.	Convertible	Chr. Step	Camp.Shell
*Pwr Mirrors	*CD Player	Splt 60/40	Sun-Power	WHEELS	Bed Liner
*Cruise Ctrl	CD Changer	Bucket	Sun-Manual	Cust. Whl	Sp-in Bed
*Tilt Wheel	Equalizer	*Cloth/Velr	Sun-Pop-Up	Whl Cvr	Liner
*Air Cond.	Alarm Sys.	Leather	TRUCKS/VANS	Alum./Alloy	Tool Box
Dual Air	Rem. Startr	Vinyl	Television	Chrome	Aux Tank
AntiLck Brk	*Keyless	Cpt'n Chair	Sliding Rr	Sty. Stl	Hyd.Lft Gt
4WH Dsc Brk	Navigation	2 4 6	Window	Dual Rear	Lift Kit
4 Wh Str'g	DVD Player	GLASS	Power Rear	Wheels	Gr Eff Pkg
*Air Bg Drvr	GPS	HeadsUp Dsp	Window	SUSPENSION	Trlr Hitch
*Air Bg Pass	VCR	Heated W/S	DRIVETRAIN	Trl Tow Pkg	Run.Boards
Air Bg Othr	*Center Cons	*Heated B/Gl	*2 WD	Off. Rd Pkg	PAINT
Pwr Antenna	Overhd Cons	*Tinted Gl	4 WD	Cmp. Spl	2-Tone
Rear Wiper		Privacy Gl	AutoLckHubs		Custom
Rear Spoilr			ManuLckHubs		Graphics
*Remote Trunk					

 Use this space to explain or describe Equipment/Accessories listed above
 and/or list and describe additional Equipment/Accessories
 Preferred Equipment Group

 RADIO: *OEM Non-OEM Brand Model No. _____
 CELLULAR
 PHONE: OEM Non-OEM Brand Model No. _____
 PAINT: Orig. Repaint(+/-)\$ _____

PRE-LOSS CONDITION

Explain if other than average condition for year, make and model vehicle:

+ Avg -
=====

INTERIOR:
 Seats: _____ X
 Carpet: _____ X
 Glass: _____ X
 Dash: _____ X
 Headln: _____ X
 EXTERIOR:
 Sht.Mt: _____ X
 Paint: _____ X
 Trim: _____ X
 MECHANICAL:
 Engine: _____ X
 Trans.: _____ X
 PRIOR DAMAGE: Yes No Est. Written: Yes No Amount: \$ _____
 OVERALL CONDITION: Above Avg. Avg. Below Avg.
 Inspected by: _____
 Date: _____

TOTAL LOSS SETTLEMENT

Method used to determine base price:
 *Computerized Evaluation ___ Comparable Vehicles ___ Book Value

 COMPLETE ONLY IF COMPUTERIZED EVALUATION USED
 Name of Vendor: Autosource Evaluation Amount: \$7,100
 Did you pay the computerized evaluation amount? ___ Yes ___ No
 If No, explain: _____
 Adjusted Amount: \$ _____

COMPLETE ONLY IF COMPARABLE VEHICLES USED

	Source/Telephone	Quote By Date	Make/Model	Avail Price
1.	_____	_____	_____	Y N
2.	_____	_____	_____	Y N
3.	_____	_____	_____	Y N

Circle vehicle number(s) used to determine base price: (1 2 3) Explain any adjustments for difference in mileage, equipment, condition, prior damage, etc.: _____
 Adjusted Amount: \$ _____

BOOK VALUES
 Book(s) used: _____ Basic Book Price: \$ _____
 List additions or deductions for equipment, mileage, prior damage, etc.: _____
 Adjusted Amount: \$ _____

 Did you pay this amount? ___ Yes ___ No If No, explain: _____

Base Price / ACV \$ _____
 Tax + _____
 Fees + _____
 Subtotal = _____
 Owner Retained Salvage - _____
 Deductible - _____
 Lienholder Payoff - _____
 Amount Paid Owner \$ _____
 Date Settled _____

Claim Rep: _____

Signature: _____

SALVAGE DISPOSITION
 Name of Purchaser: _____
 Date Sold: _____
 Date Remit Rec'd: _____
 High Salvage Bid: \$ _____
 Towing Expense: - _____
 Storage Expense: - _____
 Misc. Expense: - _____
 Net Salvage Return: \$ _____
 Remarks: _____

Disposition of Title: _____

Vehicle Inspection Report

Claim No: 49-5017-18101 Rep: _____ Claim Unit: _____
Owner: BUCK Rep Phone: _____ Rep Fax: _____
Insured: MARANDE BUCK Loss Code: _____ Date of Loss: 01/23/08
Date Report.: _____
Location Address: Phone: _____ Storage: \$ _____/day
N/A, Towing : \$ _____
Cause of Loss: Stock # _____
*Collision Theft Flood Vandalism Hail Fire Other: _____

VEHICLE DESCRIPTION

2003 Chevrolet Malibu STD 4D Sedan Lic. Plt: 723-MLB Exp.: _____
VIN: 1G1ND52J73M620492 Color: Ext. Black Int. GRAY St: WI
Engine Disp. 3.1 No. Cyl. 6 *Gas Diesel Turbo/Supercharged Electric
Trans: *Auto Manual Speeds: 3 *4 5 6 7 8 9 10
Mileage: Tires Mfg: _____ %Wear: LF 45% LR 45% SP ___%
0 Size: _____ RF 45% RR 45%

Cab Type: Reg Cab Ext. Cab Crew Cab Load/Rating: 1/2 Ton 3/4 Ton 1 Ton
Box Size: Box Type: Styleside Stepside
Van Type Passenger Cargo Regular Extended Conversion Name: _____

VEHICLE EQUIPMENT

ACCESSORIES	OTHER ACC.	SEATS	ROOF	BUMPERS	OTHER
*Pwr Steer	AM Radio	Power Seat	Vinyl Top	Rear Step	Grille Grd
*Pwr Brakes	*AM/FM Stro	Du Pwr Seat	Luggage Rck	Tube	Fog Lights
*Pwr Windows	AM/FM Cass	Heated Seat	Roll/LteBar	Chrome	Winch
*Pwr Locks	AM/FM CS/CD	Lumbar Adj.	Convertible	Chr. Step	Camp.Shell
*Pwr Mirrors	*CD Player	Splt 60/40	Sun-Power	WHEELS	Bed Liner
*Cruise Ctrl	CD Changer	Bucket	Sun-Manual	Cust. Whl	Sp-in Bed
*Tilt Wheel	Equalizer	*Cloth/Velr	Sun-Pop-Up	Whl Cvr	Liner
*Air Cond.	Alarm Sys.	Leather	TRUCKS/VANS	Alum./Alloy	Tool Box
Dual Air	Rem. Startr	Vinyl	Television	Chrome	Aux Tank
AntiLck Brk	*Keyless	Cpt'n Chair	Sliding Rr	Sty. Stl	Hyd.Lft Gt
4WH Dsc Brk	Navigation	2 4 6	Window	Dual Rear	Lift Kit
4 Wh Str'g	DVD Player	GLASS	Power Rear	Wheels	Gr Eff Pkg
*Air Bg Drvr	GPS	HeadsUp Dsp	Window	SUSPENSION	Trlr Hitch
*Air Bg Pass	VCR	Heated W/S	DRIVETRAIN	Trl Tow Pkg	Run.Boards
Air Bg Othr	*Center Cons	*Heated B/Gl	*2 WD	Off. Rd Pkg	PAINT
Pwr Antenna	Overhd Cons	*Tinted Gl	4 WD	Cmp. Spl	2-Tone
Rear Wiper		Privacy Gl	AutoLckHubs		Custom
Rear Spoiler			ManuLckHubs		Graphics
*Remote Trunk					

Use this space to explain or describe Equipment/Accessories listed above
and/or list and describe additional Equipment/Accessories
Preferred Equipment Group

RADIO: *OEM Non-OEM Brand Model No. _____
 CELLULAR
 PHONE: OEM Non-OEM Brand Model No. _____
 PAINT: Orig. Repaint(+/-)\$ _____

PRE-LOSS CONDITION

Explain if other than average condition for year, make and model vehicle:

	+ Avg -	
	=====	
INTERIOR:		
Seats: _____	X	_____
Carpet: _____	X	_____
Glass: _____	X	_____
Dash: _____	X	_____
Headln: _____	X	_____
EXTERIOR:		
Sht.Mt: _____	X	_____
Paint: _____	X	_____
Trim: _____	X	_____
MECHANICAL:		
Engine: _____	X	_____
Trans.: _____	X	_____
PRIOR DAMAGE: Yes <input type="checkbox"/> No <input type="checkbox"/> Est. Written: Yes <input type="checkbox"/> No <input type="checkbox"/> Amount: \$ _____		
OVERALL CONDITION: <input type="checkbox"/> Above Avg. <input type="checkbox"/> Avg. <input type="checkbox"/> Below Avg.		
Inspected by: _____		
Date: _____		

Report Generated by Audatex, a Solera Company

(C) 2008 Audatex North America, Inc. All Rights Reserved.