



Existing window deterioration



View of exterior existing window



View of exterior existing window

MPS - Existing Window Condition

3360 N Sherman Boulevard Milwaukee, Wisconsin

422 N 15th St. / MILWAUKEE, WISCONSIN 53233
P 262.901.0505 / F 262.901.0510 www.cka-ae.com

This graphic is an artist rendition. While efforts were made to best represent the finished project, variations in display hardware and printing may cause finishes, material patterns, and colors to vary in appearance both electronically and in physical deliverables. This artistic rendering is proposed and not an actual, real life project depiction. Any renderings, sketches, graphic materials, features, dimensions, existing or future views depicted or otherwise described herein are proposed and conceptual only, and are based upon preliminary development plans, which are subject to withdrawal, revisions and other changes. This rendering should not be relied upon as any warranties or representations express or implied, of the final detail of the proposed improvements. Any features or colors described are representative only, and Christopher Kidd & Associates, LLC reserves the right to make changes or substitutions of equal or better quality.



Interior view broken window



Existing entry doorway



North elevation exterior view

MPS - Existing Window Condition

3360 N Sherman Boulevard Milwaukee, Wisconsin

422 N 15th St. / MILWAUKEE, WISCONSIN 53233
P 262.901.0505 / F 262.901.0510 www.cka-ae.com

This graphic is an artist rendition. While efforts were made to best represent the finished project, variations in display hardware and printing may cause finishes, material patterns, and colors to vary in appearance both electronically and in physical deliverables. This artistic rendering is proposed and not an actual, real life project depiction. Any renderings, sketches, graphic materials, features, dimensions, existing or future views depicted or otherwise described herein are proposed and conceptual only, and are based upon preliminary development plans, which are subject to withdrawal, revisions and other changes. This rendering should not be relied upon as any warranties or representations express or implied, of the final detail of the proposed improvements. Any features or colors described are representative only, and Christopher Kidd & Associates, LLC reserves the right to make changes or substitutions of equal or better quality.



Interior view glass block window



Interior view existing window



Interior view gym windows

MPS - Existing Window Condition

3360 N Sherman Boulevard Milwaukee, Wisconsin

422 N 15th St. / MILWAUKEE, WISCONSIN 53233
P 262.901.0505 / F 262.901.0510 www.cka-ae.com

This graphic is an artist rendition. While efforts were made to best represent the finished project, variations in display hardware and printing may cause finishes, material patterns, and colors to vary in appearance both electronically and in physical deliverables. This artistic rendering is proposed and not an actual, real life project depiction. Any renderings, sketches, graphic materials, features, dimensions, existing or future views depicted or otherwise described herein are proposed and conceptual only, and are based upon preliminary development plans, which are subject to withdrawal, revisions and other changes. This rendering should not be relied upon as any warranties or representations express or implied, of the final detail of the proposed improvements. Any features or colors described are representative only, and Christopher Kidd & Associates, LLC reserves the right to make changes or substitutions of equal or better quality.