RECEIVED

MAY 1 2013

OFFICE OF CITY ATTORNEY

MetLife Auto & Home[®] Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204

800-634-9740

2013 MAY - 1 AM 11: 23

CITY OF MILWAUKEE

CITY CLERK'S OFFICE

MetLife[®]

City Clerk, City Of Milwaukee ATTN: Claims 200 East Wells St., Room 205 Milwaukee , WI 53202-3567

appeal

Our Claim Number: FRE56181 Your Claim Number: dol 03/07/2013 2013.4PR.31 AM 11: 20 CITY CLERK'S OFFICE

Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204 800-634-9740

MetLife®

04/23/2013

City Of Milwaukee Attn: Office Of The City Clerk 200 East Wells St., Room 205 Milwaukee, WI 53202-3567

Our Customer:

Barbara Rucker

Our Claim Number:

FRE56181

Date of Accident:

03/07/2013

Your Customer:

City Of Milwaukee

Your Claim Number

1030-2013-1104

Dear City Clerk,

Please consider this notice as a record of appeal to a denial letter from the Office of the City Attorney, Grant Langley, dated April 11, 2013.

Our insured's parked, unoccupied vehicle was struck by a city sanitation truck, bearing registration 84357, on 3/7/13, in front of 1302 N 46th St., Milkwaukee, WI.

The point of impact is a horizontal scraping which would match the size of the 2012 Mack 600 truck.

Please review the enclosed police report and reconsider your liability position.

Sincerely,

Margaret Gauthier Metropolitan Group Property and Casualty Insurance Company Supervisor, Ext: 6036 Fax: 866-260-1164

Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204 800-634-9740

MetLife®

04/23/2013

City Clerk, City Of Milwaukee 200 East Wells St., Room 205 Milwaukee, WI 53202-3567

Our Customer:

Barbara Rucker

Our Claim Number:

FRE56181

Date of Accident:

03/07/2013

\$2,026.39

Amount of Damages: Driver:

City Sanitation Driver

Plate:

84357

Location of Accident:

Milwaukee, WI

Notification of Insurance Claim

Our investigation shows that the driver of a vehicle owned by the City Clerk, City Of Milwaukee is responsible for the accident involving our customer, Barbara Rucker.

On 3/7/13, our insured's 2005 Hyundai Santa Fe was parked in front of 1304 N 46th St., Milwaukee, WI. A city sanitation truck, a 2012 Mack 600, bearing license plate 84357, struck the parked vehicle in a sideswipe type accident. Your driver did not stay to file a report; the police were called and the report is attached.

Since our insured is not at fault, you will need to reimburse us for damages paid on this claim. If you have automobile insurance, please send this letter to your insurance company and ask them to contact me right away.

Thank you.

Sincerely,

Margaret Gauthier Metropolitan Group Property and Casualty Insurance Company Phone: 800-634-9740 Ext: 6036

Fax: 866-260-1164

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204 800-634-9740

MetLife®

04/02/2013

City Of Milwaukee 2142 W Canal Street Milwaukee , WI 53233

Our Customer:

Barbara Rucker

Our Claim Number:

FRE56181

Date of Accident:

03/07/2013

Amount of Damages:

\$2,026.39

Driver:

unknown

Plate:

84357

Location of Accident:

Milwaukee, WI

Notification of Insurance Claim

Our investigation shows that the driver of a vehicle owned by the City Of Milwaukee is responsible for the accident involving our customer, Barbara Rucker.

Since our insured is not at fault, you will need to reimburse us for damages paid on this claim. If you have automobile insurance, please send this letter to your insurance company and ask them to contact me right away.

Thank you.

Sincerely,

Margaret Gauthier

Metropolitan Group Property and Casualty Insurance Company

Phone: 800-634-9740 Ext: 6036

Fax: 866-260-1164

CERTIFIED MAIL - RETURN RECEIPT REQUESTED



For Customer Support refer to the appropriate platform below:

OrderPoint

800-934-9698 Orderpoint.support@lexisnexis.com

Accurint for Insurance

866-277-8407 Accurint.support@lexisnexis.com

Lexis.com

800-543-6862

Police Call #130662500

Detailed History for Police Call #130662500 As of 4/05/2013 10:52:03

Output for:

Priority:3 Type: 1304 - ACC PDO Location: 1302 N 46TH ST,MKE

LocCross:btwn W JUNEAU AV and W VLIET ST

Created:	03/07/2013 19:43:51	PT08	006832
	03/07/2013 19:57:03		
Closed:	03/07/2013 19:57:03	PT08	006832

IC: PrimeUnit: Dispo:AD Type:1304 - ACC PDO

19:43:51 CREATE Location:1302 N 46TH ST, MKE Type:1304 Name: BARBARA RUCKER RPaddr:1302 N 46TH

ST Phone: (414) 935-9010 Dispo: AD DAREA: D3 RptDist: 4229 TypeDesc: ACC PDO

LocCross:btwn W JUNEAU AV and W VLIET ST Priority:3 Response:1PO Agency:MWPD

LocType:S Contact?:Do NOT contact Language?:No Service Provided

19:57:03 ADVSED Dispo:AD DispoLevel:0 Comment:OCC'D EARLIER THIS MORNING // CLLR STATES

HER VEH WAS PARKED, CITY GARBAGE TRUCK DROVE PAST -- AFTER TRUCK DROVE PAST THERE WAS DAMAGE TO HER VEH // THINKS GARBAGE TRUCK DAMAGED HER VEH // SHE HAS MOVED THE VEH SINCE THEN // ADVISED TO FILE

ACCIDENT REPORTAT DISTRICT STATION

19:57:04 NOMORE

19:57:03 -NPREMS Comment:(none)

CONTO	ACT	INIEO.
CUNI	ALI	INFO:

Name	Phone	RPaddr	Contact?	Language?	Contact3	Contact4
BARBARA RUCKER	(414) 935-9010	1302 N 46TH ST	Do NOT contact	No Service Provided		

Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204 800-634-9740

MetLife

04/23/2013

City Clerk, City Of Milwaukee Attn: Claims 200 East Wells St., Room 205 Milwaukee, WI 53202-3567

Your Insured: City Clerk, City Of Milwaukee

Your Policy Number:

Your Claim Number: dol 03/07/2013

Our Customer: Barbara Rucker Our Claim Number: FRE56181 Date of Accident: 03/07/2013

Dear Claims:

We understand you are financially responsible for the above referenced loss. Our investigation of the accident has determined your driver was negligent and is therefore responsible for the damages we have paid to our insured. If you have insurance coverage, please provide us with your insurance information. Enclosed is our supporting documentation.

Property Damage

Collision or ACV:

\$1,776.39

Deductible:

\$250.00

Rental:

\$0.00

Other:

\$0.00

TOTAL:

\$2,026.39

Does Massachusetts Bailment Apply?

0 H ---- D O D -- 2204 Cl -- I -- WC 20241 2204

Kindly remit payment to: MetLife Auto & Home; P.O. Box 2204, Charlotte, NC 28241-2204 If you have any questions, please call us. Please include claim number FRE56181 on all payments.

Thank you.

Margaret Gauthier

Supervisor, Ext: 6036, Fax: 866-260-1164

Metropolitan Group Property and Casualty Insurance Company

Date: Estimate ID: 3/13/2013 07:52 AM

Estimate Version:

FRE56181 -- 1

Committed Profile ID: MetLife

MetLife Auto & Home

P.O. Box 410200, Charlotte, NC 28241-9932 (800) 854-6011

Field Adjuster: Chris Adey

Cell: 262-212-6750

VO: 1-800-854-6011 x 4775

Fax:1-855-413-3884

email: cadey@metlife.com

** All supplements need prior approval.

** All supplement materials need to be sent to field adjuster.

* By providing a copy of known damages this is not an acceptance of liability or a confirmation of coverage, or that a payment is to follow.

Damage Assessed By: Christopher Adey

File Handler: Kim Chan FRARC

(800) 854-6011 ext. 5093

Type of Loss: Collision

Vehicle Production Date: 1/05

Assgn Date: 3/11/2013

Claim Number: FRE56181 - 1

Contact Phone: (414) 935-9010

Drive Train: 2.7L Inj 6 Cyl 2WD

Part Type/

Part Number

License: WPV548 WI

Search Code: MESEWI

Condition Code: Good Date of Loss:

3/7/2013

3/12/2013 Custm Contct: Deductible: 500.00

Policy No:

087012083-2

BARBARA RUCKER Insured:

Owner: BARBARA RUCKER

1302 N 46TH ST, MILWAUKEE, WI 53208 Address:

Telephone: Home Phone: (414) 935-9010

Mitchell Service: 917723

Description: 2005 Hyundai Santa Fe GLS

4D Ut Body Style:

KM8SC13D75U963025 VIN:

Mileage: 82,266

OEM/ALT:

Color: Maroon

PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER Options:

MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, LUGGAGE RACK SKID PLATES, PREMIUM SOUND SYSTEM, ANTI-LOCK BRAKE SYS., TRACTION CONTROL FOG LIGHTS, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL, AUTOMATIC TRANSMISSION

TINTED GLASS, VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM AM/FM STEREO CASSETTE/CD, FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS, REAR WINDOW WIPER

STEERING WHEEL MOUNTED CONTROLS

COPY OF ESTIMATE PROVIDED TO CUSTOMER

Line Item Line Entry Labor

Description

Front Bumper

ESTIMATE RECALL NUMBER: 03/13/2013 07:52:12 FRE56181 -- 1

Operation

Mitchell Data Version:

Number

Type

Item

OEM: JAN_13_V MAPP:JAN_13_V

Software Version:

7.0.483

Copyright (C) 1994 - 2013 Mitchell International All Rights Reserved

Page 1 of 4

Amount

Labor

Units

Estimate Version: 0 Committed Profile ID: MetLife BDY REMOVE/INSTALL 1.4 # 700005 Frt Bumper Assy 1 BDY REMOVE/REPLACE Frt Add w/Fog Lamps 0.3 2 700007 BDY CHECK/ADJUST Fog Lamps 0.4 3 Existing 4 700008 BDY REPAIR Frt Bumper Cover 1.0*# REFINISH/REPAIR C 2.3* 5 RFF Frt Bumper Cover MODIFIED REFINISH WITH FULL CLEAR COAT 6 Front Lamps REMOVE/INSTALL L Front Combination Lamp INC # 7 700038 BDY INC # 8 700055 BDY REMOVE/INSTALL R Side Marker Lamp REMOVE/REPLACE ** QUAL REPL PART 8.57 0.2 # 9 703290 BDY L Marker Lamp Assembly Front Fender BDY REMOVE/INSTALL 0.2 10 700221 L Fender Moulding 0.5*# 11 700227 BDY REPAIR L Fender Panel Existing REF REFINISH/REPAIR L Fender Panel C 1.5* 12 13 MODIFIED REFINISH WITH FULL CLEAR COAT ** QUAL REPL PART 700233 BDY REMOVE/REPLACE L Fender Liner 56.00 0.3 14 Wheel 85.00 * 0.3 703340 BDY REMOVE/REPLACE Alloy Wheel Qual Recycled Part 15 Line Markup %25.00 21.25 16 Front Door 50*# 17 701071 **BDY** REPAIR L Frt Door Repair Panel Existing REFINISH L Frt Door Outside C 2.2 REF 18 701886 REF REFINISH L Frt Door Moulding C 0.8 19 REMOVE/INSTALL L Frt Belt Moulding 0.5 # 20 701075 BDY 21 701077 BDY REMOVE/INSTALL L Frt Door Moulding 0.2 701079 BDY REMOVE/INSTALL L Frt Door Mirror INC 22 701175 BDY REMOVE/INSTALL L Frt Door Handle 0.7 # 23 Rear Door 702922 BDY REMOVE/REPLACE L Rear Door Moulding 87731-26500 141.56 0.3 24 RFF REFINISH L Rear Door Moulding C 0.6 25 Additional Costs & Materials ADD'L COST 3.00 * 936012 Hazardous Waste Disposal 26 ADDITIONAL OPERATIONS REF ADD'L OPR 2.1 27 Clear Coat Additional Costs & Materials ADD'L COST Paint/Materials 323.00 * 28 MANUAL ENTRIES Restore corrosion protection ** QUAL REPL PART 5.00 * 0.3* 900500 BDY * REMOVE/REPLACE 29 MCH * ADD'L LABOR OP Align suspension Sublet 69.95 * 0.0* 30 900500 REMOVE/REPLACE Flex Additive ** QUAL REPL PART 5.00 * 0.0* REF * 31 900500 ** QUAL REPL PART 20.00 * 900500 BDY * REMOVE/REPLACE Tape Stripe 0.3* 32 BDY * Mount- Balance If wheel/tire 25.00 * 0.0* ADD'L LABOR OP Sublet 900500 33

* - Judgment Item

- Labor Note Applies

** QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

BLUE OVAL SERVICE N15 W22180 WATERTOWN RD. WAUKESHA WI 53186 (414) 379-7547 (414) 520-4982

KEYSTONE AUTOMOTIVE 9532 W. CARMEN AVE. MILWAUKEE WI 53225 (800) 924-8230 (414) 463-1019

** 92303-26011

8.57 14 ** HY1248107 56.00

ESTIMATE RECALL NUMBER: 03/13/2013 07:52:12 FRE56181 -- 1

Mitchell Data Version:

OEM: JAN_13_V

MAPP:JAN_13_V

Copyright (C) 1994 - 2013 Mitchell International

Page 2 of 4

3/13/2013 07:52 AM

FRE56181 -- 1

Date: Estimate ID:

Date: 3/13/2013 07:52 AM Estimate ID: FRE56181 -- 1

Estimate Version: 0 Committed

Profile ID: MetLife

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Point(s) of Impact

9 Left Side (P), 10 Left Front Side (S), 11 Left Front Corner (S)

Clmnt, Ins Co: MetLife

Inspection Site: BARBARA RUCKER

Address: 1302 N 46TH ST

MILWAUKEE, WI 53208-2741

(414) 447-7908 (414) 447-7908

Inspection Date: 3/12/2013

Body Shop: UNKNOWN-OWNER TO PRESENT Address: A COPY OF THIS ESTIMATE TO

SHOP OF CHOICE

FAILURE TO PRESENT THIS ESTIMATE TO REPAIRER MAY RESULT IN ADDITIONAL EXPENSE TO YOU.

THESE REPAIRS SHOULD BE COMPLETED IN ACCORDANCE WITH I-CAR OR TECH-COR PROCEDURES.

NO SUPPLEMENTS WILL BE HONORED WITHOUT PRIOR AUTHORIZATION FROM A METLIFE AUTO AND HOME REPRESENTATIVE. DIRECTION TO PAY REQUIRED.


" The glass part price, kit and labor contained in this estimate have been calculated based on market pricing including markup for your area. The MetLife Auto & Home glass administrator is Safelite Auto Glass. Please contact Safelite Auto Glass at 888-800-4527 if you would like to arrange for them to complete the work.

Your complete customer satisfaction is our goal at MetLife Auto & Home please remember that you have the right ro select a repair facility or contractor of your choice. If you have not already chosen a shop or contractor or have no preferenve, we will be happy to refer you to a vendor in your area.

All information stored, transmitted, received, or contained in MetLife's systems is MetLife's sole property and may be accessed and decrypted by MetLife at any time and may be disclosed to appropriate third parties.

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911

Mar-12-2013 04:23p



SUMMARY MASTER TRANSACTION FILE PAGE BACK SCR M1 POL NUM 48A395780657-2 LOSS DATE 030713-0 CLAIM NUM FRE56181 - 0 PG 1 OF 1 FCO A1 EMPL# 0630511 PASSWORD FUNCTION CODE I S CLAIM S D B CURRENT LOSSES EXPENSES NET NET U SYM/ U S N O/S PAID PAID SUBRO SALVAGE I ID NAME SUFF B P R RESERVE TO DATE TO DATE REC'D REC'D T CD BARBARA A COLO Y C MILWIKKI,C PDI1 C 0 1776.39 6.30 0.00 0.00 0 0.00 0 0.00 0.00 0.00 0

END OF DATA - HIT ENTER SUFF/GROUP SUMMARY SCREEN

PF1=CLAIMS MENU PF3=INQUIRY PF5=DATA ENTRY PF12=PRINT

Date: 4/23/2013 Time: 10:31:13 AM

MTF TRANSACTION SCREEN												SCF	IM S	
					PAGE I	FORV	ND	I	PAGI	E BACK	PG	01	OF	01
	LINE	A POLICY NUMB	BEI	R 39578065	57 ST	JFF:	IX 2	2	LOS	SS DATE	03071	L30		
		CLAIM#	FI	RE56181 -	0 RI	ISK	STA	ATE	48					
CSM S P	F ID	BLK CHK NO	CI	R AMOUNT	SUITS	OD	OC	DC	CC	DATE	IMCC	MC	KD	OC
COL 0 .	. 11	BARBARA A RUCK		00000000		MF	К9		C	030713			ΥY	К9
COL 0 .	. 21	0894 005861542		00025000		MF	K9		C	031313	s	0	RD	K7
COL 0 .	4 22	0894 005860865		00152639		MF	K9		C	031313	s		RD	K7
COL 0	37	PRPT 028264621		00000325		MF	K9		C	031313			99	K9
COL 0 .	. 98					DI	J8		C	031813			MF	K9
COL 0 .	. 98					A1	A1		C	032813			DI	J8
									C	032913			CH	A1
COL 0 .	- 12 E						A1		C	040213			TW	A1
COL 0	37	PRPT 427606601		00000305		UH	A1		C	041713			99	K9
PDI 1 .	. 11	MILWIKKI, CITY,		00000000		DI	J8	•	C	030713			DI	J8
PDI 1 .	. 15			00000000		DI	J8		C	032813			DI	J8

END OF DATA - HIT ENTER FOR SUM MTF SCREEN

Date: 4/23/2013 Time: 10:31:20 AM

MetLife Auto & Home® Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204 800-634-9740

CITY OF MILWAUKEE

2013 APR 11 AM 7: 10

CITY CLERK'S OFFICE

MetLife[®]

RECEIVED

L

APR 12 2013

OFFICE OF CITY ATTORNEY

City Of Milwaukee ATTN: Brian Field 2142 W Canal Street Milwaukee, WI 53233

Our Claim Number: FRE56181 Your Claim Number: dol 03/07/2013 RECEIVED

APR 10 2013 27 5800

Subrogation - Warwick Mail Processing Center PO Box 2204 Charlotte, NC 28241-2204 800-634-9740

MetLife[®]

04/02/2013

RECEIVED

APR 12 2013

OFFICE OF CITY ATTORNEY

City Of Milwaukee

2142 W Canal Street Milwaukee, WI 53233

Our Customer:

Barbara Rucker

Our Claim Number:

FRE56181

Date of Accident:

03/07/2013

Amount of Damages:

\$2,026.39

Driver:

unknown

Plate:

84357

Location of Accident:

Milwaukee, WI

Notification of Insurance Claim

Our investigation shows that the driver of a vehicle owned by the City Of Milwaukee is responsible for the accident involving our customer, Barbara Rucker.

Since our insured is not at fault, you will need to reimburse us for damages paid on this claim. If you have automobile insurance, please send this letter to your insurance company and ask them to contact me right away.

Thank you.

Sincerely,

Margaret Gauthier

Metropolitan Group Property and Casualty Insurance Company

Phone: 800-634-9740 Ext: 6036

Fax: 866-260-1164

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

MetLife Auto & Home® Subrogation - Warwick Mail Processing Center

PO Box 2204

Charlotte, NC 28241-2204

800-634-9740

MetLife®

04/02/2013

City Of Milwaukee Attn: Brian Field 2142 W Canal Street Milwaukee, WI 53233 RECEIVED

APR 12 2013

OFFICE OF CITYATTORNEY

Your Insured: City Of Milwaukee

Your Policy Number:

Your Claim Number: dol 03/07/2013

Our Customer: Barbara Rucker Our Claim Number: FRE56181 Date of Accident: 03/07/2013

Dear Brian Field:

We understand you are financially responsible for the above referenced loss. Our investigation of the accident has determined your driver was negligent and is therefore responsible for the damages we have paid to our insured. If you have insurance coverage, please provide us with your insurance information. Enclosed is our supporting documentation.

Property Damage

Collision or ACV:

\$1,776.39

Deductible:

\$250.00

Rental:

\$0.00

Other:

\$0.00

TOTAL:

\$2,026.39

Does Massachusetts Bailment Apply?

n/a

Kindly remit payment to: MetLife Auto & Home; P.O. Box 2204, Charlotte, NC 28241-2204 If you have any questions, please call us. Please include claim number FRE56181 on all payments.

Thank you.

Margaret Gauthier

Supervisor, Ext: 6036, Fax: 866-260-1164

Metropolitan Group Property and Casualty Insurance Company

		SCR MI	
LINE A	CLAIM# FRE56181 - 0 RISK STATE	PAGE BACK PG 01 LOSS DATE 0307130	
COL 0 11 BAR: COL 0 21 0899 COL 0 . 4 22 0899 COL 0 37 PRP: COL 0 98 COL 0 98 PDI 1 11 MILW	## CHK NO CR AMOUNT SUITS OD OC DC BARA A RUCK . 00000000 MF K9 . 4 005861542 . 00025000 MF K9 . T 028264621 MF K9 . DI J8 DI J8 PR A1 PR A1 PR A1 PR A1 DI J8 DI J8 DI J8 DI J8 PR A1 PR	CC DATE IMCC MC C 030713 C 031313 S C 031313 S C 031813 C 032813 C 032913 C 030713	KD OC YY K9 RD K7 RD K7 99 K9 MF K9 DI J8 CH A1 DI J8

RECEIVED

APR 12 2013

END OF DATA - HIT ENTER FOR SUM MTF SCREEN

OFFICE OF CITY ATTORNEY

Date: Estimate ID:

Profile ID:

3/13/2013 07:52 AM FRE56181 -- 1

Estimate Version:

0 Committed

MetLife

MetLife Auto & Home

P.O. Box 410200, Charlotte, NC 28241-9932 (800) 854-6011

RECEIVED

APR 12 2013

OFFICE OF **CITY ATTORNEY**

Field Adjuster: Chris Adey

Cell: 262-212-6750

VO: 1-800-854-6011 x 4775

Fax:1-855-413-3884

email: cadey@metlife.com

** All supplements need prior approval.

** All supplement materials need to be sent to field adjuster.

* By providing a copy of known damages this is not an acceptance of liability or a confirmation of coverage, or that a payment is to

Damage Assessed By: Christopher Adey

File Handler: Kim Chan FRARC

(800) 854-6011 ext. 5093

Condition Code: Good

Date of Loss: 3/7/2013 Custm Contct:

3/12/2013 Deductible: 500.00

Policy No: 087012083-2

Type of Loss: Collision

Assgn Date: 3/11/2013 Claim Number: FRE56181 -- 1

Insured: BARBARA RUCKER

Owner: BARBARA RUCKER

Address: 1302 N 46TH ST, MILWAUKEE, WI 53208

Telephone: Home Phone: (414) 935-9010

Contact Phone: (414) 935-9010

2.7L Inj 6 Cyl 2WD

1/05

License: WPV548 WI

Drive Train:

Mitchell Service: 917723

Description: 2005 Hyundai Santa Fe GLS Body Style:

4D Ut

Vehicle Production Date:

VIN: KM8SC13D75U963025

Mileage: 82,266

OEM/ALT:

Color:

Search Code: MESEWI Maroon

PASSENGER AIRBAG, DRIVER AIRBAG, POWER LOCK, POWER WINDOW, REAR WINDOW DEFOGGER MANUAL AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN, LUGGAGE RACK SKID PLATES, PREMIUM SOUND SYSTEM, ANTI-LOCK BRAKE SYS., TRACTION CONTROL FOG LIGHTS, ALUM/ALLOY WHEELS, LEATHER STEERING WHEEL, AUTOMATIC TRANSMISSION

TINTED GLASS, VARIABLE ASSISTED STEERING, SIDE AIRBAGS, ANTI-THEFT SYSTEM AM/FM STEREO CASSETTE/CD, FRONT BUCKET SEATS, KEYLESS ENTRY SYSTEM POWER DISC BRAKES, POWER HEATED EXTERIOR MIRRORS, REAR WINDOW WIPER

STEERING WHEEL MOUNTED CONTROLS

COPY OF ESTIMATE PROVIDED TO CUSTOMER

Line Entry

Labor Number Type

Operation

Line Item Description

Part Type/ Part Number

Dollar Amount

Labor Units

Front Bumper

ESTIMATE RECALL NUMBER: 03/13/2013 07:52:12 FRE56181 -- 1

Mitchell Data Version:

Software Version:

OEM: JAN_13_V MAPP:JAN_13_V

7.0.483

Copyright (C) 1994 - 2013 Mitchell International

All Rights Reserved

Page 1 of 4

					Estimate ID: Estimate Version:	FRE56181 1	
					Committed	U	
1	700005	BDY	REMOVE/INSTALL	Ert Dunner au A	Profile ID:	MetLife	
2	700007		REMOVE/REPLACE	Frt Bumper Assy	501 010420000 01	1.4 #	ŧ
3		BDY	CHECK/ADJUST	Frt Add w/Fog Lamps		0.3	
4	700008		REPAIR	Fog Lamps		0.4	
5		REF	REFINISH/REPAIR	Frt Bumper Cover	Existing	1.0*#	,
6			IND INISHIREPAIR	Frt Bumper Cover	5000,0000 03103 d	C 2.3*	
				MODIFIED REFINISH WITH FULL CLEAR COAT		0 2.3	
7	700038	BDY	REMOVE/INSTALL	Front Lamps			
8	700055			L Front Combination Lamp		INC #	
9	703290		REMOVE/INSTALL	R Side Marker Lamp			
	, 00200	וטטו	REMOVE/REPLACE	L Marker Lamp Assembly	** QUAL REPL PART	INC # 8.57 0.2 #	
10	700221	BDY	DEMOVE/INOTALL	Front Fender		0.57 0.2 #	
11	700227	BDY	REMOVE/INSTALL	L Fender Moulding		0.0	
12	100221		REPAIR	L Fender Panel	Existing	0.2	
13		REF	REFINISH/REPAIR	L Fender Panel		0.5*#	
14	700233	DDV		MODIFIED REFINISH WITH FULL CLEAR COAT		C 1.5*	
14	700233	BDY	REMOVE/REPLACE	L Fender Liner	** QUAL REPL PART	To and lighter.	
15	702240	DD)/		_ Wheel	QUAL NEFE PART	56.00 0.3	
16	703340	BDY	REMOVE/REPLACE	Alloy Wheel	Qual Recycled Part		
10				Line Markup %25.00	Qual Recycled Part	85.00 * 0.3	
47	701071		NAMES AND ADDRESS	Front Door		21.25	
17	701071	BDY	REPAIR	L Frt Door Repair Panel	Existing		
18		REF	REFINISH	L Frt Door Outside	Existing	5.0*#	
19	701886	REF	REFINISH	L Frt Door Moulding		C 2.2	
20	701075	BDY	REMOVE/INSTALL	L Frt Belt Moulding		C 0.8	
21	701077	BDY	REMOVE/INSTALL	L Frt Door Moulding		0.5 #	
22	701079	BDY	REMOVE/INSTALL	L Frt Door Mirror		0.2	
23	701175	BDY	REMOVE/INSTALL	L Frt Door Handle		INC	
				Rear Door		0.7 #	
24	702922	BDY	REMOVE/REPLACE	L Rear Door Moulding	racion serve		
25		REF	REFINISH	L Rear Door Moulding	87731-26500	141.56 0.3	
				Additional Costs & Materials		C 0.6	
26	936012		ADD'L COST	Hazardous Waste Disposal			
				ADDITIONAL OPERATIONS		3.00 *	
27		REF	ADD'L OPR	Clear Coat			
						2.1	
28			ADD'L COST	Additional Costs & Materials Paint/Materials			
						323.00 *	
29	900500	BDY *	REMOVE/REPLACE	MANUAL ENTRIES			
30	900500	MCH *	ADD'L LABOR OP	Restore corrosion protection	** QUAL REPL PART	5.00 * 0.3*	
31	900500	REF *	REMOVE/REPLACE	Align suspension	Sublet	69.95 * 0.0*	
32	900500	BDY *	REMOVE/REPLACE	Flex Additive	** QUAL REPL PART	5.00 * 0.0*	
33	900500	BDY *		Tape Stripe	** QUAL REPL PART	20.00 * 0.3*	
	230000	וטטו	ADD'L LABOR OP	Mount- Balance If wheel/tire	Sublet	25.00 + 0.3*	

^{* -} Judgment Item

BLUE OVAL SERVICE N15 W22180 WATERTOWN RD. WAUKESHA WI 53186 (414) 379-7547 (414) 520-4982

KEYSTONE AUTOMOTIVE 9532 W. CARMEN AVE. MILWAUKEE WI 53225 (800) 924-8230 (414) 463-1019

** 92303-26011 9

8.57

14 ** HY1248107

56.00

Sublet

Software Version:

7.0.483

Copyright (C) 1994 - 2013 Mitchell International All Rights Reserved

25.00 * 0.0*

Date:

3/13/2013 07:52 AM

^{# -} Labor Note Applies

^{**} QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

Date: 3/13/2013 07:52 AM

Estimate Version:

Estimate ID: FRE56181 -- 1

0 Committed

Profile ID: MetLife

Recycler Information Section:

LKQ - Smart Parts N 4079 Highway E Hustisford WI 53034 800-349-5850;630-563-4022

15 2006 Hyundai

Description: (16X6-1/2, 5 SPOKE ALLOY), (16X6-1/2, 5

WHEEL

\$WL690

VA

85.00

Disclaimer: The price indications on recycled parts are real or composite values, based on the pricing option selected with QRP. Prices are the latest available at time of inventory download and are subject to change and availability.

To determine actual repairer net or wholesale price, call the automotive recycler of your choice.

Certain parts located for this quote are interchangeable but are not an exact match. Call the automotive recycler of your choice.

Prior Damage: minor dings

Estimate Totals

l.	Labor Subtotals Body Refinish Mechanical	Units 11.9 9.5 0.0 Taxable La		0	or	Sublet Amount 25.00 0.00 69.95	Totals 667.60 513.00 69.95 1,250.55 70.03	T T T	II.a	Part Replacement Summary Taxable Parts Parts Adjustments Sales Tax Total Replacement Parts Amount	@	5.600%	Amount 321.13 21.25 19.17 361.55
	Labor Summary	21.4					1,320.58						
III.	Additional Costs Taxable Costs Total Additional Paint Material M Init Rate = 34.00	lethod: Rates	ours = 99.9	@ , Addl F	5.60 Rate = 0.		Amount 326.00 18.26 344.26		IV.	Adjustments Insurance Deductible Customer Responsibility			Amount 500.00-
									I. II. III.	Total Labor: Total Replacement Parts: Total Additional Costs: Gross Total:			1,320.58 361.55 344.26 2,026.39
									IV.	Total Adjustments: Net Total:			500.00- 1,526.39

ESTIMATE RECALL NUMBER: 03/13/2013 07:52:12 FRE56181 -- 1

Mitchell Data Version:

Software Version:

OEM: JAN 13 V MAPP:JAN_13_V

7.0.483

Copyright (C) 1994 - 2013 Mitchell International All Rights Reserved

Page 3 of 4

3/13/2013 07:52 AM

Estimate ID: FRE56181 -- 1 Estimate Version: Committed

Profile ID: MetLife

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Point(s) of Impact

9 Left Side (P), 10 Left Front Side (S), 11 Left Front Corner (S)

Clmnt. Ins Co: MetLife

Inspection Site: BARBARA RUCKER

Address: 1302 N 46TH ST

MILWAUKEE, WI 53208-2741

(414) 447-7908 (414) 447-7908

Inspection Date: 3/12/2013

Body Shop: UNKNOWN-OWNER TO PRESENT

Address: A COPY OF THIS ESTIMATE TO

SHOP OF CHOICE

FAILURE TO PRESENT THIS ESTIMATE TO REPAIRER MAY RESULT IN ADDITIONAL EXPENSE TO YOU.

THESE REPAIRS SHOULD BE COMPLETED IN ACCORDANCE WITH I-CAR OR TECH-COR PROCEDURES.

NO SUPPLEMENTS WILL BE HONORED WITHOUT PRIOR AUTHORIZATION FROM A METLIFE AUTO AND HOME REPRESENTATIVE. DIRECTION TO PAY REQUIRED.

" The glass part price, kit and labor contained in this estimate have been calculated based on market pricing including markup for your area. The MetLife Auto & Home glass administrator is Safelite Auto Glass. Please contact Safelite Auto Glass at 888-800-4527 if you would like to arrange for them to complete the work.

Your complete customer satisfaction is our goal at MetLife Auto & Home please remember that you have the right ro select a repair facility or contractor of your choice. If you have not already chosen a shop or contractor or have no preferenve, we will be happy to refer you to a vendor in your area.

All information stored, transmitted, received, or contained in MetLife's systems is MetLife's sole property and may be accessed and decrypted by MetLife at any time and may be disclosed to appropriate third parties.

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911


ESTIMATE RECALL NUMBER: 03/13/2013 07:52:12 FRE56181 -- 1

Mitchell Data Version: Software Version:

OEM: JAN_13_V MAPP:JAN 13 V

7.0.483


Copyright (C) 1994 - 2013 Mitchell International All Rights Reserved



P3120001.jpg Mar-12-2013 04:23p




P3120002.jpg Mar-12-2013 04:23p



P3120003.jpg Mar-12-2013 04:23p




P3120004.jpg Mar-12-2013 04:23p



P3120005.jpg Mar-12-2013 04:24p




P3120006.jpg Mar-12-2013 04:24p



P3120008.jpg Mar-12-2013 04:24p




P3120009.jpg Mar-12-2013 04:24p



P3120010.jpg Mar-12-2013 04:25p




P3120011.jpg Mar-12-2013 04:25p



P3120012.jpg Mar-12-2013 04:25p




P3120013.jpg Mar-12-2013 04:25p



P3120014.jpg Mar-12-2013 04:25p



P3120015.jpg Mar-12-2013 04:26p



P3120016.jpg Mar-12-2013 04:26p




P3120017.jpg Mar-12-2013 04:26p



P3120018.jpg Mar-12-2013 04:26p




P3120019.jpg Mar-12-2013 04:27p




P3120020.jpg Mar-12-2013 04:27p



P3120021.jpg Mar-12-2013 04:27p



P3120022.jpg Mar-12-2013 04:27p



P3120023.jpg Mar-12-2013 04:27p



P3120024.jpg Mar-12-2013 04:27p



P3120025.jpg Mar-12-2013 04:28p