

## Certificate of Appropriateness—Amended

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

**Property** 

3002 W. STATE ST. Concordia Historic District

**Description of work** Replace windows on all three sides of second story sleeping porch with all-wood simulacra of surviving original windows on the rest of the house per attached specs. Windows to be Marvin Ultimate Wood double hung 1/1 sash with black perimeter bars and wood exterior screens. New window bands will be placed into existing openings.

**Date issued** 

7/18/2017

PTS ID 114289 COA: Replace sleeping porch windows

CCF # 170306

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

Any Low-E coating on the windows must be clear and untinted and meet Wisconsin Historical Society light transmission requirements.

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Tim Askin of the Historic Preservation staff as follows:

Phone: (414) 286-5712 E-mail: HPC@milwaukee.gov.

If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, www.milwaukee.gov/build, or call (414) 286-8210.

City of Milwaukee Historic Preservation Staff

m auss

Copies to: Development Center, Ald. Robert Bauman, Contractor






Present conditions: front

Present conditions: rear






Sleeping porch exterior details





Sleeping porch interior. Some windows are boarded up on both interior and exterior. These are typical existing windows that are clearly not original to the building

## Built around you."



As Viewed From The Exterior

Entered As: FS

**MO** 123 1/8" X 58 9/16"

**FS** 120" X 57"

**OC** 122 5/8" X 58 5/16"


**RO** 121" X 57 1/2"

Egress Information A1, A2, A3, A4, A5

Width: 20 7/16" Height: 22 1/4"

Net Clear Opening: 3.16 SqFt

Band of 5 windows for north wall



As Viewed From The Exterior

Entered As: FS

MO 99 1/8" X 58 9/16"

**FS** 96" X 57"

OC 98 5/8" X 58 5/16"

RO 97" X 57 1/2"

Egress Information A1, A2, A3, A4

Width: 20 7/16" Height: 22 1/4"

Net Clear Opening: 3.16 SqFt

Band of four windows for east and west walls.