



# Certificate of Appropriateness

Milwaukee Historic Preservation Commission/200 E. Wells Street/Milwaukee, WI 53202/phone 414-286-5712/fax 414-286-3004

**Property** 910 N. OLD WORLD THIRD ST. Second Ward Savings Bank  
**Description of work** Replace eleven heavily rusted window well grates around on east and west facades of building. New grates will be similar to existing in shape and grate pattern, but be made of stainless steel so as to resist future deterioration better than the existing grates. Frames and fasteners for these grates will also be replaced.  
**Date issued** 10/3/2017 PTS ID 114400 COA: replace window well grates

In accordance with the provisions of Section 320-21 (11) and (12) of the Milwaukee Code of Ordinances, the Milwaukee Historic Preservation Commission has issued a certificate of appropriateness for the work listed above. The work was found to be consistent with preservation guidelines. The following conditions apply to this certificate of appropriateness:

N/A

All work must be done in a craftsman-like manner, and must be completed within one year of the date this certificate was issued. Staff must approve any changes or additions to this certificate before work begins. Work that is not completed in accordance with this certificate may be subject to correction orders or citations. If you require technical assistance, please contact Historic Preservation staff as follows: Phone: (414) 286-5712 E-mail: HPC@milwaukee.gov.


If permits are required, you are responsible for obtaining them from the Milwaukee Development Center. If you have questions about permit requirements, please consult the Development Center's web site, [www.milwaukee.gov/build](http://www.milwaukee.gov/build), or call (414) 286-8210.

City of Milwaukee Historic Preservation Staff

Copies to: Development Center, Ald. Robert Bauman, Contractor

North  
is up

MCHS 16-118  
GROUND LEVEL PLAN  
AREA WELLS  
NTS  
KEYED AREA WELLS  
Note with grates, others concrete capped



Location diagram . The center two grates at the right of the image (3 & 4) along Kilbourn will not be replaced.



Typical existing grate.