January 23, 2009

Ronald D. Leonhardt Milwaukee City Clerk City Hall 200 E. Wells Street, Room 205 Milwaukee, WI 53202 CITY OF MILWAUKEE 2009 JAN 29 AM 1: 05

RONALD D. LEONHARD)
CITY CLERK

RE: Jason Woll

C.I. File No: 08-S-690

Mr. Leonhardt,

I am writing to appeal a decision of a claim that I made with the City of Milwaukee, with regards to damaged to my truck that was received while being towed by the City of Milwaukee. I am making a request to receive a hearing to further pursue this issue.

I received a letter of denial on January 20, 2009, that states that my claim was being denied, and the City of Milwaukee will not accept liability. In the letter it states that my truck has scratches and damage all over the passenger and driver side of the vehicle. The only damage that is in question is the damage to the rear driver side of the vehicle, near the bumper. The damage to the passenger side of the vehicle was sustained during a traffic accident, where a woman illegally ran a red light and struck my car. This damage has already been paid for and repaired by her insurance company.

The claim that I made with the City of Milwaukee was about damage sustained when my car was towed by the city of Milwaukee on June 11, 2008. The damage was received while my vehicle was in tow to the City of Milwaukee towing lot. Therefore the damage would be on the intake video at the towing lot. The damage was not there previous to my vehicle being towed would again like continue to pursue my claim against the City of Milwaukee by appealing the decision and request a hearing.

Sincerely,

Jason Woll

817 E Brady St. Apt. # 1

Milwaukee, Wisconsin 53202

(971) 645-6631

Wolli@msoe.edu

Monday, October 6, 2008

2008 OCT -6 PM 1:53

RONALD D. LEONHARD:
CITY CLERK

Sity Glerk ATTN: Glaims 200 E, Wells St. Room 205 Milwaukee, WI 53202-3567

My name is Jason Woll, I am making a claim against the city of Milwaukee for damages to my 2002 blue Chevrolet Silverado, that occurred on 6/11/08. My vehicle was towed by the city of Milwaukee on 6/11/08. After picking my car up from the Milwaukee tow lot I returned home. Upon my arrival home I noticed a large scratch on the rear driver side of the truck bed. The scratch in question had not previously existed prior to my vehicle being towed. As soon as I noticed the scratch I called the Milwaukee tow lot for further instruction on processing a claim with regards to the scratch. I was then instructed to return to the Milwaukee tow lot to fill out a claim. I then returned directly to the tow lot, and proceeded to file a claim.

The estimates for repairs were \$916.59, and \$873.43. The first estimates for the repair of the damages were received from certified estimators. The estimates were obtained from the Amato collision center, 5200 N Port Washington road Glendale, Wisconsin 53217. They can be contacted at 414-964-4400. The second estimate was performed by Steve Italiano, customer service manager, ASE certified, of Amato Collision Center. The second estimate was received from Andrew Automotive, 1621 W. LaSalle St. Milwaukee, WI 53209. The phone number is 414-540-2559. The estimate was carried out by David Maertz, assistant body shop manager, and certified estimator, of Andrew Automotive.

The amount that I am request is \$900.00 to cover the damages. This will cover all of the damages attained while being towed by the city of Milwaukee, and is within the two estimates received.

Thank you,

Jason Woll

(971) 645-6631

SITE Brady St Apt #1_

Milwanker. Wi. 53202

OFFICE OF

CITY OF MILWAUKEE

AMATO COLLISION CENTER 5200 N PORT WASHINGTON ROAD GLENDALE, WISCONSIN 53217

OFFICE: 414-964-4400 FAX: 414-964-1433

CD LOG NO 10507-1 DATE 09/30/08

SHOP: AMATO COLLISION CENTER EAST INSP DATE: ADDRESS: 5200 N. PORT WASHINGTON RD. CONTACT: 09/30/08

STEVE ITALIANO · PHONE 1: (414)964-4400 CITY STATE: GLENDALE, WI

(414) 964-1433 53217-FAX: ZIP:

CELL PHONE: (971)645-6631

OWNER: WOLL, JASON ADDRESS: 817 E BRADY ST

CITY STATE: MILWAUKEE, WI ZIP: 53202

POINT OF IMPACT: 0

VIN: LIC#: YSY-405 STATE: OR 1GCEK19T22E125882

MILEAGE: BODY COLOR: BLUE

ACCTNG CTL#: CONDITION:

E=REPLACE OEM *=USER-ENTERED VALUE NG=REPLACE NAGS UC=RECONDITIONED PRT

EP=REPLACE PXN

EC=REPLACE ECONOMY

UE=REPLACE OE SURPLUS

UM=REMAN/REBUILT PRT

OE=REPLACE PXN OE SRPLS

PC=PXN RECONDITIONED PM=PXN REMAN/REBUILT

ET=PARTL REPL LABOR IT=PARTIAL REPAIR TE=PARTL REPL PRICE BR=BLEND REFINISH I=REPAIR L=REFINISH

SB=SUBLET CG=CHIPGUARD TT=TWO-TONE RI=R&I ASSEMBLY RP=RELATED PRIOR P=CHECK N=ADDITIONAL LABOR

UP=UNRELATED PRIOR AA=APPEAR ALLOWANCE

2002 CHEVROLET SILVERADO K1500 LT 4DOOR EXT CAB 8CYL GASOLINE 5.3

CODE: U8033D/D OPTNS T/24XKOAJPDWHTUCR

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

4-WHEEL DRIVE POWER FRONT SEATS HEATED FRONT SEATS .

HEATED REMOTE CONTROL MIRRORS

POWER WINDOWS REMOTE KEYLESS ENTRY SYSTEM

LEFT REAR ACCESS DOOR POWER DOOR LOCKS

AIR CONDITIONING HEATED BACK GLASS CRUISE CONTROL AUTOMATIC TRANS

OVERHEAD CONSOLE

OP GDE MC DESCRIPTION	MFG.PART NO.	PRICE	AJ% B%	HOURS R
I 0497 PANEL, BEDSIDE	LT REPAIR			3.0*1
L 0497 13 PANEL, BEDSIDE	LT REFINISH			4.3 4
E 0350 DECAL, BEDSIDE PANEL	LT 15779676 GM PART	13.21		0.3 1
E 0438 FLARE, WHEEL OPENING	G LT 10374844 GM PART	123.70		0.5 1

2002 CHEVROLET SILVERADO K1500 LT 4DOOR EXT CAB CD LOG NO 10507-1

E 0533 TAILLAMP ASSEMBLY LT 19169017 GM PART 131.48 0.3 1 L M14 CORROSION PROTECTION REFINISH 0.3*4

6 ITEMS

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS PAINT MATERIAL PARTS & MATERIAL TOTAL TAX ON PARTS & MATERIAL	<u>@</u>	·	5.600%	268.39 147.20 415.59 23.27
LABOR 1-SHEET METAL 2-MECH/ELEC 3-FRAME	RATE 52.00 98.00 52.00	REPLACE HRS 1.1	REPAIR HRS 3.0	213.20
4-REFINISH 5-PAINT MATERIAL	52.00 32.00	4.6		239.20
LABOR TOTAL TAX ON LABOR SUBLET REPAIRS TOWING STORAGE		<u>@</u>	5.600%	452.40 25.33
GROSS TOTAL				916.59
NET TOTAL				916.59

SHOPLINK U7008 ES CD LOG 10507-1 DATE 09/30/08 12:39:43AM R6.37 CD 09/08 PXN: Y/00/00/00/00 CUM 00/00/00/00 GEOCODE 53217 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

1.2 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE

MANUFACTURER OF YOUR MOTOR VEHICLE.

ANDREW AUTOMOTIVE - BODY REPAIR CENTER

1621 W. LA SALLE ST.

MILWAUKEE, WI 53209

PH: 414-540-2559 FX: 414-228-7420

CD LOG NO 18872-1 DATE 09/30/08

SHOP:

ANDREW AUTO BODY REPAIR

INSP DATE:

09/30/08

ADDRESS: 1621 W. LASALLE ST.

CONTACT: PHONE 1:

DAVID MAERTZ (414)540-2559

CITY STATE: GLENDALE, WI ZIP:

53209-

FAX:

(414)228-7420

OWNER:

WOLL, JASON

POINT OF IMPACT: 7

LIC#:

STATE:

VIN:

1GCEK19T22E125882

BODY COLOR: BLUE

CONDITION: EXCELLENT

MILEAGE:

ACCTNG CTL#:

*=USER-ENTERED VALUE

I=REPAIR

TT=TWO-TONE

N=ADDITIONAL LABOR AA=APPEAR ALLOWANCE E=REPLACE OEM

EC=REPLACE ECONOMY

UE=REPLACE OE SURPLUS

UM=REMAN/REBUILT PRT

EU=REPLACE SALVAGE

OE=REPLACE PXN OE SRPLS

PC=PXN RECONDITIONED

TE=PARTL REPL PRICE

ET=PARTL REPL LABOR

L=REFINISH

CG=CHIPGUARD

RI=R&I ASSEMBLY

RP=RELATED PRIOR

NG=REPLACE NAGS

UC=RECONDITIONED PRT

EP=REPLACE PXN

PM=PXN REMAN/REBUILT
IT=PARTIAL REPAIR
BR=BLEND REFINISH

SB=SUBLET

P=CHECK

UP=UNRELATED PRIOR

2002 CHEVROLET SILVERADO K1500 LS 4DOOR EXT CAB 8CYL GASOLINE 5.3

CODE: U8033C/D OPTNS T/24XDJPQWTUCR

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES

4-WHEEL DRIVE REMOTE KEYLESS ENTRY SYSTEM

ELEC REMOTE CONTROL MIRRORS

AIR CONDITIONING CRUISE CONTROL

TWO-STAGE - INTERIOR SURFACES

POWER DOOR LOCKS

POWER WINDOWS

LEFT REAR ACCESS DOOR

AUTOMATIC TRANS OVERHEAD CONSOLE

OP GDE	MC DESCRIPTION		MFG.PART NO.	PRICE	AJ% B%	HOURS R
I 0497	PANEL, BEDSIDE	LT	REPAIR			4.0*1
L 0497	13 PANEL, BEDSIDE	LT	REFINISH			4.8 4
E 0350	DECAL, BEDSIDE PANEL	LT	15779676 GM PART	13.21		0.3 1
E 0438	FLARE, WHEEL OPENING			123.70		0.5 1
RI0533	•		R&I ASSEMBLY			0.3 1
L M17	COVER CAR EXTERIOR		REFINISH			0.2*4
SBM60	HAZARD, WSTE, REM.		SUBLET REPAIR	5.00*		1
7 IT	EMS					

2002 CHEVROLET SILVERADO K1500 LS 4DOOR EXT CAB CD LOG NO 18872-1

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS PAINT MATERIAL PARTS & MATERIAL TOTAL TAX ON PARTS & MATERIAL			5.600%	136.91 160.00 296.91 16.63
LABOR .	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	52.00 98.00	1.1	4.0	265.20
2-MECH/ELEC 3-FRAME	52.00			
4-REFINISH	52.00	5.0		260.00
5-PAINT MATERIAL	32.00			E0# 00
LABOR TOTAL				525.20
TAX ON LABOR		e e	5.6.00%	29.41
SUBLET REPAIRS		_		5.00
TAX ON SUBLET		@	5.600%	0.28
TOWING STORAGE				
SIORAGE				
GROSS TOTAL	,			873.43
NET TOTAL				873.43

SHOPLINK UG202 ES CD LOG 18872-1 DATE 09/30/08 12:19:12AM R6.37 CD 09/08 PXN: Y/00/00/00/00 CUM 00/00/00/00 GEOCODE 53209 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

1.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

ANDREW AUTOMOTIVE - BODY REPAIR CENTER

1621.W. LA SALLE ST.

MILWAUKEE, WI 53209

PH: 414-540-2559 FX: 414-228-7420

CD LOG NO 18872-1 DATE 09/30/08

SHOP: ANDREW AUTO BODY REPAIR INSP DATE:

ADDRESS: 1621 W. LASALLE ST.

CITY STATE: GLENDALE, WI

ZIP: 53209-

09/30/08

CONTACT: DAVID MAERTZ

PHONE 1:

MILEAGE:

(414)540-2559

FAX:

(414)228-7420

OWNER:

WOLL, JASON

POINT OF IMPACT: 7

LIC#: STATE:

VIN:

1GCEK19T22E125882

BODY COLOR: BLUE

CONDITION: EXCELLENT ACCTNG CTL#:

*=USER-ENTERED VALUE E=REPLACE OEM

EC=REPLACE ECONOMY

UE=REPLACE OE SURPLUS

UM=REMAN/REBUILT PRT

OE=REPLACE PXN OE SRPLS

PC=PXN RECONDITIONED

TE=PARTL REPL PRICE

ET=PARTL REPL LABOR

I=REPAIR TT=TWO-TONE

N=ADDITIONAL LABOR

AA=APPEAR ALLOWANCE RP=RELATED PRIOR

L=REFINISH CG=CHIPGUARD

RI=R&I ASSEMBLY

NG=REPLACE NAGS
UC=RECONDITIONED PRT
EP=REPLACE PXN
PM=PXN REMAN/REBUILT
IT=PARTIAL REPAIR
BR=BLEND REFINISH

SB=SUBLET

P=CHECK

UP=UNRELATED PRIOR

2002 CHEVROLET SILVERADO K1500 LS 4DOOR EXT CAB 8CYL GASOLINE 5.3

CODE: U8033C/D OPTNS T/24XDJPOWTUCR

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

4-WHEEL DRIVE POWER DOOR LOCKS

REMOTE KEYLESS ENTRY SYSTEM POWER WINDOWS

LEFT REAR ACCESS DOOR ELEC REMOTE CONTROL MIRRORS

AIR CONDITIONING AUTOMATIC TRANS

CRUISE CONTROL OVERHEAD CONSOLE

OP GDE M	C DESCRIPTION		MFG.PART NO.	PRICE	AJ% B%	HOURS R
					-	
I 0497	PANEL, BEDSIDE	LT	REPAIR			4.0*1
ь 0497 13	PANEL, BEDSIDE	LT	REFINISH			4.8 4
E 0350	DECAL, BEDSIDE PANEL	LT	15779676 GM PART	13.21		0.3 1
E 0438	FLARE, WHEEL OPENING	$\mathtt{L}\mathtt{T}$	10374844 GM PART	123.70		0.5 1
RI0533	TAILLAMP ASSEMBLY	LT	R&I ASSEMBLY			0.3 1
L M17	COVER CAR EXTERIOR		REFINISH			0.2*4
SBM60	HAZARD. WSTE. REM.		SUBLET REPAIR	5.00*		1
7 ITEM	S					·

2002 CHEVROLET SILVERADO K1500 LS 4DOOR EXT CAB CD LOG NO 18872-1

MC MESSAGE(S)
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES GROSS PARTS PAINT MATERIAL PARTS & MATERIAL TOTAL TAX ON PARTS & MATERIAL			5.600%	136.91 160.00 296.91 16.63
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	52.00	1.1	4.0	265.20
2-MECH/ELEC	98.00			
3-FRAME	52.00	•		
4-REFINISH	52.00	5.0	•	260.00
5-PAINT MATERIAL	32.00			
LABOR TOTAL				525.20
TAX ON LABOR		@	5.600%	29.41
SUBLET REPAIRS				5.00
TAX ON SUBLET		<u>e</u>	5.600%	0.28
TOWING		•		
STORAGE				
GROSS TOTAL .				873.43

SHOPLINK UG202 ES CD LOG 18872-1 DATE 09/30/08 12:19:12AM R6.37 CD 09/08 PXN: Y/00/00/00/00 CUM 00/00/00/00 GEOCODE 53209 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

NET TOTAL

1.3 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.


873.43


City of Milwaukee Tow Lot


COMPLAINT AND INVESTIGATION FORM

-CITY USE ONLY-	-CUSTOMER INFORMATION-
TOW#: 1358558	NAME: _ ASON WOLL
DATE: 6-11-08	ADDRESS: 817 & Brady st Apt #1
CLERK ID: KB 18	
OLLIN ID.	PHONE #: 971-645-6631
PHOTOS TAKEN Q YES NO	DATE FILED: 6-11-08
PHOTOS ATTACHED DYES KNO	· · · · · · · · · · · · · · · · · · ·
ALL FORMS COMPLETED YES ON	IO TO TO THE TOTAL TOTAL TO THE TOTAL TO THE TOTAL TO THE TOTAL TOTAL TOTAL TO THE TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TO THE TOTAL TOT
	***Complaint must be signed by citizen completing form.
CITI	ZEN'S STATEMENT
I picked up m	sehicle and left. When
I returned none	I noticed that the
rear driver side	part of The truck hed
Tow lot as son	I then returned to the
1000 10+ as 5051	as I noticed The damage.
	· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·
2	
Marin Od	6/11/08
***SIGNATURE	PATE

CIRCLE AREAS OF DAMAGES USING THE DIAGRAMS BELOW







Fo file a claim for *DAMAGE TO or THEFT FROM* your vehicle, Write a detailed letter and send to:

CITY CLERK'S OFFICE,

200 EAST WELLS STREET

CITY HALL, ROOM 205

MILWAUKEE, WI 53202

414-286-2221

<i>-CITY USE ONLY-</i> INVESIGATION RESULTS				
ROUTE TO:	□ D.	LAWRENCE	L. BLACK	☐ RETURN TO LINDA
		<u>. </u>		
	,			
		·		
SIGNATURE:				DATE:

City of Milwaukee Tow Lot Workstation ID : towlotren84
Drawer ID : TOWLOTREGG4
Workstation No. : 31873
Drawer Session No. : 40264
Receipt Number : 1973641

Receipt Number : 1973641
Payment Date : 12:28 PM
Item Description : Tow
Issue # : 1336558
Amount Due : \$95.98
Amount Paid : \$95.98
Balance Due : \$95.98

Paid by : CREDIT \$95.88 Amount Daid : \$95.88 Amount Faid : \$95.88 Amount Tendered : \$95.88 Cashier ID : YOUNG

Thank You For Your Payment

SMILWRUKEE TOW LOT 3 1 LASST LINCOLN AVE-MITMANKEE, UT \$334 TOTAL

\$95.00

JASON S WOLL

I AGREE TO PAY ABOUE TOTAL AMOUNT ACCORDING TO CARD ISSUER AGREEMENT (MERCHANT AGREENENT IF CREDIT UDICHER)

CUSTONER COPY