

Adolph Logemann Residence

2837 East Park Place



Rear of 2837 East Park Place



Southwest Corner

Removal of rear chimney, standing seam roof, rear door, and vertical siding



Southeast Corner

No Changes



Southeast Corner - No Changes



Rear of Home



Rear of Home



Impacted Chimney



Interior Kitchen Windows

- Windows are in a grid pattern, inconsistent with the rest of the windows in the house.



West side of the house.

Interior Kitchen Windows



South Kitchen Window

