

Mitchell Street Development Opportunity Corp ( MSDOC) Submittal to:

Historic Preservation Committee – City of Milwaukee

The Modjeska Theater Building on Historic Mitchell Street in Milwaukee, WI

Façade Maintenance and Repair of Exterior Brick & Terra Cotta

May 23<sup>rd</sup>, 2018



Overview of picture on page 1 and 2



West side of Modjeska Theater exit area.


Example of repaired grout line on left. Sideways arrow designates continuation of stabilization. Boxed area shows general repairs.



West side Façade and exit doorway. Grout patch and tile stabilization. Arrows pointing to work areas where patch and hold was needed.







Close up and  
Distant view of  
Cornice and brick  
repairs on  
West face of build-  
ing at second floor.



