



METROPOLITAN

MOTORS INC.



MAY 8, 2009

CITY OF MILWAUKEE
MILWAUKEE CITY CLERK
200 EAST WELLS STREET ROOM 205
MILWAUKEE, WI 53202

REF: METROPOLITAN MOTORS, INC.
C.I. FILE NO. 08-V-266-1

DEAR CITY CLERK:

I WISH TO APPEAL THIS DECISION.

SINCERELY,

MAX STEPHENSON
OWNER

CITY OF MILWAUKEE
RECEIVED
2009 MAY 11 PM 4:06
CITY ATTORNEY

CITY OF MILWAUKEE
2009 MAY 11 AM 9:47
RONALD D. LEONHARDT
CITY CLERK



METROPOLITAN MOTORS INC.



01/14/2009

City Clerks Office:

I Max Stephenson, owner of Metropolitan Motors Inc. 10221 W. Arthur Ave. West Allis, WI 53227, phone #414-327-1400, requests to be added as the contact person for claim #08-V-266. I am the owner of the vehicle in claim #08-V-266.

Sincerely

Max Stephenson

CITY OF MILWAUKEE
RECEIVED
2009 JAN 14 PM 4:01
OFFICE OF
CITY ATTORNEY

CITY OF MILWAUKEE
2009 JAN 14 AM 11:52
RONALD D. LEONHARDT
CITY CLERK

Fascimile Cover Sheet

For:



METROPOLITAN

MOTORS INC.

10221 W. Arthur Ave. • P.O. Box 27384
West Allis, Wisconsin 53227
(414) 327-1400
Fax (414) 546-5492
www.metropolitancadillacsaab.com



10221 W Arthur Ave, West Allis, WI 53227

PHONE: 414-327-1400

FAX: 414-546-5492

DATE: ✓ 14 / 2009

TO: LINDA

FROM: MAX Stephenson

NUMBER OF PAGES TO FOLLOW: 1

MESSAGE: PLEASE GIVE MAX STEPHENSON A CALL

IF THERE ARE ONLY PROBLEMS-

CITY OF MILWAUKEE

08 DEC 29 AM 11:02

RONALD D. LEONHARDT
CITY CLERK

December 20th 2008

Dear City Clerk,

I Live at 4579 North 26th

On December 19th we had a snow storm. That night the city plow trucks came through our streets late around 2 AM. I was parked in front of my house which would be 26th Street.

In the morning around 8:15 AM we went out to shovel around my vehicle. I then noticed it was hit on the rear left corner panel back light was off on the ground. Dents & scratches were on the vehicle. The neighbors were out.

cleaning there sidewalks & streets. One neighbor came and let us know he ~~seen~~ the city plow ~~hit~~ ^(my) the vehicle ^{the night of the 19th Friday} and kept going.

I then went to the yard to let them know what happened. ^{Gentleman that worked there} He went out to look at the vehicle. And ^{so they would pay for it.} ~~said~~ he suggested we write this

letter, take pictures, and get an estimate and send it to the city for a claim. He said it should take up to 2 months for payment.

The vehicle is a demonstrator for the company Metropolitan Motors in West Allis, Wisconsin. You can call Terri Gonzales at (414) 327-1400. work #.

OFFICE OF THE
CITY ATTORNEY

2008 DEC 29 PM 3:42


CITY OF MILWAUKEE
RECEIVED

I am sending you the estimates. our bodyshop
GIVE. And also pictures of the ~~vehicle~~ Damage on
the Vehicle.

Vehicle info: 2005 ~~SAB~~ 9-3 TOTAL amount. \$2,240.21

please contact Terri Gonzales at metropolitan
motors at # (414) 327-1400 in the F&I Department.

Thank you,



Terri L. Gonzales

METROPOLITAN CADILLAC, INC.
10221 WEST ARTHUR AVENUE
WEST ALLIS, WI 53227
PHONE: (414) 327-1400 FAX: (414) 546-5490

CD LOG NO 9198-1 DATE 12/22/08

SHOP: METROPOLITAN CADILLAC INSP DATE: 12/22/08
CITY STATE: , WI CONTACT: DAN "BUD" TAORMINA
OWNER: GONZALES, TERRY
POINT OF IMPACT: 8

LIC#: 4BQ STATE: WI VIN: YS3FB49SX51018726
BODY COLOR: TAN MILEAGE: 26,776
CONDITION: ACCTNG CTL#:
PROD.DATE: 10/04 PAINT CODE:

*=USER-ENTERED VALUE	E=REPLACE OEM	NG=REPLACE NAGS
EC=REPLACE ECONOMY	UE=REPLACE OE SURPLUS	UC=RECONDITIONED PRT
UM=REMAN/REBUILT PRT	EU=REPLACE SALVAGE	EP=REPLACE PXN
OE=REPLACE PXN OE SRPLS	PC=PXN RECONDITIONED	PM=PXN REMAN/REBUILT
TE=PARTL REPL PRICE	ET=PARTL REPL LABOR	IT=PARTIAL REPAIR
I=REPAIR	L=REFINISH	BR=BLEND REFINISH
TT=TWO-TONE	CG=CHIPGUARD	SB=SUBLET
N=ADDITIONAL LABOR	RI=R&I ASSEMBLY	P=CHECK
AA=APPEAR ALLOWANCE	RP=RELATED PRIOR	UP=UNRELATED PRIOR

ESTIMATE FOR VISIBLE DAMAGE ONLY...ADDL DAMAGE POSSIBLE

2005 SAAB 9-3 LINEAR 4DOOR SEDAN 4CYL GASOLINE TURBO 2.0
CODE: L2174A/C OPTNS A/24GDS

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES	TWO-STAGE - INTERIOR SURFACES
BUMPER COVER MOUNTED FOG LAMPS	AUTOMATIC TRANS
AUTO TRNS W/MAN SELECT SWITCH	

OP	GDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	B%	HOURS	R
IT0629			PANEL, QUARTER	LT LABOR/PARTL REPAI				7.0	1
L 0629			PANEL, QUARTER	LT REFINISH				2.8	4
				2.3 SURFACE					
				0.5 TWO STAGE					
BR0479	13	LID, REAR DECK		BLEND REFINISH				2.2	4
				1.1 BLEND					
				0.6 TWO STAGE SETUP					
				0.5 TWO STAGE					
RI0014			PNL, LID FINISH	R&I ASSEMBLY				0.6	1
E 0204			N/PLATE, DECK LID	12791512	26.00			0.2	1

2005 SAAB 9-3 LINEAR 4DOOR SEDAN
CD LOG NO 9198-1

E 0495	N/PLATE, DECK LID	12785873	24.00	0.2	1
RI0524	EMBLEM, DECK LID	R&I ASSEMBLY		0.2	1
RI0490	HANDLE, DECK LID	R&I ASSEMBLY		0.2	1
RI1156	FRAME, LICENSE PLATE	R&I ASSEMBLY		0.2	1
E 0533	TAILLAMP ASSEMBLY, O LT	12777312	201.00	INC	1
RI0535	TAILLAMP ASSEMBLY, I LT	R&I ASSEMBLY		0.2	1
RI0536	TAILLAMP ASSEMBLY, I RT	R&I ASSEMBLY		0.2	1
E 0565	COVER, REAR BUMPER	12798001	498.21*	1.9	1
L 0565	COVER, REAR BUMPER	REFINISH		3.1	4
		2.6 SURFACE			
		0.5 TWO STAGE			
E 0115	MLDG, REAR BUMPER COVER	12788004	42.00	INC	1
E 0888	MLDG, REAR BUMPER CO LT	12788006	19.00	INC	1
ECM03	FLEX ADDITIVE	ECONOMY PART	5.00*		4
I M14	CORROSION PROTECTION	REPAIR	*	0.3*	4*
ECM17	COVER CAR EXTERIOR	ECONOMY PART	10.00*		4*
SBM60	HAZARD. WSTE. REM.	SUBLET REPAIR	3.00*		1*
N	MASK JAMBS	ADDNL LABOR OPERA		0.4*	1*

21 ITEMS

MC MESSAGE(S)

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS					810.21
OTHER PARTS					15.00
PAINT MATERIAL					268.80
PARTS & MATERIAL TOTAL					1,094.01
TAX ON PARTS & MATERIAL @			5.600%		61.26
LABOR	RATE	REPLACE HRS	REPAIR HRS		
1-SHEET METAL	52.00	3.9	7.4		587.60
2-MECH/ELEC	90.00				
3-FRAME	52.00				
4-REFINISH	52.00	8.1	0.3		436.80
5-PAINT MATERIAL	32.00				
LABOR TOTAL					1,024.40
TAX ON LABOR		@	5.600%		57.37
SUBLET REPAIRS					3.00
TAX ON SUBLET		@	5.600%		0.17
TOWING					
STORAGE					

GROSS TOTAL 2,240.21

NET TOTAL 2,240.21

SHOPLINK U1486 ES CD LOG 9198-1 DATE 12/22/08 09:51:07AM R6.37 CD 11/08

PXN: Y/00/00/00/00/00 CUM 00/00/00/00/00 GEOCODE 53227

HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

2005 SAAB 9-3 LINEAR 4DOOR SEDAN
CD LOG NO 9198-1

2.1 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT
PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE.
WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE
MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE
MANUFACTURER OF YOUR MOTOR VEHICLE.





