My Detailed Description of the Incident To Whom it may concern: On August 9th, I Damion Kreger, was parked in my driveway overnight. My address is: 5306 N. 6240 Street and there is an empty lot to the right (South) of our driveway. In the lot, thereo is a large tree 15 to 20 feetil to the right of our driveway? On the right of August 9th, morning of August 10th, around 1:00 A.M., the tree branches broke and landed on my truck. There are alot of damages to my truck. The lot that the tree is on is city property. The tree is very large and the limbs hung over my driveway 10 to 15 feet. The limbs that fell were rotten at the base of the branches, coming off the tree Also has large mushrooms and lots of ants where the break August 9th the weather

was Stormy, which also was afactor August 10th I called the Milwaukee City Forestry Dept. They came and took pictures of the damages. They removed the tree limbs off of the driveway and my nick

, i	
	Danion R. Kneas
:	Danion R. Kneger 5306. N. 62 St.
	Milw. WI. 53218
}	
	Phone # (414) 588-4951
:	
1	
:	
)	
_	
;	

RUSS DARROW COLLISION CENTER 7676 NORTH 76TH STREET MILWAUKEE WI 53224-9010

PHONE (414) 362-7520 FAX (414) 355-6744 MOBILE ESTIMATING (414) 587-9015 AT DEALERSHIPS

CD LOG NO 17454-1 DATE 08/11/09

RUSS DARROW COLLISION CENTER SHOP:

ADDRESS: 7676 NORTH 76TH STREET CITY STATE: MILWAUKEE, WI

INSP DATE: 08/11/09
CONTACT: CHRIS MARQUARDT
PHONE 1: (414)362-7520
PHONE 2: (414)354-8338 ZIP: 53223-FAX: (414)355-6744

HOME PHONE: (414) 588-4951

OWNER: KREGER, DAMION ADDRESS: 5306 N 62ND ST CITY STATE: MILWAUKEE, WI

ZIP: 53218

TYPE OF LOSS: /DRV POINT OF IMPACT: 13

STATE: WI LIC#: FQ6579 VIN: 1D7HA16N06J183112

31,666 BODY COLOR: WHITE MILEAGE:

ACCTNG CTL#: CONDITION: GOOD

VEH. INSP#: DRIVEABLE: YES

ET=PARTL REPL LABOR IT=PARTIAL REPAIR TE=PARTL REPL PRICE

BR=BLEND REFINISH I=REPAIR L=REFINISH TT=TWO-TONE CG=CHIPGUARD SB=SUBLET

RI=R&I ASSEMBLY N=ADDITIONAL LABOR P=CHECK

AA=APPEAR ALLOWANCE RP=RELATED PRIOR UP=UNRELATED PRIOR

TREE FELL ON TOP OF VEHICLE

POSSIBLE ADDITIONAL DAMAGES ONCE VEHICLE IS TORN DOWN

2006 DODGE RAM 150/1500 SLT 2DOOR STANDARD CAB 8CYL GASOLINE 4.7

CODE: N8343A/A OPTNS N/24ZABS

OPTIONS:

TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

HEATED REMOTE CONTROL MIRRORS POWER WINDOWS POWER DOOR LOCKS OVERHEAD CONSOLE

OP GDE	MC DESCRIPTION	MF	G.PART NO.	PRICE	AJ8	B왕	HOURS	R
								-
RI0028	GRILLE ASSEMBLY	R&I	ASSEMBLY				INC	1
RI0041	HEADLAMP ASSY, HALOG	LT R&I	ASSEMBLY				0.3	1
RI0042	HEADLAMP ASSY, HALOG	RT R&I	ASSEMBLY				0.3	1

2006 DODGE RAM 150/1500 SLT 2DOOR STANDARD CAB CD LOG NO 17454-1

E 0083	PANEL, HOOD	55275733AF 515.00	2.2 1
	13 PANEL, HOOD	REFINISH	6.0 4
T 0000	20 211111111111111111111111111111111111	3.0 SURFACE	
		1.5 EDGE	
•		0.6 TWO STAGE SETUP	
		0.9 TWO STAGE	
E 0035	01 LABEL, HOOD	52113745AA 2.15	0.1 1
RI0086	PAD, INSULATOR HOOD		0.4 1
	RETAINER, HOOD INSULATO		1
BR0103		BLEND REFINISH	1.2 4
DROTOS		0.8 BLEND	
		0.4 TWO STAGE	
ጥጥ∩1∩3	15 FENDER, FRONT LT	T TWO TONE	1.0 4
110100	20 1 11101111 110111	0.4 TWO TONE SETUP	
		0.6 TWO TONE	
I 0104	FENDER, FRONT RI	r repair	2.5*1
L 0104		r refinish	2.3 4
T 0104	I BROBLY I ROMA	1.9 SURFACE	
		0.4 TWO STAGE	
TT0104	FENDER, FRONT R	r TWO TONE	0.6 4
110101		0.6 TWO TONE	
RI1039	CABLE, ANTENNA R	r R&I ASSEMBLY	0.3 1
RI0156	SKIRT, INNER FENDER L		0.6 1
RI0157	SKIRT, INNER FENDER R		0.4 1
SB0143	WINDSHIELD, SHADED	SUBLET REPAIR 280.00*+25.00	1
2202.13	PREMIER AUTO GLASS INC		
E 1171		г 55276549AA 6.20	INC 1
E 1172		r 55276549AA 6.20	INC 1
E 0147	BLADE ASSEMBLY, WIPE L'	r 55077100AC INC	1
E 0148	BLADE ASSEMBLY, WIPE R		1
E 0145		r 55077133AC 42.65	0.1 1
E 0146		r 55077132AC 42.65	0.1 1
E 0173	PANEL, COWL TOP	55056006AF 334.00	0.2 1
E 1149	CLIP, COWL TOP PANEL	MULTI-PART 16.80	1
E 1105	MLDG, PILLAR DRIP L'	T 55277187AB 49.15	INC 1
E 1106	MLDG, PILLAR DRIP R'	T 55277186AB 48.85	INC 1
BR0178	PILLAR, DOOR FRAME R L'	T BLEND REFINISH	1.2 4
		0.8 BLEND	
		0.4 TWO STAGE	
BR0179	PILLAR, DOOR FRAME R R	T BLEND REFINISH	1.0 4
		0.9 BLEND	
		0.1 TWO STAGE	
I 1018	PANEL, PLENUM	REPAIR	3.0*1
	ROLLED DOWN FROM IMPAC		
L 1018	PANEL, PLENUM	REFINISH	0.6 4
		0.5 SURFACE	
		0.1 TWO STAGE	
I 0209	PNL, FRONT DOOR OUTE L		4.0*1
L 0209	PNL, FRONT DOOR OUTE L		2.7 4
		2.7 SURFACE	
		INC TWO STAGE	0 0 4
TT0209	PNL, FRONT DOOR OUTE L	T TWO TONE	0.8 4

		0.8 TWO TONE		
I 0210	PNL, FRONT DOOR OUTE RT	REPAIR		6.0*1
L 0210	PNL, FRONT DOOR OUTE RT			2.7 4
		2.7 SURFACE		
		INC TWO STAGE		
TT0210	PNL, FRONT DOOR OUTE RT	TWO TONE		0.8 4
	·	0.8 TWO TONE		
RI0277	W/STRIP, BELT OUTER LT	R&I ASSEMBLY		0.2 1
RI0278	W/STRIP, BELT OUTER RT	R&I ASSEMBLY		0.2 1
RI0231	PNL, INNER DOOR TRIM LT	R&I ASSEMBLY		INC 1
RI0232	PNL, INNER DOOR TRIM RT	R&I ASSEMBLY		INC 1
E 0119	N/PLATE, FRONT DOOR LT	55077336AA	41.55	0.2 1
E 0120	N/PLATE, FRONT DOOR RT		41.55	0.2 1
RI0400	MIRROR, OUTER R/C LT MIRROR, OUTER R/C RT	R&I ASSEMBLY		0.3 1
RI0401	MIRROR, OUTER R/C RT	R&I ASSEMBLY		0.3 1
RI0251	CHANNEL, FRONT GLASS LT			0.2 1
RI0252	CHANNEL, FRONT GLASS RT	R&I ASSEMBLY		0.2 1
RI0227	HANDLE, FRONT DOOR O LT			1.3 1
RI0228	HANDLE, FRONT DOOR O RT	R&I ASSEMBLY		1.3 1
E 0341	PANEL, ROOF	55275816AA	804.00	16.8 1
L 0341	PANEL, ROOF	REFINISH		2.5 4
		2.5 SURFACE		
		INC TWO STAGE		
E 0357	MLDG, ROOF DRIP LT	55277351AA	15.45	INC 1
E 0358	MLDG, ROOF DRIP RT	55277350AA	19.85	INC 1
RI0883	ROOF HEADLINER R & I	R&I ASSEMBLY		INC 1
SB0369	BACK GLASS, TINTED	SUBLET REPAIR	118.00*	1
	PREMIER AUTO GLASS R&I			
EC0370	SEALANT KIT, BACK GLASS		25.00*	INC 1
RI0511	COMPL BED ASSY R & I	R&I ASSEMBLY		3.0 1
RI0548	LAMP, HIGH MOUNTED STOP	R&I ASSEMBLY		INC 1
ECM14	CORROSION PROTECTION	ECONOMY PART	*	0.5*4*
ECM17	COVER CAR EXTERIOR		10.00*	2*
SBM60	HAZARD. WSTE. REM.	SUBLET REPAIR	5.00*	1*
ECM68		ECONOMY PART	15.00*	1*
N	GLASS CLEAN UP	ADDNL LABOR OPERA		1.0*1*

63 ITEMS

MC MESSAGE(S)

01 CALL DEALER FOR EXACT PART NUMBER / PRICE

13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

15 INCLUDES 0.4 HOURS FIRST PANEL TWO-TONE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS 2,019.65
OTHER PARTS 50.00
PAINT MATERIAL 812.60
PARTS & MATERIAL TOTAL 2,882.25
TAX ON PARTS & MATERIAL @ 5.600% 161.41

LABOR RATE REPLACE HRS REPAIR HRS

2006 DODGE RAM 150/1500	SLT 2DOOR STANDARD CAB
CD LOG NO 17454-1	

1-SHEET METAL 2-MECH/ELEC	54.00 103.00	29.2	16.5	2,467.80
3-FRAME	54.00	00.0		1 200 60
4-REFINISH	54.00	23.9		1,290.60
5-PAINT MATERIAL	34.00			2 750 40
LABOR TOTAL		_		3,758.40
TAX ON LABOR		@	5.600%	210.47
SUBLET REPAIRS				473.00
TAX ON SUBLET		e e	5.600%	26.49
TOWING				
STORAGE				
SIONAGE				
				7 510 00
GROSS TOTAL				7,512.02
				7 510 00
ΝΕΤ ΤΟΤΆΙ.				7.512.02

SHOPLINK U1732 ES CD LOG 17454-1 DATE 08/11/09 10:17:54AM R6.37 CD 07/09 HOST LOG

(C) 1998 - 2008 AUDATEX NORTH AMERICA, INC.

2.9 HRS WERE ADDED TO THIS EST. BASED ON AUDATEX TWO-STAGE REFINISH FORMULA. AUDATEX TWO-STAGE EXTERIOR THRESHOLD OF 2.5 HOURS WAS CALCULATED IN THIS ESTIMATE.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

NOTICE: WHEN SELECTING A REPAIR FACILITY, THE VEHICLE OWNER SHOULD CONSIDER THAT THE REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AND THE RESTORATION OF CORROSIVE RESISTANT COATINGS AS RECOMMENDED BY THE MANUFACTURE. FAILURE TO HAVE THE VEHICLE PROPERLY REPAIRED COULD RESULT IN A SAFETY HAZARD

08/11/2009 at 09:41 AM 98049

Job Number:

REFLECTIONS AUTO BODY INC.

6920 N. 76th Street Milwaukee, WI 53223 (414)358-2110 Fax: (414)358-2232

PRELIMINARY ESTIMATE

Written By: DAN BACON Adjuster:

Insured: DAMIEN KRUEGER Claim #
Owner: DAMIEN KRUEGER Policy #

Address: 5306 N 62ND STREET Deductible:
MILWAUKEE, WI 53218 Date of Loss:

Evening: (414)588-4951

Evening: (414) fract:

Inspect Location:

Insurance

Company: Days to Repair

2006 DODG RAM 1500 4X2 8-4.7L-FI 2D LONG WHITE/SILV Int:

VIN: 1D7HA16N06J183112 Lic: WI Prod Date: 02/2006 Odometer: Air Conditioning Tilt Wheel Intermittent Wipers

Dual Mirrors Clear Coat Paint Power Steering

Power Brakes AM Radio FM Radio Stereo Cassette Search/Seek

Anti-Lock Brakes (2) Driver Air Bag Passenger Air Bag 4 Wheel Disc Brakes Rear Step Bumper 6 Speed Transmission

Overdrive Styled Steel Wheels

NO.	OP.	DESCRIPTION	QT	EXT.	PRICE	LABOR	PAINT
1		FENDER					_
2*	Rpr	RT Fender				2.0	2.0
3		Add for Clear Coat					0.8
4		FRONT LAMPS					
5	R&I	RT Headlamp assy w/o black				0.4	
		bezel					•
6		HOOD & GRILLE					
7	Repl	Hood w/o scoop	1	496	.00	1.5	3.2
8		Add for Clear Coat					0.6
9		Add for Underside (Complete)					1.6
10	R&I	R&I grille assy				Incl.	
11#	Rpr	UPPER COWL FLANGE AT SCREEN				1.5	
		ATTACHMENT					
12		ELECTRICAL					•
13	R&I	Antenna mast				0.1	
14*	R&I	Adapter				0.2	
15		WINDSHIELD .					
16	Repl	Windshield Dodge	1	466	.00	Incl.	

PRELIMINARY ESTIMATE
2006 DODG RAM 1500 4X2 8-4.7L-FI 2D LONG WHITE/SILV Int:

NO.	OP.	DESCRIPTION	QTY	EXT. PRI	CE LABOR	PAINT
17		CAB				
18	Repl	Roof panel	1	804.00	13.5	2.8
19		Overlap Major Adj. Panel				-0.4
20		Add for Clear Coat				0.5
21	Repl	Cowl grille	1	334.00	Incl.	
22.	Repl	Seal to cowl		23.35		
23	R&I	Headliner w/o overhead console			Incl.	
24	R&I	Rear trim panel gray			0.3	
25*		RT Upper seal				
26*	R&I	LT Upper seal			$\frac{0.2}{0.2}$	
27	R&I	RT W'strip on body			Incl.	
28		LT W'strip on body			Inc1.	
29		DOOR				
30*	Rpr	RT Door shell w/o SRT			4.5	2.8
31	•	Overlap Major Adj. Panel				-0.4
32		Add for Clear Coat				0.5
33	Repl	RT Nameplate "RAM 1500"	1	41.55	0.3	0.0
34		RT Belt w'strip	_		0.3	
35		RT Mirror manual 6x9, black			0.3	
36		RT Run channel			0.2	
37	R&I	RT Door glass Dodge			0.5	
38	R&I	RT Handle, outside w/o			0.3	
		keyless entry			0.0	
39	R&I	RT R&I trim panel			0.5	
40*		LT Door shell w/o SRT			5.5	2.8
41	-	Overlap Major Adj. Panel			<u> </u>	-0.4
42*		Add for Clear Coat				0.5
43*	R&I	LT Nameplate "RAM 1500"			0.3	0.5
44	R&I	LT Belt w'strip			$\frac{0.3}{0.3}$	
45		LT Mirror manual 6x9, black			0.3	
46		LT Run channel			0.2	
47	R&I	LT Door glass Dodge			0.5	
48	R&I	LT Handle, outside w/o			0.3	
		keyless entry				
49	R&I	LT R&I trim panel			0.5	
50		BACK GLASS				
51	R&I	Back glass Dodge stationary			Incl.	
		w/o heat				
52		REAR LAMPS				
53	R&I	High mount lamp			Incl.	
54#	Repl	Restore Corrosion Protection	1	12.00		
55#		Car Cover/ Mask for Overspray	1	10.00		
56#		Hazardous Waste Disposal	1	5.00		•
57#		Urethane Kit	2	50.00		
58#	Rpr	Clean & Re-Tape Mldg(s)			0.4	Incl.
59#	R&I	RT & LT ROOF MLDS			0.4	
		Co.ht - + - 1		0041 00		
		Subtotals ==>		2241.90	35.5	16.9

Job Number:

PRELIMINARY ESTIMATE

2006 DODG RAM 1500 4X2 8-4.7L-FI 2D LONG WHITE/SILV Int:

Parts Body Labor Paint Labor Paint Supplies Sublet/Misc.	35.5 hrs @ \$ 52.00/hr 16.9 hrs @ \$ 52.00/hr 16.9 hrs @ \$ 32.00/hr	2164.90 1846.00 878.80 540.80 77.00
SUBTOTAL Sales Tax	\$ \$ 5507.50 @ 5.6000%	5507.50
GRAND TOTAL	<u> </u>	5815.92
ADJUSTMENTS: Deductible		0.00
CUSTOMER PAY INSURANCE PAY	\$ \$	0.00

Thank You For Your Business.

This is an estimate only. This estimate does not account for hidden or unseen damage. Parts prices may vary and are subject to invoice.

Authorization of Repair

Customer Signature	Date//
************	************

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

08/11/2009 at 09:41 AM 98049

Job Number:

PRELIMINARY ESTIMATE

2006 DODG RAM 1500 4X2 8-4.7L-FI 2D LONG WHITE/SILV Int:

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide DR3TM06, CCC Data Date 07/10/2009, and the parts selected are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor information provided by MOTOR may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. Non-Original Equipment Manufacturer aftermarket parts are described as AM, Qual Repl Parts or Comp Repl Parts which stands for Competitive Replacement Parts. Used parts are described as LKQ, Qual Recy Parts, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries. Some 2010 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The Pathways estimator has a complete list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

CCC Pathways - A product of CCC Information Services Inc.

MOTORCAR COLLISION 8120 W. BRADLEY ROAD MILWAUKEE, WI 53223

OFFICE: 414-354-2400 FAX: 414-354-3128

*** PRELIMINARY ESTIMATE ***

Ó8/11/2009 10:56 AM

Owner

Owner: DAMION KREGER Address: 5306 N. 62ND ST. City State Zip: Milwaukee, WI 53218

Cell: (414)588-4951

FAX:

Inspection

Inspection Date: 08/11/2009 10:47 AM

Primary Impact: Hood Driveable: Yes

Inspection Type: Direct Repair Program

Secondary Impact: Roof Rental Assisted:

First Contact Date/Time:

Appointment Date/Time: 08/1 t/2009 10:47 AM

Appraiser License # :

Appraiser Name: JIM KELLER Address: City State Zip:

Work/Day: (414)354-2400 FAX: (414)354-3128

Repairer

Repairer: Motorcar Crash1 Address: 8120 W. Bradley Road City State Zip: Milwaukee, WI 53223 Email: JKellerJr@Crash1.com

Contact: Jim Keller Work/Day: (414)354-2400 FAX: (414)354-3128

Target Complete Date/Time:

Days To Repair: 12

2006 Dodge Ram 150/1500 SLT 2 DR Standard Cab Short Bed 8cyl Gasoline 4.7 5 Speed Automatic

> Lic Expire: Veh Insp#: Condition:

VIN: 1D7HA16N065183112

Mileage Type: Actual Code: N8342A Ext. Refinish: Two-Stage Int. Refinish: Two-Stage

Options

AM/FM CD Player Anti-Lock Rear Brakes Cruise Control Intermittent Wipers Power Brakes Power Windows Theft Deterrent System Trip Computer

Air Conditioning Center Console Dual Airbags Keyless Entry System Power Door Locks Split Front Bench Seat Tilt Steering Wheel Velour/Cloth Seats

Aluminum/Alloy Wheels Chrome Step Bumper Heated Power Mirrors Lighted Entry System Power Steering Tachometer Tinted Glass

Damages

Lin	ne	Ор	Guide	МС	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
	1	RI	28		Grille Assembly	R & I Assembly			INC	SM
	2	Ε	83	46	Panel,Hood	55275733AF	\$529.00		2.2	SM
	3	L	83	13	Panel, Hood	Refinish			6.0	RF
	4	NG	143		Windshield,Shaded	NAGS DW1456-GB	\$352.25*		4.3	SM
	5	Ε	1023		Panel,Plenum	55275783AF	\$199.00		2.0	SM

08/11/2009 11.03 AM Page Lot 3

Claim #								08/11/2	2009 10 56 AM
6 L	1023	Panel Ple	num	Refinish	•			0.6	RF
7 RI	1500	Console,0	Overhead	R&IAss	embly			INC	SM
8 I	207	Door She	II,Front LT	Repair	•			3.0*	SM
9 L	207	Door She	II,Front I_T	Refinish				3.6	RF
10 TT	207	15 Door She	II,Front LT	Two-Tone	•			1.3	RF
11 l	208	Door She	II,Front RT	Repair				7.0*	SM
12 L	208	Door She	II,Front RT	Refinish				3.6	RF
13 TT	208	Door She	II,Front RT	Two-Tone	•			0.9	RF
14 RI	246	W/Strip,F	t Door Body RT	₽&IAss	embly			0.4	SM
15 RI	277	W/Strip,B	elt Outer LT	R & I Ass	embly			0.2	SM
16 RI	278	W/Strip,B	elt Outer RT	R&I A ss	embly			0.2	· SM
17 RI	231	Pnl,Inner	Door Trim LT	R&IAss	embly			INC	SM
18 RI	232	Pnl,Inner	Door Trim RT	R&I A ss	embly			INC	SM
19 E	119	N/Plate,F	ront Door LT	55077336	SAA -	\$4t.55		0.2	SM
20 E	120	N/Plate,F	ront Door RT	55077336	SAA	\$41.55		0.2	SM .
21 RI	400	Mirror,Ou	ter R/C LT	R & I Ass	embly			0.3	SM
22 RI	401	Mirror,Ou	ter R/C RT	R & I Ass	embly			0.3	SM
23 RI	227	Handle,Fr	ont Door Otr LT	R & J Ass	embly			1.3	SM
24 RI	228	Handle,Fr	ont Door Otr RT	R & I Ass	embly			1.3	SM
25 I	341	Panel,Roo	of	Repair				20.0*	SM
		>> Incl Se	t Up and Pull Tir	me					
26 L	341	Panel,Ro		Refinish				2.6	RF
27 RI	883	Roof Hear	dliner R & I	R & I Ass	embly			2.0*	SM
28 RI	548	Lamp,Hig	h Mounted Stop	R&IAss	embly			0.3	SM
29 N	M14	Corrosion	Protection	Additiona	l Labor	\$7.00*		0.3*	SM
30 N	M17	Cover Ca	r Exterior	Additiona	Labor	\$5.00*		0.2*	RF
31 EC	M29	Glass Inst	allation Kit	Replace B	Economy	\$25.00*			SM
32 N	M60	Hazardou	s Waste Remova	al Additional	Labor	\$5.00*			SM
33 l	M69	Glass Cle	an Up	Repair				1.5*	SM
33 Iten	ns					,			
		MC	Message						
		13	INCLUDES	0.6 HOURS FIR	RST PANEL T	WO-STAGE ALI	LOWANCE		
		15	INCLUDES (0.4 HOURS FIF	RST PANEL T	WO-TONE ALLO	OWANCE		
		46	PRINTABLE	ALTERNATE F	PARTS COM	PARE			
F-424- T-4-1 8		-							-
Estimate Total &	Entrie								
Gross Parts						\$811.10		•	
Other Parts						\$394.25			
Paint Materials						\$601.60			
Parts & Material T	otal		•			Ψ001.00	\$1,806.95		
Tax on Parts & Ma				@ 5.600°	6		\$101.19	•	
Labor		Da	te Replace Hrs	Dannir Ura	Total Hrs				
Caboi		na	te neplace His	nepail 1115	- TOTAL THIS				
Sheet Metal (SM)		\$52.0	00 15.2	31.8	47.0	\$2,444.00			
Mech/Elec (ME)		\$85.0							
Frame (FR)		\$52.0							
Refinish (RF)		\$52.0	00 18.6	0.2	18.8	\$977.60			
Paint Materials		\$32.0	00						
Labor Total					65.8 F	Hours	\$3,421.60		
Tax on Labor				@ 5.600%			\$191.61		
Gross Total							\$5,521.35		
Net Total							\$ 5,5 2 1.35		•
							T-,		

Alternate Parts Y/01/00/00/01/01 CUM 01/00/00/01/01 Zip Code: 53223 Default

Audatex Estimating 6.0.025 ES 08/11/2009 11:03 AM REL 6.0.025 DT 07/01/2009 DB 08/08/2009 Copyright (C) 2008 Audatex North America, Inc.

2.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA. ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

08/11/2009 11:03 AM Page 2 of 3 THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

Op Codes

* = User-Entered Value EC = Replace Economy ET = Partial Replace Labor TE = Partial Replace Price L = Refinish

TT = Two-Tone
BR = Blend Refinish
CG = Chipguard

AA = Appearance Allowance

E = Replace OEM

OE = Replace PXN OE Srpls

EP = Replace PXN

PM = Replace PXN Reman/Rebit PC = Replace PXN Reconditioned

SB = Sublet Repair ! = Repair

RI = R & I Assembly RP = Related Prior Damage NG = Replace NAGS

UE = Replace OE Surplus EU = Replace Recycled

UM = Replace Reman/Rebuilt UC = Replace Reconditioned

N = Additional Labor IT = Partia! Repair

P = Check



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2008 Audatex North America, Inc.

Audatex Estimating is a trademark of Audatex North America, Inc.