


CCF 160575 1037 West Juneau Avenue 3-17-2020 Looking northeast from North 11<sup>th</sup> Street at the gate. The north leaf is locked in place, while the south leaf can swing open over the sidewalk and into the roadway.



CCF 160575 1037 West Juneau Avenue 3-17-2020 Looking south away from West Juneau Avenue at the east sidewalk of North 11<sup>th</sup> Street.