







Photo 1 - View of South Elevation of the House



Photo 2 - Southwest Corner of the Existing Garage



Photo 3 - West Elevation of the Existing Garage



Photo 4 - South Elevation of the Existing Garage



Photo 5 - North Elevation of the Existing Garage



Photo 6 - North Elevation of the Lot Showing the Existing Retaining Wall and Fence West of the Garage




Photo 7 - Northwest Corner of the Existing Garage Showing Deterioration of the Stucco and Concrete



Photo 8 - East Elevation of the Interior of the Existing Garage Showing Deterioration of the Structure



Photo 9 - West Elevation of the Interior of the Existing Garage Showing Deterioration of the Structure




Photo 10 - West Elevation of the Interior of the Existing Garage Showing Deterioration of the Structure



Photo 11 - Southwest Corner of the Interior of the Existing Garage Showing Deterioration of the Structure by the Service Door